

Nov. 4, 2014
BOND



Bond 2014 Summary By Campus Feeder Pattern

Austin High School

**CAMPUS NAMES****AMOUNT****AUSTIN HIGH SCHOOL****\$3,242,651**

Austin High School Deficiency Categories	2014 Bond
All doors require re-keying	Proposed
Controls Require Repair	Proposed
Membrane Flashings At Drain Requires Repair	Proposed
Switchgear Is Needed Or Requires Replacement	Proposed
The Aluminum Window Is Damaged And Requires Replacement	Proposed
The Metal Exterior Door Requires Replacement	Proposed
The Motor Control Center Is Damaged And Should Be Replaced	Proposed
The Multi-Ply Bitumen Roof Covering Requires Replacement	Proposed
The Retractable Bleachers are Damaged and Require Replacement	Proposed
The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced	Proposed
The Wood Roof Subdeck Is Damaged And Requires Replacement	Proposed
Austin High School Total for Facility Deficiencies	\$2,688,842
Exterior Entrance Doors	Proposed
Austin High School Total for Life-Cycle Needs	\$25,320
Security Cameras	Proposed
Security Vestibules	Proposed
Window Film	Proposed
Access Control including Video Intercom	Proposed
Austin High School Total Safety and Security	\$528,489

This does not include: district wide investments for safety & security; campus wireless and network infrastructure; buses and bus cameras; land; and new campuses. Questions? Contact steven.bassett@fortbendisd.com