Fort Bend Independent School District Capital Plan

As of July 21, 2014 (Draft)

Fort Bend Independent School District Capital Plan Table of Contents

| Plan Summary by Phase 1 and 2 | Page 1 |
|--|---------|
| Phase 1 by Funding Source | Page 2 |
| Contingency Included in Proposed 2014 Bond Program | Page 3 |
| New Construction and Classroom Additions Detail - Phase 1 Only | Page 4 |
| Current Facility Deficiencies Detail by Site - Phase 1 Only | Page 5 |
| Educational Adequacy Deficiencies Detail by Campus - Phase 1 Only | Page 20 |
| Facility Life-Cycle Needs Detail by Site - Phase 1 Only | Page 24 |
| Security Cameras Budget Estimate - Phase 1 Only | Page 32 |
| Security Vestibules Budget Estimate - Phase 1 Only | Page 33 |
| Window Film Budget Estimate - Phase 1 Only | Page 34 |
| Security Fencing Budget Estimate - Phase 1 Only | Page 36 |
| Access Control Including Video Intercom Budget Estimate - Phase 1 Only | Page 37 |
| Emergency Generators Budget Estimate - Phase 1 Only | Page 38 |
| Emergency Notification System Budget Estimate - Phase 1 Only | Page 39 |
| Two Way Radio Budget Estimate - Phase 1 Only | Page 40 |
| Bus Cameras and GPS Budget Estimate - Phase 1 Only | Page 41 |
| Bus Replacement Budget Estimate - Phase 1 Only | Page 42 |
| Technology Budget Estimate - Phase 1 Only | Page 43 |
| Athletic Facility Cycle Replacement Budget Estimate - Phase 1 Only | Page 44 |
| White Fleet Vehicle Replacement Budget Estimate - Phase 1 Only | Page 45 |

Fort Bend ISD Capital Plan Plan Summary by Phase as of July 21, 2014

| Description | Phase 1 | Phase 2 | Total |
|--|---------------------|--------------------|-----------------|
| New Construction and Classroom Additions | \$275,310,873 | \$141,132,327 | \$416,443,200 |
| Current Facility Deficiencies | \$114,146,566 | \$137,031,258 | \$251,177,824 |
| Educational Adequacy Deficiencies | \$3,898,328 | \$51,927,631 | \$55,825,959 |
| Facility Life-Cycle Needs | \$41,860,102 | \$85,785,836 | \$127,645,938 |
| Construction Total | \$435,215,868 | \$415,877,053 | \$851,092,921 |
| Security Cameras | \$14,118,000 | | \$14,118,000 |
| Security Vestibules | \$4,332,450 | | \$4,332,450 |
| Window Film | \$1,824,915 | | \$1,824,915 |
| Security Fencing | \$1,283,993 | | \$1,283,993 |
| Access Control including Video Intercom | \$3,415,000 | | \$3,415,000 |
| Emergency Generators | \$3,200,000 | | \$3,200,000 |
| Emergency Notification System | \$524,600 | | \$524,600 |
| Crisis Communication Devices for Staff | | \$3,800,000 | \$3,800,000 |
| Radio Frequency Identification | | \$4,100,000 | \$4,100,000 |
| Two Way Radio | \$1,432,768 | | \$1,432,768 |
| Safety and Security Total | \$30,131,726 | \$7,900,000 | \$38,031,726 |
| Bus Cameras and GPS | \$908,369 | | \$908,369 |
| Bus Replacement | \$18,000,000 | \$16,500,000 | \$34,500,000 |
| Transportation Total | \$18,908,369 | \$16,500,000 | \$35,408,369 |
| Transportation Fotol | \$15,505,505 | Ÿ10,500,000 | |
| Internet Infrastructure Upgrade | \$4,375,968 | | \$4,375,968 |
| Wide Area Network/Backbone Refresh | \$17,281,694 | | \$17,281,694 |
| Data Center SAN and Virtualization | \$7,759,250 | | \$7,759,250 |
| Data Center Facilities Modifications | \$620,991 | | \$620,991 |
| Wireless Network Deployment | \$22,152,153 | | \$22,152,153 |
| Local Area Network Refresh | \$12,160,000 | | \$12,160,000 |
| Telephone System Upgrade | \$5,074,894 | | \$5,074,894 |
| Adding Communications Closets on Campus | \$1,267,000 | | \$1,267,000 |
| Data Warehouse | | \$5,000,000 | \$5,000,000 |
| Technology (does not include device refresh) | \$70,691,950 | \$5,000,000 | \$75,691,950 |
| Land | \$18,425,880 | | \$18,425,880 |
| Athletic Facility Cycle Replacement | \$1,791,216 | \$2,816,000 | \$4,607,216 |
| White Fleet Vehicle Replacement | \$1,498,232 | | \$1,498,232 |
| Energy Conservation Initiatives (TBD) | | | \$0 |
| Bond Support (6% of construction) | \$26,112,952 | \$24,952,623 | \$51,065,575 |
| Total Capital Requirements | \$602,776,192 | \$473,045,676 | \$1,075,821,868 |
| Ausilahla Funds | | | |
| Available Funds Unissued but Authorized Debt | \$63,000,000 | | \$63,000,000 |
| Other Capital Funds | \$11,002,261 | | \$11,002,261 |
| Prior Bond Contingency | \$33,799,000 | | \$33,799,000 |
| Total Available Funds | \$107,801,261 | \$0 | \$107,801,261 |
| Total Potential Bond Need | \$494,974,932 | \$473,045,676 | \$968,020,607 |

Fort Bend ISD Capital Plan Phase 1 by Funding Source

| New Construction and Classroom Additions \$205,057,163 \$70,253,710 \$0 \$277,545 \$114,146,56 \$141,246,021 \$0 \$77,735 \$114,146,56 \$141,246,021 \$0 \$77,735 \$114,146,56 \$141,246,121 \$0 \$77,735 \$14,146,56 \$141,246,121 \$0 \$77,735 \$14,146,56 \$141,241,241 \$0 \$77,735 \$14,146,56 \$141,241,241 \$0 \$77,735 \$14,146,56 \$141,241,241 \$10 \$77,735 \$77,735 \$14,146,56 \$141,241,241 \$10 \$77,735 \$77,735 \$14,146,56 \$141,241,241 \$10 \$77,735 \$77,73 | Description | Proposed 2014 Bond Program | Other Capital Funds | General Fund (Items under \$5K) | Phase 1 Total |
|--|--|-------------------------------|---------------------------------------|------------------------------------|------------------|
| Current Facility Deficiencies \$113,869,021 \$0 \$277,545 \$114,146,566 Educational Adequacy Deficiencies \$3,886,1889 \$0 \$72,139 \$3,888,321 Facility Life-Cycle Needs \$41,761,519 \$0 \$98,582 \$41,860,100 Construction Total \$366,513,893 \$70,233,710 \$448,266 \$4352,158 Security Cameras \$14,118,000 \$14,118,000 \$14,118,000 \$448,266 \$4332,451 Security Vestibules \$4,332,450 \$6,332,451 \$6,332,451 \$6,332,451 \$6,332,451 \$6,332,451 \$6,332,451 \$6,332,451 \$6,332,451 \$6,332,451 \$6,322,451 \$6,322,461 \$6,322,461 \$6,322,461 \$6,322,461 \$6,322,461 \$6,322,461 \$6,322,461 \$6,322,461 \$6,322,461 \$6,322,461 \$6,000 \$6,322,461 \$6,000 \$6,322,461 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 | • | | | | |
| Facility Infectional Adequacy Deficiencies \$3,826,189 \$0 \$72,139 \$3,898,32 \$4,1860,10 | | | | | \$114,146,566 |
| Facility Life-Cycle Needs \$41,761,519 \$0 \$98,582 \$41,860,100 Construction Total \$364,513,893 \$70,253,710 \$448,266 \$435,215,865 Security Cameras \$14,118,000 \$14,118,000 \$14,118,000 \$14,118,000 \$14,118,000 \$14,118,000 \$14,118,000 \$14,118,000 \$14,118,000 \$14,24,915 \$1,224,915 \$1,224,915 \$1,224,915 \$1,224,915 \$1,224,915 \$1,224,915 \$1,224,915 \$1,224,915 \$1,224,919 \$1,228,993 \$ | • | | | | |
| Security Cameras Sale, 118,000 S448,266 S435,215,861 | | | | , , | |
| Security Vestibules \$4,332,450 \$6,332,451 \$1,824,915 \$1,824,915 \$1,824,915 \$1,824,915 \$1,824,915 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,990 \$34,200,000 \$34,200,000 \$1,280,000 \$1,400,000 | | | · · · · · · · · · · · · · · · · · · · | | \$435,215,868 |
| Security Vestibules \$4,332,450 \$6,332,451 \$1,824,915 \$1,824,915 \$1,824,915 \$1,824,915 \$1,824,915 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,993 \$1,283,990 \$34,200,000 \$34,200,000 \$1,280,000 \$1,400,000 | Security Cameras | \$14.118.000 | | | \$14.118.000 |
| Window Film \$1,824,915 \$1,824,915 Security Fencing \$1,283,993 \$1,283,993 Access Control Including Video Intercom \$3,415,000 \$3,415,000 Emergency Generators \$3,200,000 \$524,600 \$524,600 Two Way Radio \$1,432,768 \$1,432,768 \$1,432,765 Safety and Security Total \$30,131,726 \$0 \$0 \$30,131,727 Bus Cameras and GPS \$908,369 \$0 \$908,366 \$0 \$30,800,000 \$0 \$18,000,000 Transportation Total \$15,000,000 \$3,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$18,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$18,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$0 \$18,000,000 \$0 \$12,200,000 \$0 \$12,215,152,152,152,152,152,152,152,152,1 | • | | | | |
| Security Fencing \$1,283,993 \$1,283,993 Access Control including Video Intercom \$3,415,000 \$3,415,000 Emergency Generators \$3,200,000 \$3,200,000 Emergency Notification System \$5224,600 \$5224,600 Two Way Radio \$1,432,768 \$1,432,768 Safety and Security Total \$30,131,726 \$0 \$0 \$30,013,726 Bus Cameras and GPS \$908,369 \$0 \$908,366 \$908,366 Bus Replacement \$15,000,000 \$3,000,000 \$0 \$18,000,360 Transportation Total \$15,908,369 \$3,000,000 \$0 \$18,908,366 Internet Infrastructure Upgrade \$0 \$4,375,968 \$4,375,968,366 Wide Area Network/Backbone Refresh \$17,281,699 \$3,000,000 \$0 \$18,908,366 Wide Area Network Pedidities Modifications \$0 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250 \$7,759,250< | • | | | | |
| Access Control Including Video Intercom | | | | | |
| Emergency Generators \$3,200,000 \$524,600 \$524,600 \$524,600 \$524,600 \$524,600 \$524,600 \$524,600 \$524,600 \$524,600 \$524,600 \$524,600 \$524,600 \$524,600 \$524,600 \$50 \$30,131,726 \$50 \$50 \$30,131,726 \$50 \$50 \$30,131,721 \$50 \$50 \$30,131,721 \$50 \$50 \$30,131,721 \$50 \$50 \$50,301,31,721 \$50 \$50 \$30,013,1721 \$50 \$50 \$50 \$30,000,000 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$18,000,500 \$50 \$17,251,500 \$50 \$50,759,500 \$50,779,500 \$50,779,500 \$50,779,500 \$50,779,500 \$50,7 | - | _ | | | |
| Emergency Notification System \$524,600 \$524,600 Two Way Radio \$1,432,768 \$1,432,768 Safety and Security Total \$30,131,726 \$0 \$0 \$30,131,721 Bus Cameras and GPS \$908,369 \$0 \$908,369 \$0 \$18,000,000 Bus Replacement \$15,000,000 \$3,000,000 \$0 \$18,000,000 Transportation Total \$15,908,369 \$3,000,000 \$0 \$18,008,361 Internet Infrastructure Ugrade \$0 \$4,375,968 \$4,375,968 \$4,375,968 Wide Area Network/Backbone Refresh \$17,281,694 \$0 \$17,281,694 \$0 \$17,281,694 Data Center SAN and Virtualization \$0 \$7,759,250 \$7,759,259 \$7,759,259 Wireless Network Deployment \$22,152,153 \$0 \$22,152,151 \$0 \$22,152,151 Local Area Network Refresh \$0 \$12,160,000 \$12,160,000 \$12,260,000 \$12,260,000 Telephone System Uggrade \$0 \$1,267,000 \$1,267,000 \$1,267,000 \$1,267,000 \$1,267,000 \$1,26 | _ | | | | |
| Two Way Radio \$1,432,768 \$0 \$1,432,761 Safety and Security Total \$30,131,726 \$0 \$0 \$30,131,721 Bus Cameras and GPS \$908,369 \$0 \$908,365 Bus Replacement \$15,000,000 \$3,000,000 \$0 \$18,000,000 Transportation Total \$15,908,369 \$3,000,000 \$0 \$18,908,365 Internet Infrastructure Upgrade \$0 \$4,375,968 \$4,375,968 \$4,375,968 Wide Area Network/Backbone Refresh \$17,281,694 \$0 \$17,281,699 \$0 \$17,281,699 Data Center SAN and Virtualization \$0 \$7,759,250 \$7,759,255 \$7,759,255 \$7,759,255 Data Center Facilities Modifications \$0 \$620,991 \$620,999 | | | | | |
| Safety and Security Total \$30,131,726 \$0 \$30,131,726 Bus Cameras and GPS \$908,369 \$0 \$908,366 Bus Replacement \$15,000,000 \$3,000,000 \$0 \$18,000,000 Transportation Total \$15,908,369 \$3,000,000 \$0 \$18,908,366 Internet Infrastructure Upgrade \$0 \$4,375,968 \$4,375,968 \$4,375,968 Wide Area Network/Backbone Refresh \$17,281,694 \$0 \$17,281,699 \$0 \$17,292,251 \$0 \$12,159,251 \$0 \$12,160,000 \$12,1 | | • • | | | |
| Bus Cameras and GPS \$908,369 \$0 \$908,369 Bus Replacement \$15,000,000 \$3,000,000 \$0 \$18,000,000 Transportation Total \$15,908,369 \$3,000,000 \$0 \$18,000,365 Internet Infrastructure Upgrade \$0 \$4,375,968 \$4,375,968 Wide Area Network/Backbone Refresh \$17,281,694 \$0 \$17,281,699 Data Center SAN and Virtualization \$0 \$7,759,250 \$7,759,250 Data Center Facilities Modifications \$0 \$620,991 \$620,991 Wireless Network Deployment \$22,152,153 \$0 \$22,152,151 Local Area Network Refresh \$0 \$12,160,000 \$12,160,000 Telephone System Upgrade \$0 \$5,074,894 \$5,074,894 Adding Communications Closets on Campus \$0 \$1,267,000 \$1,267,000 Technology (does not include device refresh) \$39,433,847 \$31,258,103 \$0 \$70,691,951 Land \$18,425,880 \$18,425,880 Athletic Facility Cycle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) Bond Support (6% of construction) \$26,112,952 Total Capital Requirements \$494,526,666 \$107,801,261 \$448,266 \$602,776,191 Available Funds Unissued but Authorized Debt \$63,000,000 \$33,799,000 Total Available Funds \$0 \$11,002,261 \$11,002,266 Prior Bond Contingency \$33,799,000 \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$107,801,261 | - | | ¢0 | ćo | |
| Bus Replacement \$15,000,000 \$3,000,000 \$0 \$18,000,000 Transportation Total \$15,908,369 \$3,000,000 \$0 \$18,908,369 Internet Infrastructure Upgrade \$0 \$4,375,968 \$4,375,968 \$4,375,968 Wide Area Network/Backbone Refresh \$17,281,694 \$0 \$17,281,694 \$0 Data Center SAN and Virtualization \$0 \$7,759,250 \$7,759,255 \$7,759,255 Data Center Facilities Modifications \$0 \$620,991 \$620,999 | Safety and Security Total | 330,131,720 | 30 | , ju | 330,131,720 |
| Transportation Total | Bus Cameras and GPS | \$908,369 | \$0 | | \$908,369 |
| Internet Infrastructure Upgrade \$0 \$4,375,968 \$4,375,968 Wide Area Network/Backbone Refresh \$17,281,694 \$0 \$517,281,694 Data Center SAN and Virtualization \$0 \$7,759,250 \$7,759,251 Data Center Facilities Modifications \$0 \$620,991 \$620,999 Wireless Network Deployment \$22,152,153 \$0 \$22,152,151 Local Area Network Refresh \$0 \$12,160,000 \$12,160,000 Telephone System Upgrade \$0 \$5,074,894 \$5,074,894 Adding Communications Closets on Campus \$0 \$1,267,000 \$1,267,000 Technology (does not include device refresh) \$39,433,847 \$31,258,103 \$0 \$70,691,951 Land \$18,425,880 \$18,425,880 Athletic Facility Cycle Replacement \$0 \$1,791,216 \$1,791,211 White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) Bond Support (6% of construction) \$26,112,952 Total Capital Requirements \$494,526,666 \$107,801,261 \$448,266 \$602,776,192 Available Funds Unissued but Authorized Debt \$63,000,000 \$63,000,000 Other Capital Funds Prior Bond Contingency \$33,799,000 \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$11,002,266 Prior Bond Contingency \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$107,801,261 | Bus Replacement | \$15,000,000 | \$3,000,000 | \$0 | \$18,000,000 |
| Wide Area Network/Backbone Refresh \$17,281,694 \$0 \$17,281,69 Data Center SAN and Virtualization \$0 \$7,759,250 \$7,759,251 Data Center Facilities Modifications \$0 \$620,991 \$620,992 Wireless Network Deployment \$22,152,153 \$0 \$22,152,153 Local Area Network Refresh \$0 \$12,160,000 \$12,160,000 Telephone System Upgrade \$0 \$5,074,894 \$5,074,894 Adding Communications Closets on Campus \$0 \$1,267,000 \$1,267,000 Technology (does not include device refresh) \$39,433,847 \$31,258,103 \$0 \$70,691,951 Land \$18,425,880 \$1,791,216 \$1,791,216 \$1,791,211 White Fleet Vehicle Replacement \$0 \$1,791,216 \$1,791,211 White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) \$6 \$60,000,000 \$60,000,000 Bond Support (6% of construction) \$26,112,952 \$26,112,952 \$26,112,952 Total Capital Requirements \$494,526,666 <t< td=""><td>Transportation Total</td><td>\$15,908,369</td><td>\$3,000,000</td><td>\$0</td><td>\$18,908,369</td></t<> | Transportation Total | \$15,908,369 | \$3,000,000 | \$0 | \$18,908,369 |
| Data Center SAN and Virtualization \$0 \$7,759,250 \$7,759,250 Data Center Facilities Modifications \$0 \$620,991 \$620,991 Wireless Network Deployment \$22,152,153 \$0 \$22,152,153 Local Area Network Refresh \$0 \$12,160,000 \$12,2160,000 Telephone System Upgrade \$0 \$5,074,894 \$5,074,894 Adding Communications Closets on Campus \$0 \$1,267,000 \$1,267,000 Technology (does not include device refresh) \$39,433,847 \$31,258,103 \$0 \$70,691,951 Land \$18,425,880 \$18,425,880 \$18,425,880 \$18,425,880 \$1,791,216 \$1,791,216 \$1,791,211 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,232 \$1,498,233 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 | Internet Infrastructure Upgrade | \$0 | \$4,375,968 | | \$4,375,968 |
| Data Center Facilities Modifications \$0 \$620,991 \$620,991 Wireless Network Deployment \$22,152,153 \$0 \$22,152,153 Local Area Network Refresh \$0 \$12,160,000 \$12,160,000 Telephone System Upgrade \$0 \$5,074,894 \$5,074,894 Adding Communications Closets on Campus \$0 \$1,267,000 \$1,267,000 Technology (does not include device refresh) \$39,433,847 \$31,258,103 \$0 \$70,691,951 Land \$18,425,880 \$18,425,880 \$18,425,880 \$18,425,880 Athletic Facility Cycle Replacement \$0 \$1,791,216 \$1,791,216 White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) \$1 \$1 Bond Support (6% of construction) \$26,112,952 \$26,112,952 Total Capital Requirements \$494,526,666 \$107,801,261 \$48,266 \$602,776,192 Available Funds \$11,002,261 \$11,002,261 \$11,002,261 \$11,002,261 Prior Bond Contingency \$33,799,000 \$333,799,000 | Wide Area Network/Backbone Refresh | \$17,281,694 | \$0 | | \$17,281,694 |
| Wireless Network Deployment \$22,152,153 \$0 \$22,152,152 Local Area Network Refresh \$0 \$12,160,000 \$12,160,000 Telephone System Upgrade \$0 \$5,074,894 \$5,074,894 Adding Communications Closets on Campus \$0 \$1,267,000 \$1,267,000 Technology (does not include device refresh) \$39,433,847 \$31,258,103 \$0 \$70,691,951 Land \$18,425,880 \$18,425,880 \$18,425,880 \$18,425,881 Athletic Facility Cycle Replacement \$0 \$1,791,216 \$1,791,211 White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) \$1 \$1 \$1 Bond Support (6% of construction) \$26,112,952 \$26,112,952 \$26,112,952 Total Capital Requirements \$494,526,666 \$107,801,261 \$448,266 \$60,000,000 Available Funds \$11,002,261 \$11,002,261 \$11,002,261 Prior Bond Contingency \$33,799,000 \$33,799,000 \$33,799,000 Total Available Funds \$0 \$ | Data Center SAN and Virtualization | \$0 | \$7,759,250 | | \$7,759,250 |
| Local Area Network Refresh \$0 \$12,160,000 \$12,160,000 Telephone System Upgrade \$0 \$5,074,894 \$5,074,894 Adding Communications Closets on Campus \$0 \$1,267,000 \$1,267,000 Technology (does not include device refresh) \$39,433,847 \$31,258,103 \$0 \$70,691,956 Land \$18,425,880 \$18,425,880 \$18,425,880 \$18,425,880 Athletic Facility Cycle Replacement \$0 \$1,791,216 \$1,791,211 White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,233 Energy Conservation Initiatives (TBD) \$6 \$6 \$107,801,261 \$448,266 \$602,776,193 Available Funds \$494,526,666 \$107,801,261 \$448,266 \$602,776,193 Available Funds \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$63, | Data Center Facilities Modifications | \$0 | \$620,991 | | \$620,991 |
| Telephone System Upgrade \$0 \$5,074,894 \$5,074,894 Adding Communications Closets on Campus \$0 \$1,267,000 \$1,267,000 Technology (does not include device refresh) \$39,433,847 \$31,258,103 \$0 \$70,691,956 Land \$18,425,880 \$18,425,880 Athletic Facility Cycle Replacement \$0 \$1,791,216 \$1,791,216 White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) \$60,112,952 Total Capital Requirements \$494,526,666 \$107,801,261 \$448,266 \$602,776,193 Available Funds Unissued but Authorized Debt \$63,000,000 \$63,000,000 Other Capital Funds \$11,002,261 \$11,002,266 Prior Bond Contingency \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$107,801,261 | Wireless Network Deployment | \$22,152,153 | \$0 | | \$22,152,153 |
| Adding Communications Closets on Campus \$0 \$1,267,000 \$1,267,000 Technology (does not include device refresh) \$39,433,847 \$31,258,103 \$0 \$70,691,956 Land \$18,425,880 \$18,425,880 Athletic Facility Cycle Replacement \$0 \$1,791,216 \$1,791,216 White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) \$50,000 \$1,000,000 Available Funds Unissued but Authorized Debt \$63,000,000 \$63,000,000 Other Capital Funds \$11,002,266 Prior Bond Contingency \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$107,801,266 | Local Area Network Refresh | \$0 | \$12,160,000 | | \$12,160,000 |
| Technology (does not include device refresh) \$39,433,847 \$31,258,103 \$0 \$70,691,956 Land \$18,425,880 \$18,425,880 \$18,425,880 \$1,791,216 \$1,791,216 \$1,791,216 \$1,791,216 \$1,791,216 \$1,791,216 \$1,498,232 | Telephone System Upgrade | \$0 | \$5,074,894 | | \$5,074,894 |
| Land \$18,425,880 \$18,425,880 Athletic Facility Cycle Replacement \$0 \$1,791,216 \$1,791,216 White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) Bond Support (6% of construction) \$26,112,952 \$26,112,952 Total Capital Requirements \$494,526,666 \$107,801,261 \$448,266 \$602,776,193 Available Funds Unissued but Authorized Debt \$63,000,000 \$63,000,000 Other Capital Funds \$11,002,261 \$11,002,266 Prior Bond Contingency \$33,799,000 \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$107,801,266 | Adding Communications Closets on Campus | \$0 | \$1,267,000 | | \$1,267,000 |
| Athletic Facility Cycle Replacement \$0 \$1,791,216 \$1,791,216 White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) \$1,498,232 \$26,112,952 Bond Support (6% of construction) \$26,112,952 \$26,112,952 Total Capital Requirements \$494,526,666 \$107,801,261 \$448,266 \$602,776,193 Available Funds Unissued but Authorized Debt \$63,000,000 \$63,000,000 Other Capital Funds \$11,002,261 \$11,002,262 Prior Bond Contingency \$33,799,000 \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$107,801,263 | Technology (does not include device refresh) | \$39,433,847 | \$31,258,103 | \$0 | \$70,691,950 |
| White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) \$1 </td <td>Land</td> <td>\$18,425,880</td> <td></td> <td></td> <td>\$18,425,880</td> | Land | \$18,425,880 | | | \$18,425,880 |
| White Fleet Vehicle Replacement \$0 \$1,498,232 \$1,498,232 Energy Conservation Initiatives (TBD) \$1 </td <td>Athletic Facility Cycle Replacement</td> <td>\$0</td> <td>\$1,791,216</td> <td></td> <td>\$1,791,216</td> | Athletic Facility Cycle Replacement | \$0 | \$1,791,216 | | \$1,791,216 |
| Energy Conservation Initiatives (TBD) \$107,801,261 \$26,112,952 \$ | White Fleet Vehicle Replacement | | | | \$1,498,232 |
| Bond Support (6% of construction) \$26,112,952 \$26,112,952 Total Capital Requirements \$494,526,666 \$107,801,261 \$448,266 \$602,776,192 Available Funds Unissued but Authorized Debt \$63,000,000 \$63,000,000 \$63,000,000 \$63,000,000 \$11,002,261 \$11,002,261 \$11,002,262 \$11,002,262 \$11,002,262 \$11,002,262 \$107,801,261 \$0 \$107,801,262 \$107,80 | · | | | | \$0 |
| Available Funds Unissued but Authorized Debt \$63,000,000 \$63,000,000 Other Capital Funds \$11,002,261 \$11,002,262 Prior Bond Contingency \$33,799,000 \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$107,801,262 | Bond Support (6% of construction) | \$26,112,952 | | | \$26,112,952 |
| Unissued but Authorized Debt \$63,000,000 \$63,000,000 Other Capital Funds \$11,002,261 \$11,002,262 Prior Bond Contingency \$33,799,000 \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$107,801,261 | Total Capital Requirements | \$494,526,666 | \$107,801,261 | \$448,266 | \$602,776,192 |
| Unissued but Authorized Debt \$63,000,000 \$63,000,000 Other Capital Funds \$11,002,261 \$11,002,262 Prior Bond Contingency \$33,799,000 \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$107,801,261 | Available Funds | | | | |
| Other Capital Funds \$11,002,261 \$11,002,262 Prior Bond Contingency \$33,799,000 \$33,799,000 Total Available Funds \$0 \$107,801,261 \$0 \$107,801,262 | | | \$63,000,000 | | \$63,000,000 |
| Total Available Funds \$0 \$107,801,261 \$0 \$107,801,262 | | | | | \$11,002,261 |
| | | | | | \$33,799,000 |
| Grand Total \$494,526,666 \$0 \$448,266 \$494,974,93: | Total Available Funds | \$0 | \$107,801,261 | \$0 | \$107,801,261 |
| | Grand Total | \$494,526,666 | \$0 | \$448,266 | \$494,974,932 |

Fort Bend ISD Capital Plan Contingency Included in Proposed 2014 Bond Program

| | Proposed | | | |
|--|---------------|-------------|--------------|------------------------------------|
| | Project | Contingency | Contingency | |
| Description | Budget | Percent (%) | Amount (\$) | Contingency Source |
| New Construction and Classroom Additions | \$205,057,163 | 16.0% | \$32,809,146 | Jacobs Engineering Soft Cost Model |
| Current Facility Deficiencies | \$113,869,021 | 17.0% | \$19,357,734 | Jacobs Engineering Soft Cost Model |
| Educational Adequacy Deficiencies | \$3,826,189 | 17.0% | \$650,452 | Jacobs Engineering Soft Cost Model |
| Facility Life-Cycle Needs | \$41,761,519 | 17.0% | \$7,099,458 | Jacobs Engineering Soft Cost Model |
| Construction Total | \$364,513,893 | | \$59,916,790 | |
| Security Cameras | \$14,118,000 | 0.0% | \$0 | N/A |
| Security Vestibules | \$4,332,450 | 10.0% | \$433,245 | Fort Bend ISD Operations |
| Window Film | \$1,824,915 | 0.0% | \$0 | N/A |
| Security Fencing | \$1,283,993 | 0.0% | \$0 | N/A |
| Access Control including Video Intercom | \$3,415,000 | 0.0% | \$0 | N/A |
| Emergency Generators | \$3,200,000 | 0.0% | \$0 | N/A |
| Emergency Notification System | \$524,600 | 0.0% | \$0 | N/A |
| Two Way Radio | \$1,432,768 | 0.0% | \$0 | N/A |
| Safety and Security Total | \$30,131,726 | | \$433,245 | |
| Bus Cameras and GPS | \$908,369 | 0.0% | \$0 | N/A |
| Bus Replacement | \$15,000,000 | 0.0% | \$0 | n/A |
| Transportation Total | \$15,908,369 | | \$0 | |
| | | | | |
| Internet Infrastructure Upgrade | \$0 | 0.0% | \$0 | Education Partner Solutions |
| Wide Area Network/Backbone Refresh | \$17,281,694 | 7.4% | \$1,280,125 | Education Partner Solutions |
| Data Center SAN and Virtualization | \$0 | 0.0% | \$0 | N/A |
| Data Center Facilities Modifications | \$0 | 0.0% | \$0 | N/A |
| Wireless Network Deployment | \$22,152,153 | 7.4% | \$1,640,901 | Education Partner Solutions |
| Local Area Network Refresh | \$0 | 0.0% | \$0 | N/A |
| Telephone System Upgrade | \$0 | 0.0% | \$0 | N/A |
| Adding Communications Closets on Campus | \$0 | 0.0% | \$0 | N/A |
| Technology (does not include device refresh) | \$39,433,847 | | \$2,921,026 | |
| Land | \$18,425,880 | 0.0% | \$0 | N/A |
| Athletic Facility Cycle Replacement | \$0 | 0.0% | \$0 | N/A |
| White Fleet Vehicle Replacement | \$0 | 0.0% | \$0 | N/A |
| Bond Support (6% of construction) | \$26,112,952 | 0.0% | \$0 | N/A |
| Grand Total | \$494,526,666 | | \$63,271,061 | 12.8% of Total |

Fort Bend ISD Capital Plan New Construction and Classroom Additions Detail - Phase 1 Only

| | School | Location | Estimated Year Needed | Planning Area | Comments | Estimated Cost Phase 1 | 2014 Bond Proposal | Other Capital Funds | General Fund (Items Under \$5K) |
|---|-----------------------|------------|--------------------------|------------------|---|---------------------------|-----------------------|------------------------|------------------------------------|
| 1 | Elementary 46 | Aliana | 2015-16 | Α | To address enrollment growth | \$25,330,510 | | \$25,330,510 | |
| 2 | Elementary 47 | Riverstone | 2015-16 | В | To address enrollment growth | \$35,760,720 | \$35,760,720 | | |
| 3 | Elementary 48 | TBD | 2015-16 | С | To address enrollment growth | \$25,330,510 | \$25,330,510 | | |
| 4 | Elementary 49 | TBD | 2016-17 | А | To address enrollment growth | \$25,330,510 | \$25,330,510 | | |
| 5 | Elementary 50 | TBD | 2017-18 | А | To address enrollment growth | \$25,330,511 | \$25,330,511 | | |
| 6 | Elementary 51 | TBD | 2019-20 | TBD | To address enrollment growth | \$25,330,512 | \$25,330,512 | | |
| 7 | Middle School 15 | TBD | 2017-18 | С | To address enrollment growth | \$44,923,200 | | \$44,923,200 | |
| 8 | Elementary Classrooms | TBD | 2015-17 | A, B, C | Classroom additions to address enrollment growth | \$21,974,400 | \$21,974,400 | | |
| 9 | Career & Tech Center | TBD | 2017-18 | TBD | District-wide Career and Technology Education Center | \$46,000,000 | \$46,000,000 | | |
| 8 | | | | | Total | \$275,310,873 | \$205,057,163 | \$70,253,710 | \$0 |

| | or. N | | B | | stimated Cost | 2014 Bond | Other Capital | General Fund |
|----------|---------------------------------|---|-------------|----------------------|----------------------|----------------------|---------------|--------------------|
| _ | Site Name | Deficiency Description | Priority 1 | Priority 2 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 1 | Administration Annex | All doors require re-keying Public Address Is Inadequate And Should Be Replaced | \$64,878 | \$10,543 | \$10,543 \$64,878 | \$10,543 \$64,878 | | |
| 3 | | Scuppers Require Replacement | \$04,878 | \$1,196 | \$1,196 | \$04,878 | | \$1,196 |
| 4 | | Skylight Requires Replacement | \$5,450 | 71,150 | \$5,450 | \$5,450 | | \$1,150 |
| 5 | | The Air Handler HVAC Component Requires Replacement | 75,450 | \$699,364 | \$699,364 | \$699,364 | | |
| 6 | | The Exterior Condenser Requires Replacement | | \$11,764 | \$11,764 | \$11,764 | | |
| 7 | | The Metal Roof Architectural Roof Covering Requires Replacement | \$499,633 | | \$499,633 | \$499,633 | | |
| 8 | Administration Annex Total | <u> </u> | \$569,961 | \$722,867 | \$1,292,828 | | | |
| 9 | | | | | | | | |
| 10 | Administration Building | All doors require re-keying | | \$19,842 | \$19,842 | \$19,842 | | |
| 11 | | Asbestos Containing Materials are Present in the Facility | \$35,023 | | \$35,023 | \$35,023 | | |
| 12 | | Public Address Is Inadequate And Should Be Replaced | \$64,986 | | \$64,986 | \$64,986 | | |
| 13 | | The Air Handler HVAC Component Requires Replacement | | \$881,682 | \$881,682 | \$881,682 | | |
| 14 | | The Exterior Condenser Requires Replacement | | \$80,000 | \$80,000 | \$80,000 | | |
| 15 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$2,385 | \$2,385 | | | \$2,385 |
| 16 | Administration Building Total | | \$100,010 | \$983,909 | \$1,083,918 | | | |
| 17 | | | | | | | | |
| | Aquatic Practice Facility | All doors require re-keying | | \$11,006 | \$11,006 | \$11,006 | | |
| 19 | | LC: The Exterior / xWalls (Wall SF Basis) / Wood system is beyond its useful life. | | \$15,000 | \$15,000 | \$15,000 | | |
| - | Aquatic Practice Facility Total | | | \$26,007 | \$26,007 | | | |
| 21 | | All I | | ć25 7 00 | ć25 7 00 | ć25 7 00 | | |
| - | Armstrong Elementary | All doors require re-keying | | \$25,780 | \$25,780 | \$25,780 | | |
| 23 | Armstrong Elementary Total | | | \$25,780 | \$25,780 | | | |
| | Athletic Complex | All doors require re-keying | | \$12,406 | \$12,406 | \$12,406 | | |
| 26 | · | Asphalt paving is damaged and requires replacement | | \$1,093,020 | \$1,093,020 | \$1,093,020 | | |
| 27 | | The Aluminum Window Is Damaged And Requires Replacement | | \$70,902 | \$70,902 | \$70,902 | | |
| 28 | | The Exterior Condenser Requires Replacement | | \$8,110 | \$8,110 | \$8,110 | | |
| 29 | | The Exterior Ramp is not ADA Compliant | \$254,807 | | \$254,807 | \$254,807 | | |
| 30 | | The Interior Door Hardware Requires Replacement | | \$119,597 | \$119,597 | \$119,597 | | |
| 31 | | The Metal Exterior Door Requires Replacement | | \$158,497 | \$158,497 | \$158,497 | | |
| 32 | | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$93,460 | | \$93,460 | \$93,460 | | |
| 33 | | The Overhead Door Requires Replacement | | \$24,222 | \$24,222 | \$24,222 | | |
| 34 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$11,924 | \$11,924 | \$11,924 | | |
| 35 | Athletic Complex Total | | \$348,267 | \$1,498,678 | \$1,846,945 | | | |
| 36 | | | | | | | | |
| - | Austin High School | All doors require re-keying | | \$81,719 | \$81,719 | \$81,719 | | |
| 38 | | Controls Require Repair | | \$17,140 | \$17,140 | \$17,140 | | |
| 39 | | Membrane Flashings At Drain Requires Repair | | \$6,722 | \$6,722 | \$6,722 | | |
| 40 | | Switchgear Is Needed Or Requires Replacement | | \$53,869 | \$53,869 | \$53,869 | | |
| 41 | | The Aluminum Window Is Damaged And Requires Replacement The Matel Fytogica Deep Requires Penlacement | | \$23,812 | \$23,812 | \$23,812 | | |
| 42 43 | | The Metal Exterior Door Requires Replacement The Motor Control Center Is Damaged And Should Be Replaced | | \$91,569 \$11,256 | \$91,569 \$11,256 | \$91,569 \$11,256 | | |
| 44 | | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$2,244,108 | <i>ϕ</i> 11,∠30 | \$11,256 | \$11,256 | | |
| 45 | | The Retractable Bleachers are Damaged and Require Replacement | \$2,244,108 | \$142,767 | \$2,244,108 | \$2,244,108 | | |
| 45 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$5,811 | \$5,811 | \$5,811 | | |
| 47 | | The Wood Roof Subdeck Is Damaged And Requires Replacement | | \$10,069 | \$10,069 | \$10,069 | | |
| | Austin High School Total | The Frederical Subdection Surraged vind requires replacement | \$2,244,108 | \$444,734 | \$2,688,842 | 710,003 | | |
| 49 | | | 7-,,100 | ÷ · · · · · · · | +=,500,012 | | | |
| | Austin Parkway Elementary | All doors require re-keying | | \$22,318 | \$22,318 | \$22,318 | | |
| 51 | , , | Counter Flashing Requires Replacement | | \$14,174 | \$14,174 | \$14,174 | | |
| 52 | | Curbs Require Reflashing | | \$31,675 | \$31,675 | \$31,675 | | |
| 53 | | Edge Metal Requires Replacement | | \$45,477 | \$45,477 | \$45,477 | | |
| 54 | | Exhaust Fan Curbs are too Low and Should be Raised and Reflashed (<8") | | \$37,586 | \$37,586 | \$37,586 | | |
| 55 | | Expansion Joint Cover Should Be Replaced | | \$86,004 | \$86,004 | \$86,004 | | |
| 56 | | Expansion Joint Laps Require Repair | | \$8,030 | \$8,030 | \$8,030 | | |

| 103Briargate ElementaryAll doors require re-keying\$19,478\$19,478\$19,478104Emergency Battery Pack Lighting Is Required\$1,466\$1,466\$1,466105The Aluminum Storefront Exterior Door Requires Replacement\$14,325\$14,325\$14,325106The Boiler HVAC Component Is Damaged And Requires Replacement\$3,235\$3,235\$3,235107The Interior Door Hardware Requires Replacement\$117,636\$117,636\$117,636 | | | | | | | 2014 P | Oth Cit-l | Community |
|---|-----|-----------------------------------|--|-------------|-------------|-------------|-------------|-----------|-------------------|
| Section Committed on National Membrane Report Report Section | | Sita Nama | Deficiency Description | Priority 1 | | | | • | |
| | E 7 | Site Name | · · | Priority 1 | | | • | rulius | (items onder 55k) |
| | | | | | | | . , | | |
| | | | | | | | | | |
| Section Sect | | | | | | | \$77,095 | | ¢244 |
| Memorance Fischings A Brown Regulare (speak of Regular Regul | | | | | | | | | |
| | | | | | . , | | | | |
| Metal Cognit gai prints Feed to ST 1948 5477 5477 5477 5476 | | | | | | | ć7.011 | | \$2,444 |
| Metal Couriner Flashing is Loose Or Changed And Should de Replaced \$4,848 \$4,488 \$4,4 | | | | | | | \$7,011 | | ¢472 |
| Media Roof-To-Curb Flashings And Emanaged And Should Be Released \$1,488 \$1,488 \$1,288 \$1,288 \$1,288 \$1,288 \$1,288 \$1,288 \$1,288 \$1,288 \$1,288 \$1,288 \$1,288 \$1,289 \$1,229 | | | | | | | ¢11.064 | | \$472 |
| | | | Ü | | | | \$11,964 | | ¢4.496 |
| Second S | | | | | | | | | |
| Secondary A Processor Secondary Networks Regard \$1,299 \$1,29 | | | , , | | . , | | | | |
| | | | • | | | | | | |
| The Art Handler MAC Component Requires Replacement | | | | Ć04 407 | \$1,299 | | 604 407 | | \$1,299 |
| The Signature Reputation Paralle Requires Replacement | | | • • | \$91,487 | Ć700 265 | | | | |
| The Single-Ply Membrane Roof Covering Requires Replacement \$1,146,016 \$1,248,010 \$1,248,100 \$1,248, | | | | | | | \$709,265 | | 40 =00 |
| 14 Marie Parkway Elementary Total 51.286,103 51.286,103 51.286,104 51.286,105 51.2 | | | | 4 | \$3,588 | | * | | \$3,588 |
| Teach | | | ine Singie-Piy Membrane Roof Covering Requires Replacement | | A4 455 515 | | \$1,146,616 | | |
| The Statistic School | | Austin Parkway Elementary Total | | \$1,238,103 | \$1,185,713 | \$2,423,816 | | | |
| Membrane Flashings Al Drain Requires Repair So. 111 | | | | | | | | | |
| The Institute Statisting | | Baines Middle School | , , , | | | | . , | | |
| The Mulki-Ply Bittumen Roof Covering Requires Replacement \$1,710,802 \$1,710,8 | | | | | | | \$6,111 | | |
| Section Sect | | | , | | \$3,002 | | | | \$3,002 |
| State Stat | | | The Multi-Ply Bitumen Roof Covering Requires Replacement | | | | \$1,710,802 | | |
| Standard | | Baines Middle School Total | | \$1,710,802 | \$65,936 | \$1,776,738 | | | |
| Same | _ | | | | | | | | |
| Fire Sprinklers Piping is Damaged And Requires Replacement | | Barrington Place Elementary | , , , | | | | \$22,721 | | |
| Second Description Second | | | | | \$803 | | | | \$803 |
| The Existing Sidewalk is Cracked And Poses A Hazard To Accessibility \$3,0075 \$30,015 \$30,015 \$30,015 \$1,200,773 \$1,200,77 | | | | \$175,000 | | | | | |
| The Single-Pky Membrane Roof Covering Requires Replacement | | | Switchgear Is Needed Or Requires Replacement | | \$53,869 | \$53,869 | | | |
| Startington Place Elementary Total S1,375,773 \$107,409 \$1,483,181 | | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$30,015 | \$30,015 | \$30,015 | | |
| Section Sect | 87 | | The Single-Ply Membrane Roof Covering Requires Replacement | \$1,200,773 | | \$1,200,773 | \$1,200,773 | | |
| 90 Blue Ridge Elementary All doors require re-keying \$18,708 \$18,708 \$25,024 \$25,024 \$25,024 \$25,024 \$19,025 \$25,024 \$19,025 \$25,024 \$25,0 | 88 | Barrington Place Elementary Total | | \$1,375,773 | \$107,409 | \$1,483,181 | | | |
| The Aluminum Window Is Damaged And Requires Replacement \$25,024 \$25,02 | 89 | | | | | | | | |
| Section Sect | 90 | Blue Ridge Elementary | All doors require re-keying | | \$18,708 | \$18,708 | \$18,708 | | |
| State Stat | | | | | \$25,024 | \$25,024 | \$25,024 | | |
| 98 Sevie Middle School All doors require re-keying \$55,167 | 92 | | The Exterior Ramp is not ADA Compliant | \$12,601 | | \$12,601 | \$12,601 | | |
| 95 Bowie Middle School All doors require re-keying \$55,167 \$55,167 \$55,167 \$68 Bowie Middle School Total \$55,167 \$55,167 \$55,167 \$68 Bowie Middle School Total \$55,167 \$55,167 \$69 \$60 | 93 | Blue Ridge Elementary Total | | \$12,601 | \$43,732 | \$56,334 | | | |
| 98 Bowie Middle School Total 955,167 955,167 97 98 Brazos Bend Elementary All doors require re-keying 522,100 522,10 | 94 | | | | | | | | |
| 97 | | | All doors require re-keying | | | | \$55,167 | | |
| 98 Brazos Bend Elementary All doors require re-keying \$22,100 \$22,100 \$22,100 99 Commendary LC: The Electrical / Switchgear System Is Beyond Its Useful Life \$133,677 \$133,677 \$133,677 \$133,677 \$133,677 \$100 \$60,000 \$ | _ | Bowie Middle School Total | | | \$55,167 | \$55,167 | | | |
| Standard | _ | | | | | | | | |
| 100 The Roof Air Handler/Exhaust is Damaged And Requires Replacement \$60,000 \$60,000 \$60,000 101 Brazos Bend Elementary Total \$215,777 \$215,777 \$215,777 \$205,775 \$205,777 \$205,777 \$205,777 \$205,777 \$205,775 \$205,777 \$205,777 | | Brazos Bend Elementary | | | | | | | |
| 101 Brazos Bend Elementary Total \$215,777 \$215,777 102 | | | | | | | | | |
| 102 In the property of the Metal Exterior Door Requires Replacement \$19,478 \$19,478 \$19,478 \$19,478 \$19,478 \$19,478 \$19,478 \$19,478 \$19,478 \$19,478 \$19,478 \$19,478 \$19,478 \$19,478 \$1,466 \$1,466 \$1,435 \$14,325 \$11,636 \$117,636 \$117,636 \$117,636 \$117,636 \$117,636 \$117,636 | | | The Roof Air Handler/Exhaust is Damaged And Requires Replacement | | | | \$60,000 | | |
| 103 Briargate Elementary All doors require re-keying \$19,478 \$14,666 \$117,636 \$11 | 101 | Brazos Bend Elementary Total | | | \$215,777 | \$215,777 | | | |
| 104 Emergency Battery Pack Lighting Is Required \$1,466 < | 102 | | | | | | | | |
| 105 The Aluminum Storefront Exterior Door Requires Replacement \$14,325 \$14,325 \$14,325 \$14,325 \$14,325 \$3,235 \$3, | 103 | Briargate Elementary | | | | | \$19,478 | | |
| 106 The Boiler HVAC Component Is Damaged And Requires Replacement \$3,235 \$3,235 \$3,235 \$3,235 \$3,235 \$3,235 \$3,235 \$117,636 | 104 | | | | | | | | \$1,466 |
| 107 The Interior Door Hardware Requires Replacement \$117,636 \$117,636 \$117,636 108 The Metal Exterior Door Requires Replacement \$24,418 \$24,418 \$24,418 109 The Urinal Plumbing Fixtures Are Damaged And Should Be Installed \$4,883 \$4,883 \$4,883 110 Briargate Elementary Total \$185,442 \$185,442 \$185,442 | 105 | | The Aluminum Storefront Exterior Door Requires Replacement | | | | \$14,325 | | |
| 108The Metal Exterior Door Requires Replacement\$24,418\$24,418109The Urinal Plumbing Fixtures Are Damaged And Should Be Installed\$4,883\$4,883110Briargate Elementary Total\$185,442\$185,442111 | 106 | | The Boiler HVAC Component Is Damaged And Requires Replacement | | \$3,235 | \$3,235 | | | \$3,235 |
| 109 The Urinal Plumbing Fixtures Are Damaged And Should Be Installed \$4,883 \$4,883 \$4,883 \$110 Briargate Elementary Total \$185,442 \$185,442 \$111 | 107 | | The Interior Door Hardware Requires Replacement | | \$117,636 | \$117,636 | \$117,636 | | |
| 110 Briargate Elementary Total \$185,442 \$185,442 111 (11) | 108 | | The Metal Exterior Door Requires Replacement | | \$24,418 | \$24,418 | \$24,418 | | |
| 111 | 109 | | The Urinal Plumbing Fixtures Are Damaged And Should Be Installed | | \$4,883 | \$4,883 | | | \$4,883 |
| | 110 | Briargate Elementary Total | | | \$185,442 | \$185,442 | | | |
| 112 Burton Elementary All doors require re-keying \$23,715 \$23,715 \$23,715 | 111 | | | | | | | | |
| | 112 | Burton Elementary | All doors require re-keying | | \$23,715 | \$23,715 | \$23,715 | | |

| | | | | | | 20112 | 01 0 11 | |
|-----|------------------------------|---|----------------|------------------------|---------------------|----------------------|---------------|--------------------|
| | Site Name | Definion on Description | Dui a vitu . 1 | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
| 113 | Site Name | Deficiency Description | Priority 1 | Priority 2 \$12,670 | Phase 1 \$12,670 | Proposal | Funds | (Items Under \$5K) |
| 114 | | Curbs Require Reflashing Expansion Joint Cover Should Be Replaced | | \$17,201 | \$12,670 | \$12,670 \$17,201 | | |
| 115 | | Expansion Joint Laps Require Repair | | \$80,304 | \$80,304 | \$80,304 | | |
| 116 | | Fire Alarm is Missing or Inadequate | \$162,737 | 300,304 | \$162,737 | \$162,737 | | |
| 117 | | LC: The Mechanical / Pkg Units (Count Basis) / Roof Top Unit (DX Gas) system is beyond its useful life. | \$102,737 | \$173,780 | \$173,780 | \$173,780 | | |
| 118 | | LC: The Mechanical / Pkg Units (Count Basis) / Rout Top Onit (DX Gas) system is beyond its useful life. LC: The Mechanical / Pkg Units (Count Basis) / Split DX Unit system is beyond its useful life. | | \$21,388 | \$173,780 | \$21,388 | | |
| 119 | | Membrane Flashings At Equipment Curbs Require Repair | | \$4,207 | \$4,207 | 321,388 | | \$4,207 |
| 120 | | Metal Counter Flashing Is Loose Or Damaged And Should Be Replaced | | \$7,178 | \$7,178 | \$7,178 | | \$4,207 |
| 121 | | Penetration Boot Requires Replacement | | \$4,046 | \$4,046 | \$7,176 | | \$4,046 |
| 122 | | Public Address Is Inadequate And Should Be Replaced | \$125,000 | 34,040 | \$125,000 | \$125,000 | | 54,040 |
| 123 | | Sealant At Penetration Boot Requires Repair | \$123,000 | \$1,949 | \$1,949 | \$123,000 | | \$1,949 |
| 124 | | Sealant At Pitch Pan Is Damaged And Should Be Repaired | | \$3,684 | \$3,684 | | | \$3,684 |
| 125 | | Skylight Requires Replacement | | \$10,093 | \$10,093 | \$10,093 | | \$3,064 |
| 126 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$18,009 | \$10,093 | \$18,009 | | |
| 127 | | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$849,403 | \$10,009 | \$849,403 | \$849,403 | | |
| | Burton Elementary Total | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$1,137,140 | \$378,224 | \$1,515,364 | \$649,403 | | |
| 129 | Burton Elementary Total | | 31,137,140 | 3370,224 | 31,313,304 | | | |
| | Bush High School | All doors require re-keying | | \$94,523 | \$94,523 | \$94,523 | | |
| 131 | Bush riigh School | Shingle Roof Requires Replacement | \$1,830 | 734,323 | \$1,830 | \$34,323 | | \$1,830 |
| 132 | | Switchgear Is Needed Or Requires Replacement | \$1,630 | \$53,869 | \$53,869 | \$53,869 | | \$1,630 |
| 133 | | The Aluminum Window Is Damaged And Requires Replacement | | \$3,636 | \$3,636 | \$33,609 | | \$3,636 |
| 134 | | The Interior Door Hardware Reguires Replacement | | \$27,448 | \$27,448 | \$27,448 | | \$3,030 |
| 135 | | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$69,699 | 327,440 | \$69,699 | \$69,699 | | |
| 136 | | The Wood Exterior Door Is Damaged And Requires Repair | \$09,033 | \$891 | \$891 | \$09,099 | | \$891 |
| | Bush High School Total | The Wood Exterior Door is Damaged And Requires Repair | \$71,529 | \$180,368 | \$251,897 | | | 2021 |
| 138 | Bush riigh School Total | | 371,323 | 3180,308 | \$231,637 | | | |
| | Clements High School | All doors require re-keying | | \$100,551 | \$100,551 | \$100,551 | | |
| 140 | Ciements riigh School | Complete HVAC System Wide Replacement | | \$383,401 | \$383,401 | \$383,401 | | |
| 141 | | Coping Termination At End Wall Is Damaged And Should Be Repaired | | \$5,034 | \$5,034 | \$5,034 | | |
| 142 | | Counter Flashing Requires Replacement | | \$17,009 | \$17,009 | \$17,009 | | |
| 143 | | Curbs Require Reflashing | | \$20,905 | \$20,905 | \$20,905 | | |
| 144 | | Elevator Cab And Or Controls Require Repair | | \$71,022 | \$71,022 | \$71,022 | | |
| 145 | | Elevator Control/Relay Is Damaged And Should Be Replaced | \$8,019 | Ş71,022 | \$8,019 | \$8,019 | | |
| 146 | | Expansion Joint Cover Should Be Replaced | \$8,013 | \$34,402 | \$34,402 | \$34,402 | | |
| 147 | | Expansion Joint Laps Require Repair | | \$6,023 | \$6,023 | \$6,023 | | |
| 148 | | Expansion Joint Termination At End Wall Requires Repair | | \$28,398 | \$28,398 | \$28,398 | | |
| 149 | | LC: The Electrical / Switchgear System Is Beyond Its Useful Life | | \$384,991 | \$384,991 | \$384,991 | | |
| 150 | | Membrane Flashing At Curb (<2') Requires Repair | | \$15,425 | \$15,425 | \$15,425 | | |
| 151 | | Membrane Flashings At Drain Requires Repair | | \$3,666 | \$3,666 | \$15,425 | | \$3,666 |
| 152 | | Membrane Flashings At Equipment Curbs Require Repair | | \$5,609 | \$5,609 | \$5,609 | | 73,000 |
| 153 | | Metal Coping Lap Joints Have Lost Their Seal And Should Be Resealed | | \$755 | \$755 | \$5,005 | | \$755 |
| 154 | | Metal Roof-To-Curb Flashings Are Damaged And Should Be Resealed | | \$3,589 | \$3,589 | | | \$3,589 |
| 155 | | Re-Seal Metal Roof-To-Wall Flashing At Wall | | \$1,529 | \$1,529 | | | \$1,529 |
| 156 | | Shingle Roof Requires Replacement | \$2,635 | 71,323 | \$2,635 | | | \$2,635 |
| 157 | | Skylight Requires Replacement | ۷۷,033 | \$20,186 | \$2,033 | \$20,186 | | روريد |
| 158 | | The Air Handler HVAC Component Requires Replacement | | \$6,350,937 | \$6,350,937 | \$6,350,937 | | |
| 159 | | The Boiler HVAC Component Is Damaged And Requires Replacement | | \$26,201 | \$26,201 | \$26,201 | | |
| 160 | | The Electrical Transformer Requires Replacement | | \$23,531 | \$23,531 | \$23,531 | | |
| 161 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$3,002 | \$3,002 | 723,331 | | \$3,002 |
| 162 | | The Exterior Chiller Requires Replacement | | \$133,766 | \$133,766 | \$133,766 | | 75,002 |
| 163 | | The Metal Roof Architectural Roof Covering Requires Replacement | \$104,090 | 7133,700 | \$104,090 | \$104,090 | | |
| 164 | | The Plumbing / Domestic Water Piping System Is Beyond Its Useful Life | 7104,030 | \$2,009,963 | \$2,009,963 | \$2,009,963 | | |
| 165 | | The Wood Exterior Door Is Damaged And Requires Repair | | \$446 | \$446 | 72,003,303 | | \$446 |
| | Clements High School Total | The Wood Exterior Door is Damaged And Nequires Nepail | \$114,744 | \$9,650,340 | \$9,765,084 | | | 344 0 |
| 167 | Comments in Bri School Fotol | | 7117,744 | 43,030,340 | 75,705,004 | | | |
| | Colony Bend Elementary | All doors require re-keying | | \$19,123 | \$19,123 | \$19,123 | | |
| 100 | co.o, sena Elementary | / m doord require re negring | | 713,123 | 715,125 | 713,123 | | |

| | Site Name | Deficiency Description | Driority 1 | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|-----|-------------------------------------|---|-------------------------|----------------|----------------------------|------------------------------|---------------|--------------------|
| 169 | Site Name | Deficiency Description Generator Requires Replacement | Priority 1 \$160,144 | Priority 2 | Phase 1 \$160,144 | Proposal \$160,144 | Funds | (Items Under \$5K) |
| 170 | | Gutter Joints Require Repair | \$100,144 | \$296 | \$296 | \$100,144 | | \$296 |
| 171 | | Gutters Require Replacement | | \$2,625 | \$2,625 | | | \$2,625 |
| 172 | | LC: The Mechanical / Condenser (Count Basis) / Outside Air Cooled system is beyond its useful life. | | \$17,824 | \$17,824 | \$17,824 | | \$2,623 |
| 173 | | Switchgear Is Needed Or Requires Replacement | | \$53,869 | \$53,869 | \$53,869 | | |
| 174 | | The Exterior Condenser Requires Replacement | | \$8,110 | \$8,110 | \$8,110 | | |
| 175 | | The Motor Control Center Is Damaged And Should Be Replaced | | \$11,256 | \$11,256 | \$11,256 | | |
| 176 | | Thru-Wall Flashing At Rise-Wall Should Be Raised And Reflashed | | \$10,000 | \$10,000 | \$10,000 | | |
| 177 | Colony Bend Elementary Total | | \$160,144 | \$123,103 | \$283,247 | | | |
| 178 | | | | | | | | |
| 179 | Colony Meadows Elementary | All doors require re-keying | | \$21,510 | \$21,510 | \$21,510 | | |
| 180 | | Fire Sprinklers Piping Is Damaged And Requires Repair | \$10,000 | | \$10,000 | \$10,000 | | |
| 181 | | Generator Requires Replacement | \$32,029 | | \$32,029 | \$32,029 | | |
| 182 | | Switchgear Is Needed Or Requires Replacement | | \$53,869 | \$53,869 | \$53,869 | | |
| 183 | | The Air Handler HVAC Component Requires Replacement | | \$1,285,263 | \$1,285,263 | \$1,285,263 | | |
| 184 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$3,002 | \$3,002 | | | \$3,002 |
| 185 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$2,385 | \$2,385 | | | \$2,385 |
| 186 | Colony Meadows Elementary Total | | \$42,029 | \$1,366,028 | \$1,408,057 | | | |
| 187 | | | | | | | | |
| 188 | Commonwealth Elementary | All doors require re-keying | | \$23,311 | \$23,311 | \$23,311 | | |
| 189 | | Emergency Battery Pack Lighting Is Required | | \$13,197 | \$13,197 | \$13,197 | | |
| 190 | | Package Roof Top Unit Requires Replacement | | \$70,000 | \$70,000 | \$70,000 | | |
| 191 | | The Dryvit Exterior Is Damaged And Requires Repair | | \$50,001 | \$50,001 | \$50,001 | | |
| 192 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$3,002 | \$3,002 | | | \$3,002 |
| 193 | | The Exterior Condenser Requires Replacement | | \$20,274 | \$20,274 | \$20,274 | | |
| 194 | | The Metal Roof Subdeck Is Damaged And Requires Replacement | | \$2,552 | \$2,552 | | | \$2,552 |
| | Commonwealth Elementary Total | | | \$182,337 | \$182,337 | | | |
| 196 | | | | 4 | 4 | 4 | | |
| | Cornerstone Elementary | All doors require re-keying | | \$25,323 | \$25,323 | \$25,323 | | |
| | Cornerstone Elementary Total | | | \$25,323 | \$25,323 | | | |
| 199 | C | All de ser assertine de l'action | | ¢c0.002 | ¢c0.002 | ¢c0.002 | | |
| | Crockett Middle School | All doors require re-keying | | \$60,082 | \$60,082 | \$60,082 | | ćaor |
| 201 | | Built Up Roofing (Bur) Membrane Has Holes That Should Be Repaired Coping Termination At End Wall Is Damaged And Should Be Repaired | | \$285 \$336 | \$285 \$336 | | | \$285 \$336 |
| 202 | | Metal Coping Is Damaged Or Loose And Should Be Repaired | | \$5,039 | \$5,039 | \$5,039 | | Ş 5 50 |
| | Crockett Middle School Total | Metal Coping is Daniaged Of Loose And Should be Repaired | | \$65,742 | \$5,059 \$65,742 | \$3,039 | | |
| 205 | CIOCKELL WILddie School Total | | | 303,742 | 303,742 | | | |
| _ | Design & Construction Building | All doors require re-keying | | \$2,134 | \$2,134 | | | \$2,134 |
| 207 | Design & construction building | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$6,003 | \$6,003 | \$6,003 | | 72,134 |
| - | Design & Construction Building Tota | , | | \$8,137 | \$8,137 | ψ0,003 | | |
| 209 | 5 | | | 7-,7 | Ŧ- ,-9 . | | | |
| | Don Cook Natatorium | All doors require re-keying | | \$10,376 | \$10,376 | \$10,376 | | |
| 211 | - | The Distribution Panel Requires Replacement | | \$7,177 | \$7,177 | \$7,177 | | |
| 212 | | The Exterior Condenser Requires Replacement | | \$39,747 | \$39,747 | \$39,747 | | |
| 213 | | The Fan Coil HVAC Component Requires Replacement | | \$43,685 | \$43,685 | \$43,685 | | |
| 214 | | The Panelboard Requires Replacement | | \$7,473 | \$7,473 | \$7,473 | | |
| 215 | | The Power Service Is Inadequate And Should Be Replaced | | \$66,096 | \$66,096 | \$66,096 | | |
| 216 | Don Cook Natatorium Total | | | \$174,553 | \$174,553 | | | |
| 217 | | | | | | | | |
| | Drabek Elementary | All doors require re-keying | | \$23,433 | \$23,433 | \$23,433 | | |
| 219 | | LC: The Mechanical / Cooling - Chillers / Indoor Water Cooled system is beyond its useful life. | | \$325,000 | \$325,000 | \$325,000 | | |
| 220 | | Re-Seal Laps In Open Valley | | \$80,160 | \$80,160 | \$80,160 | | |
| 221 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$2,830 | \$2,830 | | | \$2,830 |
| 222 | Drabek Elementary Total | | | \$431,422 | \$431,422 | | | |
| 223 | | | | | | | | |
| 224 | Dulles Elementary | All doors require re-keying | | \$24,478 | \$24,478 | \$24,478 | | |

| | Cita Nama | Definitional Description | Dui a vita . 1 | | stimated Cost | 2014 Bond | Other Capital Funds | General Fund |
|------------|----------------------------|---|----------------|-------------------------------|-----------------------|-----------------------------|------------------------|--------------------|
| 225 | Site Name | Deficiency Description | Priority 1 | Priority 2 \$80,729 | Phase 1 \$80,729 | Proposal \$80,729 | runas | (Items Under \$5K) |
| 226 | | Package Roof Top Unit Requires Replacement The Air Handler HVAC Component Requires Replacement | | \$2,019,053 | \$2,019,053 | \$2,019,053 | | |
| 227 | | The Chiller HVAC Component is Damaged And Requires Replacement | | \$168,719 | \$168,719 | \$168,719 | | |
| 228 | | The Fan Coil HVAC Component is Buninged into Requires Replacement | | \$2,720 | \$2,720 | \$100,713 | | \$2,720 |
| 229 | | The Package Unit HVAC Component Requires Replacement | | \$4,827 | \$4,827 | | | \$4,827 |
| | Dulles Elementary Total | | | \$2,300,526 | \$2,300,526 | | | 1 /- |
| 231 | • | | | . , , , | . , , | | | |
| 232 | Dulles High School | All doors require re-keying | | \$96,942 | \$96,942 | \$96,942 | | |
| 233 | | Bleachers Are Damaged And Require Replacement | | \$142,767 | \$142,767 | \$142,767 | | |
| 234 | | Drains Are Clogged And Should Be Replaced | | \$155,479 | \$155,479 | \$155,479 | | |
| 235 | | Generator Requires Replacement | \$74,734 | | \$74,734 | \$74,734 | | |
| 236 | | Gutters Require Replacement | | \$200,000 | \$200,000 | \$200,000 | | |
| 237 | | Package Roof Top Unit Requires Replacement | | \$245,995 | \$245,995 | \$245,995 | | |
| 238 | | Public Address Is Inadequate And Should Be Replaced | \$280,217 | | \$280,217 | \$280,217 | | |
| 239 | | Switchgear Is Needed Or Requires Replacement | | \$107,738 | \$107,738 | \$107,738 | | |
| 240 | | The Air Handler HVAC Component Requires Replacement | | \$1,463,000 | \$1,463,000 | \$1,463,000 | | |
| 241 | | The Boiler HVAC Component Is Damaged And Requires Replacement | | \$90,570 | \$90,570 | \$90,570 | | |
| 242 | | The Distribution Panel Requires Replacement | | \$21,530 | \$21,530 | \$21,530 | | |
| 243 | | The Electrical Disconnect Requires Replacement | | \$34,899 | \$34,899 | \$34,899 | | |
| 244 | | The Electrical Transformer Requires Replacement | | \$119,818 | \$119,818 | \$119,818 | | |
| 245 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$13,507 | \$13,507 | \$13,507 | | |
| 246 | | The Exterior Condenser Requires Replacement | | \$8,110 | \$8,110 | \$8,110 | | |
| 247 | | The Fan Coil HVAC Component Requires Replacement | | \$350,942 | \$350,942 | \$350,942 | | ¢4.632 |
| 248 | | The Furnaces HVAC Component Requires Replacement | | \$1,623 | \$1,623 | Ć4F 004 | | \$1,623 |
| 249 250 | | The Interior Door Hardware Requires Replacement | | \$45,094 \$61,046 | \$45,094 \$61,046 | \$45,094 \$61,046 | | |
| 251 | | The Metal Exterior Door Requires Replacement The Motor Control Center Is Damaged And Should Be Replaced | | \$191,346 | \$191,346 | \$191,346 | | |
| 252 | | The Panelboard Requires Replacement | | \$98,804 | \$98,804 | \$98,804 | | |
| 253 | | The Power Service Is Inadequate And Should Be Replaced | | \$322,220 | \$322,220 | \$322,220 | | |
| 254 | | The Radiant Heat HVAC Component Is Damaged And Requires Replacement | | \$2,537 | \$2,537 | Ş322,220 | | \$2,537 |
| 255 | | The Roof Condenser Requires Replacement | | \$19,144 | \$19,144 | \$19,144 | | γ2,337 |
| 256 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$7,600 | \$7,600 | \$7,600 | | |
| | Dulles High School Total | | \$354,951 | \$3,800,709 | \$4,155,660 | Ţ:/J000 | | |
| 258 | 3 | | , , | 1 - 7 7 | , ,, | | | |
| 259 | Dulles Middle School | All doors require re-keying | | \$56,272 | \$56,272 | \$56,272 | | |
| 260 | | Elevator Cab And Or Controls Require Repair | | \$35,511 | \$35,511 | \$35,511 | | |
| 261 | | Elevator Control/Relay Is Damaged And Should Be Replaced | \$8,019 | | \$8,019 | \$8,019 | | |
| 262 | | Gutters Require Replacement | | \$35,006 | \$35,006 | \$35,006 | | |
| 263 | | LC: The Mechanical / Fan Coils (Count Basis) / Chilled Water (Cool) system is beyond its useful life. | | \$314,409 | \$314,409 | \$314,409 | | |
| 264 | | Metal Coping Is Damaged Or Loose And Should Be Replaced | | \$9,953 | \$9,953 | \$9,953 | | |
| 265 | | Re-Seal Metal Roof-To-Wall Flashing At Wall | | \$191 | \$191 | | | \$191 |
| 266 | | The Air Handler HVAC Component Requires Replacement | | \$1,738,161 | \$1,738,161 | \$1,738,161 | | |
| 267 | | The Aluminum Window Is Damaged And Requires Replacement | | \$219,338 | \$219,338 | \$219,338 | | |
| 268 | | The Boiler HVAC Component Is Damaged And Requires Replacement | | \$79,850 | \$79,850 | \$79,850 | | |
| 269 | | The Interior Door Hardware Requires Replacement | | \$672,486 | \$672,486 | \$672,486 | | |
| 270 | | The Metal Exterior Door Requires Replacement | 426 121 | \$67,151 | \$67,151 | \$67,151 | | |
| 271 | | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$26,401 | 67.244 | \$26,401 | \$26,401 | | |
| 272 | Dullos Middlo School Total | The Package Unit HVAC Component Requires Replacement | 624 420 | \$7,241 | \$7,241 | \$7,241 | | |
| 274 | Dulles Middle School Total | | \$34,420 | \$3,235,568 | \$3,269,989 | | | |
| | Elkins High School | All dears require to keying | | ¢00 021 | ¢00 021 | 600 021 | | |
| 276 | EIKIHS HIĞH SCHOOL | All doors require re-keying Complete HVAC System Wide Replacement | | \$88,931 \$390,960 | \$88,931 \$390,960 | \$88,931 \$390,960 | | |
| 277 | | Emergency Lighting Is Inadequate Or Not Present And Should Be Installed | | \$6,857 | \$390,960 | \$6,857 | | |
| 278 | | LC: The Electrical / Emerg Gen (KVA) / Emergency Generator system is beyond its useful life. | \$142,589 | / ده, ن | \$142,589 | \$142,589 | | |
| 279 | | The Air Handler HVAC Component Requires Replacement | 7142,303 | \$863,849 | \$863,849 | \$863,849 | | |
| 280 | | The Chiller HVAC Component Is Damaged And Requires Replacement | | \$261,535 | \$261,535 | \$261,535 | | |
| _00 | | 2 to component is sumaged that negatives neplacement | | γ=0±,000 | ψ=0±,555 | ψ=01,333 | | |

| | | | | | stimated Cost | 2014 Bond | Other Capital | General Fund |
|------------|--------------------------------------|--|---------------|-------------------------------|-------------------------------|-------------|---------------|--------------------|
| | Site Name | Deficiency Description | Priority 1 | Priority 2 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 281 | | The Interior Door Hardware Requires Replacement | | \$19,606 | \$19,606 | \$19,606 | | |
| 282 | Elkins High School Total | The Urinal Plumbing Fixtures Are Damaged And Should Be Installed | \$142,589 | \$9,766 \$1,641,505 | \$9,766 \$1,784,094 | \$9,766 | | |
| 284 | EIKINS HIGH SCHOOL LOCAL | | \$142,589 | \$1,041,505 | \$1,784,094 | | | |
| 285 | Ferndell Henry Center For Learning | All doors require re-keying | | \$18,401 | \$18,401 | \$18,401 | | |
| 286 | Ferndell Henry Center For Learning T | | | \$18,401 | \$18,401 | . , | | |
| 287 | | | | | | | | |
| 288 | First Colony Middle School | All doors require re-keying | | \$44,065 | \$44,065 | \$44,065 | | |
| 289 | | Expansion Joint Cover Should Be Replaced | | \$1,720 | \$1,720 | | | \$1,720 |
| 290 | | Expansion Joint Termination At End Wall Requires Repair | | \$473 | \$473 | | | \$473 |
| 291 | | The Air Handler HVAC Component Requires Replacement | | \$3,758,364 | \$3,758,364 | \$3,758,364 | | |
| 292 | | The Interior Door Hardware Requires Replacement | | \$50,976 | \$50,976 | \$50,976 | | |
| 293 | | The Motor Control Center Is Damaged And Should Be Replaced | | \$11,256 | \$11,256 | \$11,256 | | |
| - | First Colony Middle School Total | | | \$3,866,853 | \$3,866,853 | | | |
| 295 | Fleming Elementary | All doors require re-keying | | \$22,907 | \$22,907 | \$22,907 | | |
| 297 | Fierming Elementary | Curbs Require Reflashing | | \$12,670 | \$12,670 | \$12,670 | | |
| 298 | | Edge Metal Requires Replacement | | \$12,670 | \$12,670 | \$30,318 | | |
| 299 | | Generator Requires Replacement | \$213,525 | 730,310 | \$213,525 | \$213,525 | | |
| 300 | | Membrane Flashings At Metal Edge Require Repair | +/ | \$11,309 | \$11,309 | \$11,309 | | |
| 301 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$60,030 | \$60,030 | \$60,030 | | |
| 302 | | The Exterior Condenser Requires Replacement | | \$33,791 | \$33,791 | \$33,791 | | |
| 303 | | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$847,079 | | \$847,079 | \$847,079 | | |
| 304 | | The Package Unit HVAC Component Requires Replacement | | \$65,166 | \$65,166 | \$65,166 | | |
| 305 | Fleming Elementary Total | | \$1,060,605 | \$236,191 | \$1,296,795 | | | |
| 306 | | | | | | | | |
| - | Fort Settlement Middle School | All doors require re-keying | | \$56,016 | \$56,016 | \$56,016 | | |
| 308 | | Expansion Joint Cover Should Be Replaced | | \$10,751 | \$10,751 | \$10,751 | | |
| 309 | | Gutter Joints Require Repair | | \$41,410 | \$41,410 | \$41,410 | | |
| 310 311 | | Repair Holes In Metal Roof Panels The Water Heater Dismiss Firtures Are Demograd And Should Be Benjaged | | \$50,000 \$2,385 | \$50,000 \$2,385 | \$50,000 | | \$2,385 |
| 312 | Fort Settlement Middle School Total | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$160,561 | \$160,561 | | | \$2,505 |
| 313 | rort Settlement Wildule School Total | | | 3100,301 | 3100,301 | | | |
| - | Garcia Middle School | All doors require re-keying | | \$54,836 | \$54,836 | \$54,836 | | |
| 315 | | Expansion Joint Cover Should Be Replaced | | \$34,402 | \$34,402 | \$34,402 | | |
| 316 | | Expansion Joint Termination At End Wall Requires Repair | | \$473 | \$473 | 1- /- | | \$473 |
| 317 | | Generator Requires Replacement | \$74,734 | · | \$74,734 | \$74,734 | | · |
| 318 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$12,006 | \$12,006 | \$12,006 | | |
| 319 | | The Exterior Cooling Tower Is Damaged And Requires Replacement | | \$71,642 | \$71,642 | \$71,642 | | |
| 320 | | The Fan Coil HVAC Component Requires Replacement | | \$16,323 | \$16,323 | \$16,323 | | |
| 321 | | The Metal Exterior Door Requires Replacement | | \$61,046 | \$61,046 | \$61,046 | | |
| 322 | | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$1,520,713 | Ć454460 | \$1,520,713 | \$1,520,713 | | |
| 323 | Consideration Code 177 1 | The Retractable Bleachers are Damaged and Require Replacement | A4 =0= | \$154,189 | \$154,189 | \$154,189 | | |
| 324 325 | Garcia Middle School Total | | \$1,595,447 | \$404,916 | \$2,000,363 | | | |
| | Glover Elementary | All doors require re-keying | | \$22,318 | \$22,318 | \$22,318 | | |
| 327 | GIOVET Elementary | Fire Alarm is Missing or Inadequate | \$166,647 | 722,310 | \$166,647 | \$166,647 | | |
| 328 | | Public Address Is Inadequate And Should Be Replaced | \$125,000 | | \$100,047 | \$125,000 | | |
| 329 | | The Modified Roof Covering Requires Replacement | \$730,059 | | \$730,059 | \$730,059 | | |
| | Glover Elementary Total | • | \$1,021,705 | \$22,318 | \$1,044,023 | , | | |
| 331 | <u>,</u> | | | | | | | |
| 332 | Goodman Elementary | All doors require re-keying | | \$22,898 | \$22,898 | \$22,898 | | |
| 333 | | Fire Alarm is Missing or Inadequate | \$169,115 | | \$169,115 | \$169,115 | | |
| 334 | | Generator Is Damaged And Requires Repair | | \$45,629 | \$45,629 | \$45,629 | | |
| 335 | | Gutters Require Replacement | | \$350 | \$350 | | | \$350 |
| 336 | | Membrane Flashings At Equipment Curbs Require Repair | | \$1,402 | \$1,402 | | | \$1,402 |

| Sita Nama | Deficiency Description | Drianity 1 | | Stimated Cost | | Other Capital | General Fund |
|------------------------------------|---|---------------------|-----------------------|-----------------------|-----------------------|---------------|-------------------------------|
| Site Name | Deficiency Description Membrane Flashings At Penetration Require Repair | Priority 1 | Priority 2 \$1,188 | Phase 1 \$1,188 | Proposal | Funds | (Items Under \$5K) \$1,188 |
| 338 | Penetration Boot Requires Replacement | | \$2,023 | \$2,023 | | | \$2,023 |
| 339 | Sealant At Penetration Boot Requires Repair | | \$975 | \$975 | | | \$975 |
| 340 | The Metal Roof Architectural Roof Covering Requires Replacement | \$165,000 | ψ3.3 | \$165,000 | \$165,000 | | ψ3.3 |
| 341 | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$31,682 | | \$31,682 | \$31,682 | | |
| 342 | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | , , , , , , | \$2,830 | \$2,830 | , - , | | \$2,830 |
| 343 Goodman Elementary Total | | \$365,797 | \$77,294 | \$443,091 | | | |
| 344 | | | | | | | |
| 345 Hall Stadium | All doors require re-keying | | \$4,359 | \$4,359 | | | \$4,359 |
| 346 | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$6,003 | \$6,003 | \$6,003 | | |
| 347 | The Metal Exterior Door Requires Replacement | | \$12,209 | \$12,209 | \$12,209 | | |
| 348 | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$8,491 | \$8,491 | \$8,491 | | |
| 349 Hall Stadium Total | | | \$31,063 | \$31,063 | | | |
| 350 | | | | | | | |
| 351 Heritage Rose Elementary | All doors require re-keying | | \$35,188 | \$35,188 | \$35,188 | | |
| 352 Heritage Rose Elementary Total | | | \$35,188 | \$35,188 | | | |
| 353 | All doors require re-keying | | ¢10.011 | Ć10 011 | Ć10 011 | | |
| 354 Highlands Elementary 355 | 1 7 0 | ¢12E 000 | \$19,911 | \$19,911 \$125,000 | \$19,911 \$125,000 | | |
| 356 | Public Address Is Inadequate And Should Be Replaced Switchgear Is Needed Or Requires Replacement | \$125,000 | \$53,869 | \$53,869 | \$125,000 | | |
| 357 | The Air Handler HVAC Component Requires Replacement | | \$1,504,841 | \$1,504,841 | \$1,504,841 | | |
| 358 | The Exterior Condenser Requires Replacement | | \$28,859 | \$1,304,841 | \$28,859 | | |
| 359 | The Metal Exterior Door Requires Replacement | | \$30,523 | \$30,523 | \$30,523 | | |
| 360 | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$7,154 | \$7,154 | \$7,154 | | |
| 361 Highlands Elementary Total | The Water Heater Hambing Fixtures file Buildaged file Should be replaced | \$125,000 | \$1,645,158 | \$1,770,158 | ψ7,13 ⁻¹ | | |
| 362 | | +===,=== | + -// | 7-,::0,=00 | | | |
| 363 Hightower High School | All doors require re-keying | | \$95,030 | \$95,030 | \$95,030 | | |
| 364 | Coping Termination At End Wall Is Damaged And Should Be Repaired | | \$1,678 | \$1,678 | | | \$1,678 |
| 365 | Counter Flashing Is Damaged Or Loose And Should Be Repaired | | \$52,651 | \$52,651 | \$52,651 | | |
| 366 | Elevator Cab And Or Controls Require Repair | | \$106,533 | \$106,533 | \$106,533 | | |
| 367 | Elevator Control/Relay Is Damaged And Should Be Replaced | \$8,019 | | \$8,019 | \$8,019 | | |
| 368 | Emergency Battery Pack Lighting Is Required | | \$1,466 | \$1,466 | | | \$1,466 |
| 369 | Emergency Lighting Is Inadequate Or Not Present And Should Be Installed | | \$686 | \$686 | | | \$686 |
| 370 | LC: The Roofing / Roofing System / 10 Metal (Architectural) system is beyond its useful life. | | \$3,468 | \$3,468 | | | \$3,468 |
| 371 | Lead Flashing Requires Repair | | \$10,999 | \$10,999 | \$10,999 | | |
| 372 | Membrane Flashing At Curb (<2') Requires Repair | | \$42,068 | \$42,068 | \$42,068 | | |
| 373 | Membrane Flashing At Parapet (>2') Requires Repair | | \$24,122 | \$24,122 | \$24,122 | | |
| 374 | Metal Coping Is Damaged Or Loose And Should Be Replaced | | \$166,708 | \$166,708 | \$166,708 | | Å545 |
| 375 | Metal Coping Lap Joints Have Lost Their Seal And Should Be Resealed | | \$515 | \$515 | 67.644 | | \$515 |
| 376 377 | Re-Seal Metal Roof-To-Wall Flashing At Wall The Air Handler HVAC Component Requires Replacement | | \$7,644 \$133,000 | \$7,644 \$133,000 | \$7,644 | | |
| 378 | The Air Handler HVAC Component Requires Replacement The Aluminum Window Is Damaged And Requires Replacement | | \$133,000 | \$133,000 \$3,636 | \$133,000 | | \$3,636 |
| 379 | The Electrical Transformer Requires Replacement | | \$9,985 | \$3,030 | \$9,985 | | 33,030 |
| 380 | The Exterior Dry Type Transformer Requires Replacement | | \$14,918 | \$14,918 | \$14,918 | | |
| 381 | The Exterior Dry Type Hansformer Requires Replacement The Exterior Meter Service Is Damaged And Should Be Replaced | | \$13,559 | \$13,559 | \$13,559 | | |
| 382 | The Interior Door Hardware Requires Replacement | | \$1,961 | \$1,961 | \$15,555 | | \$1,961 |
| 383 | The Metal Roof Architectural Roof Covering Requires Replacement | \$4,396,767 | . , | \$4,396,767 | \$4,396,767 | | , ,,,,,,,, |
| 384 | The Overhead Door Requires Replacement | . ,, | \$4,037 | \$4,037 | , , , | | \$4,037 |
| 385 | The Power Service Is Inadequate And Should Be Replaced | | \$3,305 | \$3,305 | | | \$3,305 |
| 386 Hightower High School Total | | \$4,404,786 | \$697,969 | \$5,102,755 | | | |
| 387 | | · | <u> </u> | | | <u> </u> | <u> </u> |
| 388 Hodges Bend Middle School | All doors require re-keying | | \$46,023 | \$46,023 | \$46,023 | | |
| 389 | Bleachers Are Damaged And Require Replacement* needs review figure inconsistent with previous types. | | \$475,891 | \$475,891 | \$475,891 | | |
| 390 | Elevator Control/Relay Is Damaged And Should Be Replaced | \$8,019 | | \$8,019 | \$8,019 | | |
| 391 | Generator Requires Replacement | \$147,991 | | \$147,991 | \$147,991 | | |
| 392 | Switchgear Is Needed Or Requires Replacement | | \$53,869 | \$53,869 | \$53,869 | | |

| | | | | | · | 2014 P | Oth C 'tl | Community |
|------------|---------------------------------|--|----------------------|------------------|--------------------------|-----------------------|------------------------|------------------------------------|
| | Site Name | Deficiency Description | Priority 1 | Priority 2 | stimated Cost Phase 1 | 2014 Bond Proposal | Other Capital Funds | General Fund (Items Under \$5K) |
| 393 | Site Waine | The Air Handler HVAC Component Requires Replacement | Filolity 1 | \$1,852,634 | \$1,852,634 | \$1,852,634 | Tulius | (iteliis olidei \$5k) |
| 394 | | The Aluminum Storefront Exterior Door Requires Replacement | | \$21,488 | \$21,488 | \$21,488 | | |
| 395 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$30,015 | \$30,015 | \$30,015 | | |
| 396 | | The Large Diameter Exhausts/Hoods Are Missing/Damaged And Require Replacement | | \$152,261 | \$152,261 | \$152,261 | | |
| 397 | | The Motor Control Center Is Damaged And Should Be Replaced | | \$101,301 | \$101,301 | \$101,301 | | |
| 398 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$5,661 | \$5,661 | \$5,661 | | |
| 399 | Hodges Bend Middle School Total | | \$156,010 | \$2,739,143 | \$2,895,153 | | | |
| 400 | | | | | | | | |
| | Holley Elementary | All doors require re-keying | | \$23,996 | \$23,996 | \$23,996 | | |
| 402 | | LC: The Mechanical / Cooling - Chillers / Indoor Water Cooled system is beyond its useful life. | | \$325,000 | \$325,000 | \$325,000 | | |
| 403 | Holley Elementary Total | | | \$348,995 | \$348,995 | | | |
| 404 | | All I | | 645.205 | 645.205 | 645 205 | | |
| 405 | Hopson Field House | All doors require re-keying | Ć44.00C | \$15,205 | \$15,205 | \$15,205 | | |
| 406 | | Fire Pump Is Damaged And Requires Repair LC: The Mechanical / Cooling - Chillers / Outdoor Air Cooled system is beyond its useful life. | \$41,996 | \$360,000 | \$41,996 \$360,000 | \$41,996 \$360,000 | | |
| 407 | | The Boiler HVAC Component Is Damaged And Requires Replacement | | \$300,000 | \$360,000 | \$73,318 | | |
| 409 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$5,811 | \$5,811 | \$5,811 | | |
| 410 | | The Water Heater Humbing Fixtures are Damaged And Should be Replaced | \$41,996 | \$454,333 | \$496,329 | \$3,011 | | |
| 411 | nopour icia nouse rota. | | ψ . <u>_</u> ,,,,,, | V.0.1,000 | ¥ .50,025 | | | |
| 412 | Hunters Glen Elementary | All doors require re-keying | | \$20,407 | \$20,407 | \$20,407 | | |
| 413 | | LC: The Roofing / Roofing System / 10 Metal (Architectural) system is beyond its useful life. | | \$11,229 | \$11,229 | \$11,229 | | |
| 414 | | The Metal Exterior Door Requires Replacement | | \$42,732 | \$42,732 | \$42,732 | | |
| 415 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$19,367 | \$19,367 | \$19,367 | | |
| 416 | Hunters Glen Elementary Total | | | \$93,736 | \$93,736 | | | |
| 417 | | | | | | | | |
| | Jones Elementary | All doors require re-keying | | \$23,230 | \$23,230 | \$23,230 | | |
| _ | Jones Elementary Total | | | \$23,230 | \$23,230 | | | |
| 420 | | All I | | 622.027 | 622.027 | 622.027 | | |
| 421 | Jordan Elementary | All doors require re-keying | Ć12 401 | \$23,837 | \$23,837 | \$23,837 | | |
| 422 | | The Metal Roof Architectural Roof Covering Requires Replacement The Multi-Ply Bitumen Roof Covering Requires Replacement | \$12,491 \$50,162 | | \$12,491 \$50,162 | \$12,491 \$50,162 | | |
| 424 | Jordan Elementary Total | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$62,653 | \$23,837 | \$86,490 | \$30,102 | | |
| 425 | Jordan Elementary Total | | 302,033 | 323,637 | 380,430 | | | |
| _ | Kempner Ag | All doors require re-keying | | \$2,177 | \$2,177 | | | \$2,177 |
| 427 | | The Interior Door Hardware Requires Replacement | | \$3,921 | \$3,921 | | | \$3,921 |
| 428 | | The Metal Exterior Door Requires Replacement | | \$7,964 | \$7,964 | \$7,964 | | 1 - 7 - |
| 429 | | The Metal Roof Architectural Roof Covering Requires Replacement | \$41,636 | . , | \$41,636 | \$41,636 | | |
| 430 | Kempner Ag Total | | \$41,636 | \$14,061 | \$55,697 | | | |
| 431 | | | | | | | | |
| | Kempner High School | All doors require re-keying | <u> </u> | \$89,399 | \$89,399 | \$89,399 | | |
| 433 | | Switchgear Is Needed Or Requires Replacement | | \$53,869 | \$53,869 | \$53,869 | | |
| 434 | | The Air Handler HVAC Component Requires Replacement | | \$5,033,168 | \$5,033,168 | \$5,033,168 | | |
| 435 | | The Aluminum Window Is Damaged And Requires Replacement | | \$26,700 | \$26,700 | \$26,700 | | |
| 436 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$15,008 | \$15,008 | \$15,008 | | |
| 437 438 | | The Interior Door Hardware Requires Replacement | | \$45,151 | \$45,151 | \$45,151 | | |
| | Kempner High School Total | The Overhead Door Requires Replacement | | \$32,296 | \$32,296 | \$32,296 | | |
| 440 | | | | \$5,295,592 | \$5,295,592 | | | |
| 441 | | All doors require re-keying | | \$49,770 | \$49,770 | \$49,770 | | |
| 441 | Eure Orympia Miladie School | Generator Requires Replacement | \$48,043 | | \$48,043 | \$48,043 | | |
| 443 | | LC: The Electrical / Auto Xfer Switch / Automatic Transfer Switch system is beyond its useful life. | у ч 0,043 | \$3,565 | \$3,565 | J40,043 | | \$3,565 |
| 444 | | Skylight Requires Replacement | \$24,527 | 45,505 | \$24,527 | \$24,527 | | ,5,505 |
| 445 | | The Aluminum Storefront Exterior Door Requires Replacement | T- :/-=/ | \$121,763 | \$121,763 | \$121,763 | | |
| 446 | | The Aluminum Window Is Damaged And Requires Replacement | | \$101,809 | \$101,809 | \$101,809 | | |
| 447 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$3,002 | \$3,002 | | | \$3,002 |
| 448 | | The Exterior Ramp is not ADA Compliant | \$31,503 | | \$31,503 | \$31,503 | | |

| | | | | | · | 2014 D | Oth C!t-1 | Company I Sound |
|-----|------------------------------------|---|-------------|-------------------------------|-----------------------------------|---|---------------|--------------------|
| | Sita Nama | Deficiency Description | Driority 1 | | Stimated Cost | 2014 Bond | Other Capital | General Fund |
| 449 | Site Name | Deficiency Description The Metal Systemics Dear Requires Perlagement | Priority 1 | Priority 2 \$79,360 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 450 | | The Metal Exterior Door Requires Replacement The Medified Reof Covering Requires Penlacement | \$1,327,068 | \$79,360 | \$79,360 \$1,327,068 | \$79,360 \$1,327,068 | | |
| | Lake Olympia Middle School Total | The Modified Roof Covering Requires Replacement | \$1,327,008 | \$359,267 | \$1,327,008 \$1,790,409 | \$1,327,008 | | |
| 451 | Lake Olympia iviludie School Total | | 31,431,142 | 3339,207 | \$1,790,409 | | | |
| 453 | Lakeview Elementary | All doors require re-keying | | \$24,473 | \$24,473 | \$24,473 | | |
| 454 | zaneview ziementary | Gutters Require Replacement | | \$1,050 | \$1,050 | Ψ2.,3 | | \$1,050 |
| 455 | | LC: The Mechanical / Fan Coils (Count Basis) / Chilled Water (Cool) system is beyond its useful life. | | \$7,486 | \$7,486 | \$7,486 | | 7-/ |
| 456 | | LC: The Mechanical / Pkg Units (Count Basis) / Roof Top Unit (DX Gas) system is beyond its useful life. | | \$23,171 | \$23,171 | \$23,171 | | |
| 457 | | The Aluminum Window Is Damaged And Requires Replacement | | \$49,086 | \$49,086 | \$49,086 | | |
| 458 | | The Chiller HVAC Component Is Damaged And Requires Replacement | | \$136,395 | \$136,395 | \$136,395 | | |
| 459 | | The Exterior Condenser Requires Replacement | | \$37,326 | \$37,326 | \$37,326 | | |
| 460 | | The Exterior Cooling Tower Is Damaged And Requires Replacement | | \$126,601 | \$126,601 | \$126,601 | | |
| 461 | | The Furnaces HVAC Component Requires Replacement | | \$4,735 | \$4,735 | 1 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | | \$4,735 |
| 462 | | The Metal Exterior Door Requires Replacement | | \$36,628 | \$36,628 | \$36,628 | | , , |
| 463 | | The Panelboard Requires Replacement | | \$9,963 | \$9,963 | \$9,963 | | |
| 464 | | The Retractable Bleachers are Damaged and Require Replacement | | \$142,767 | \$142,767 | \$142,767 | | |
| 465 | | The Single-Ply Membrane Roof Covering Requires Replacement | \$1,083,340 | | \$1,083,340 | \$1,083,340 | | |
| 466 | | The Steel Window Is Damaged And Requires Replacement | , ,,- | \$307,846 | \$307,846 | \$307,846 | | |
| 467 | | The Wood Exterior Door Is Damaged And Requires Replacement | | \$47,782 | \$47,782 | \$47,782 | | |
| 468 | Lakeview Elementary Total | | \$1,083,340 | \$955,309 | \$2,038,649 | . , | | |
| 469 | | | , ,,- | , , | , ,,- | | | |
| 470 | Lantern Lane Elementary | All doors require re-keying | | \$20,040 | \$20,040 | \$20,040 | | |
| 471 | , | Skylight Requires Replacement | \$4,088 | | \$4,088 | | | \$4,088 |
| 472 | | The Fan Coil HVAC Component Requires Replacement | . , | \$163,229 | \$163,229 | \$163,229 | | , , |
| 473 | | The Metal Exterior Door Requires Replacement | | \$36,628 | \$36,628 | \$36,628 | | |
| 474 | | The Metal Roof Architectural Roof Covering Requires Replacement | \$12,491 | | \$12,491 | \$12,491 | | |
| 475 | Lantern Lane Elementary Total | <u> </u> | \$16,579 | \$219,896 | \$236,475 | • • | | |
| 476 | , | | | | | | | |
| 477 | Lexington Creek Elementary | All doors require re-keying | | \$22,318 | \$22,318 | \$22,318 | | |
| 478 | | Expansion Joint Cover Should Be Replaced | | \$10,751 | \$10,751 | \$10,751 | | |
| 479 | | Re-Seal Metal Roof-To-Wall Flashing At Wall | | \$306 | \$306 | | | \$306 |
| 480 | | The Air Handler HVAC Component Requires Replacement | | \$1,538,225 | \$1,538,225 | \$1,538,225 | | |
| 481 | | The Exterior Air Handler Is Damaged And Requires Replacement | | \$161,800 | \$161,800 | \$161,800 | | |
| 482 | Lexington Creek Elementary Total | | | \$1,733,399 | \$1,733,399 | | | |
| 483 | | | | | | | | |
| 484 | M.R. Wood | All doors require re-keying | | \$12,583 | \$12,583 | \$12,583 | | |
| 485 | | Expansion Joint Laps Require Repair | | \$2,008 | \$2,008 | | | \$2,008 |
| 486 | | The Asphalt Shingles Roof Covering Is Damaged And Requires Replacement | | \$428,593 | \$428,593 | \$428,593 | | |
| | M.R. Wood Total | | | \$443,184 | \$443,184 | | | |
| 488 | | | | | | | | |
| 489 | Marshall High School | All doors require re-keying | | \$89,691 | \$89,691 | \$89,691 | | |
| 490 | | Damaged Metal Cover Plate | | \$11,265 | \$11,265 | \$11,265 | | |
| 491 | | Gutters Require Replacement | | \$525 | \$525 | | | \$525 |
| 492 | | Joint Between Rake Cover And Roof Panel Requires Re-Sealing | | \$12,993 | \$12,993 | \$12,993 | | |
| 493 | | LC: The Mechanical / Cooling - Chillers / Indoor Water Cooled system is beyond its useful life. | | \$427,767 | \$427,767 | \$427,767 | | |
| 494 | | Open Metal Valley Is Damaged And Should Be Replaced | | \$6,909 | \$6,909 | \$6,909 | | |
| 495 | | Repair Holes In Metal Roof Panels | | \$3,358 | \$3,358 | | | \$3,358 |
| 496 | | The Air Handler HVAC Component Requires Replacement | | \$4,934,428 | \$4,934,428 | \$4,934,428 | | |
| 497 | | The Interior Door Hardware Requires Replacement | | \$205 | \$205 | | | \$205 |
| 498 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$2,830 | \$2,830 | | | \$2,830 |
| | Marshall High School Total | | | \$5,489,971 | \$5,489,971 | | | |
| 500 | | | | | | | | |
| | McAuliffe Middle School | All doors require re-keying | | \$44,067 | \$44,067 | \$44,067 | | |
| 502 | | Generator Requires Replacement | \$160,144 | * | \$160,144 | \$160,144 | | |
| 503 | | Membrane Flashings At Metal Edge Require Repair | | \$170 | \$170 | An c :: | | \$170 |
| 504 | | The Air Handler HVAC Component Requires Replacement | | \$3,247,583 | \$3,247,583 | \$3,247,583 | | |

| | Cita Nama | Definition of Provided to | Dut-utte 4 | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|------------|-----------------------------------|--|---------------|----------------------|----------------------|----------------------|---------------|--------------------|
| 505 | Site Name | Deficiency Description | Priority 1 | Priority 2 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 505 506 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility The Interior Poor Hardware Popular Property Comments The Interior Poor Hardware Poor Hardware Popular Property Comments The Interior Poor Hardware Poo | | \$24,012 | \$24,012 | \$24,012 | | |
| 506 | | The Interior Door Hardware Requires Replacement The Motel Exterior Door Populies Replacement | | \$40,491 \$12,209 | \$40,491 \$12,209 | \$40,491 \$12,209 | | |
| 508 | McAuliffe Middle School Total | The Metal Exterior Door Requires Replacement | \$160.144 | | | \$12,209 | | |
| 508 | MICAUITTE MIDDIE SCHOOL LOTAL | | \$160,144 | \$3,368,531 | \$3,528,675 | | | |
| | Meadows Elementary | All doors require re-keying | | \$19,316 | \$19,316 | \$19,316 | | |
| 511 | ivieadows Elementary | Package Roof Top Unit Requires Replacement | | \$59,296 | \$19,310 | \$59,296 | | |
| 512 | | The Air Handler HVAC Component Requires Replacement | | \$516,636 | \$516,636 | \$516,636 | | |
| 513 | | The Distribution Panel Requires Replacement | | \$21,530 | \$21,530 | \$21,530 | | |
| 514 | | The Electrical Disconnect Requires Replacement | | \$57,583 | \$57,583 | \$57,583 | | |
| 515 | | The Electrical Transformer Requires Replacement | | \$39,939 | \$39,939 | \$39,939 | | |
| 516 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$15,008 | \$15,008 | \$15,008 | | |
| 517 | | The Motor Control Center Is Damaged And Should Be Replaced | | \$146,323 | \$146,323 | \$146,323 | | |
| 518 | | The Panelboard Requires Replacement | | \$44,835 | \$44,835 | \$44,835 | | |
| | Meadows Elementary Total | The Fanciboard Requires Replacement | | \$920,466 | \$920,466 | 744,033 | | |
| 520 | Weadows Elementary Total | | | 7520,400 | 7320,400 | | | |
| | Mission Bend Elementary | All doors require re-keying | | \$23,022 | \$23,022 | \$23,022 | | |
| 522 | 141331011 Della Elementary | Gutters Require Replacement | | \$2,800 | \$2,800 | 723,022 | | \$2,800 |
| 523 | | Metal Roof Jack Is Damaged And Should Be Repaired | | \$248 | \$248 | | | \$248 |
| 524 | | Skylight Requires Replacement | \$1,363 | ÿ2-10 | \$1,363 | | | \$1,363 |
| 525 | | The Chiller HVAC Component Is Damaged And Requires Replacement | 71,303 | \$272,791 | \$272,791 | \$272,791 | | 71,303 |
| 526 | | The Electrical Transformer Requires Replacement | | \$79,878 | \$79,878 | \$79,878 | | |
| 527 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$60,030 | \$60,030 | \$60,030 | | |
| 528 | | The Motor Control Center Is Damaged And Should Be Replaced | | \$11,256 | \$11,256 | \$11,256 | | |
| 529 | | The Power Service Is Inadequate And Should Be Replaced | | \$132,193 | \$132,193 | \$132,193 | | |
| _ | Mission Bend Elementary Total | The Fower service is mudequate And should be replaced | \$1,363 | \$582,218 | \$583,580 | Ģ13 2 ,133 | | |
| 531 | ivission bend Elementary Total | | 71,505 | 7302,210 | 4303,300 | | | |
| 532 | Mission Glen Elementary | All doors require re-keying | | \$20,315 | \$20,315 | \$20,315 | | |
| 533 | , | LC: The Mechanical / Unit Heaters / Electric system is beyond its useful life. | | \$26,735 | \$26,735 | \$26,735 | | |
| 534 | | The Air Handler HVAC Component Requires Replacement | | \$1,013,532 | \$1,013,532 | \$1,013,532 | | |
| 535 | | The Electrical Disconnect Requires Replacement | | \$139,595 | \$139,595 | \$139,595 | | |
| 536 | | The Electrical Transformer Requires Replacement | | \$22,221 | \$22,221 | \$22,221 | | |
| 537 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$3,002 | \$3,002 | . , | | \$3,002 |
| 538 | | The Exterior Condenser Requires Replacement | | \$4,866 | \$4,866 | | | \$4,866 |
| 539 | | The Exterior Cooling Tower Is Damaged And Requires Replacement | | \$180,010 | \$180,010 | \$180,010 | | , , |
| 540 | | The HVAC Terminal Device Requires Replacement | | \$66,289 | \$66,289 | \$66,289 | | |
| 541 | Mission Glen Elementary Total | | | \$1,476,564 | \$1,476,564 | , , | | |
| 542 | • | | | | | | | |
| 543 | Mission West Elementary | All doors require re-keying | | \$22,721 | \$22,721 | \$22,721 | | |
| 544 | | Counter Flashing Requires Replacement | | \$5,670 | \$5,670 | \$5,670 | | |
| 545 | | Expansion Joint Cover Should Be Replaced | | \$17,201 | \$17,201 | \$17,201 | | |
| 546 | | Generator Requires Replacement | \$213,525 | | \$213,525 | \$213,525 | | |
| 547 | | Membrane Flashing At Curb (<2') Requires Repair | | \$140 | \$140 | • | | \$140 |
| 548 | | Membrane Flashings At Equipment Curbs Require Repair | | \$140 | \$140 | | | \$140 |
| 549 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$4,502 | \$4,502 | | | \$4,502 |
| 550 | | The Modified Roof Covering Requires Replacement | \$766,296 | | \$766,296 | \$766,296 | | |
| 551 | Mission West Elementary Total | | \$979,821 | \$50,375 | \$1,030,196 | | | |
| 552 | • | | • • | | | | | |
| 553 | Missouri City Middle School | All doors require re-keying | | \$55,945 | \$55,945 | \$55,945 | | |
| 554 | Missouri City Middle School Total | | | \$55,945 | \$55,945 | • | | |
| 555 | • | | | • | | | | |
| 556 | Oakland Elementary | All doors require re-keying | | \$27,341 | \$27,341 | \$27,341 | | |
| 557 | Oakland Elementary Total | | | \$27,341 | \$27,341 | | | |
| 558 | • | | | | . , | | | |
| | Old Kempner Stadium | All doors require re-keying | | \$5,349 | \$5,349 | \$5,349 | | |
| 560 | · | The Metal Exterior Door Requires Replacement | | \$12,209 | \$12,209 | \$12,209 | | |

| | Cita Nama | Definition of Description | Dut - utto - 4 | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|------------|---------------------------------------|---|----------------|-----------------------------|-----------------------------|----------------------|---------------|----------------------------|
| F.C.1 | Site Name | Deficiency Description | Priority 1 | Priority 2 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 561 | Old Kempner Stadium Total | The Wood Exterior Is Damaged And Requires Replacement | | \$16,526 \$34,085 | \$16,526 \$34,085 | \$16,526 | | |
| 563 | Old Kempher Stadium Total | | | \$34,085 | \$34,085 | | | |
| - | Oyster Creek Elementary | All doors require re-keying | | \$23,301 | \$23,301 | \$23,301 | | |
| 565 | Oyster creek Elementary | LC: The Mechanical / Cooling - Chillers / Outdoor Air Cooled system is beyond its useful life. | | \$449,156 | \$449,156 | \$449,156 | | |
| 566 | | Re-Seal Laps In Open Valley | | \$66,760 | \$66,760 | \$66,760 | | |
| 567 | | Re-Work/Re-Place "Dead Valley" | | \$4,482 | \$4,482 | 700,:00 | | \$4,482 |
| 568 | | The Metal Exterior Door Requires Replacement | | \$24,418 | \$24,418 | \$24,418 | | Ų 1, 10 <u>2</u> |
| 569 | | The Package Unit HVAC Component Requires Replacement | | \$16,895 | \$16,895 | \$16,895 | | |
| 570 | Oyster Creek Elementary Total | | | \$585,012 | \$585,012 | , , | | |
| 571 | | | | | | | | |
| 572 | Palmer Elementary | All doors require re-keying | | \$20,811 | \$20,811 | \$20,811 | | |
| 573 | | Loose/Missing Exposed Panel Fasteners | | \$20,141 | \$20,141 | \$20,141 | | |
| 574 | | Surface or slope / cross-slope of walkway not compliant. | \$8,983 | | \$8,983 | \$8,983 | | |
| 575 | | The Air Handler HVAC Component Requires Replacement | | \$532,000 | \$532,000 | \$532,000 | | |
| 576 | | The Interior Door Hardware Requires Replacement | | \$2,699 | \$2,699 | | | \$2,699 |
| 577 | Palmer Elementary Total | | \$8,983 | \$575,651 | \$584,634 | | | |
| 578 | | | | | | | | |
| 579 | Parks Elementary | All doors require re-keying | | \$23,363 | \$23,363 | \$23,363 | | |
| 580 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$600 | \$600 | | | \$600 |
| 581 | | The Metal Exterior Door Requires Replacement | | \$79,360 | \$79,360 | \$79,360 | | |
| 582 | Parks Elementary Total | | | \$103,323 | \$103,323 | | | |
| 583 | | | | | | | | |
| 584 | Pecan Grove Elementary | All doors require re-keying | | \$19,911 | \$19,911 | \$19,911 | | |
| 585 | | Curbs Require Reflashing | | \$3,167 | \$3,167 | | | \$3,167 |
| 586 | | Expansion Joint Cover Should Be Replaced | | \$4,300 | \$4,300 | | | \$4,300 |
| 587 | | Expansion Joint Laps Require Repair | | \$803 | \$803 | | | \$803 |
| 588 | | Expansion Joint Termination At End Wall Requires Repair | | \$947 | \$947 | | | \$947 |
| 589 | | LC: The Mechanical / Pkg Units (Count Basis) / Split DX Unit system is beyond its useful life. | | \$64,165 | \$64,165 | \$64,165 | | |
| 590 | | LC: The Roofing / Roofing System / Modified Bitumen System Is Beyond Its Useful Life | | \$424,203 | \$424,203 | \$424,203 | | 4 |
| 591 | | Membrane Flashings At Drain Requires Repair | | \$3,666 | \$3,666 | 4 | | \$3,666 |
| 592 | | Membrane Flashings At Metal Edge Require Repair | | \$5,655 | \$5,655 | \$5,655 | | 440 |
| 593 | | Metal Coping Lap Joints Have Lost Their Seal And Should Be Resealed | | \$19 | \$19 | ģ52.0C0 | | \$19 |
| 594 | | Switchgear Is Needed Or Requires Replacement | | \$53,869 | \$53,869 | \$53,869 | | |
| 595 | | The Air Handler HVAC Component Requires Replacement | | \$1,117,426 | \$1,117,426 \$17,941 | \$1,117,426 | | |
| 596 597 | | The Distribution Panel Requires Replacement The Electrical Disconnect Requires Replacement | | \$17,941 \$52,348 | \$17,941 | \$17,941 \$52,348 | | |
| 598 | | The Electrical Disconnect Requires Replacement The Electrical Transformer Requires Replacement | | \$11,765 | \$11,765 | \$11,765 | | |
| 599 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$6,003 | \$6,003 | \$6,003 | | |
| 600 | | The Exterior Condenser Requires Replacement | | \$14,868 | \$14,868 | \$14,868 | | |
| 601 | | The HVAC Terminal Device Reguires Replacement | | \$144,275 | \$144,275 | \$144,275 | | |
| 602 | | The Motor Control Center Is Damaged And Should Be Replaced | | \$11,256 | \$11,256 | \$11,256 | | |
| 603 | | The Panelboard Requires Replacement | | \$73,895 | \$73,895 | \$73,895 | | |
| 604 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$2,830 | \$2,830 | <i>ϕ. 5,533</i> | | \$2,830 |
| | Pecan Grove Elementary Total | The Water Heater Hambing Fixtales File Samages File Should be Replaced | | \$2,033,314 | \$2,033,314 | | | \(\frac{2}{2}\) |
| 606 | , , , , , , , , , , , , , , , , , , , | | | +=,===,=== | + 2,000,021 | | | |
| | PFC Admin Annex | All doors require re-keying | | \$14,278 | \$14,278 | \$14,278 | | |
| 608 | | Controls Require Repair | | \$19,899 | \$19,899 | \$19,899 | | |
| 609 | | Generator Requires Replacement | \$64,058 | | \$64,058 | \$64,058 | | |
| 610 | | Gutter Joints Require Repair | • | \$30 | \$30 | | | \$30 |
| 611 | | Public Address Is Inadequate And Should Be Replaced | \$15,239 | | \$15,239 | \$15,239 | | |
| 612 | | Shingle Roof Requires Replacement | \$120,000 | | \$120,000 | \$120,000 | | |
| 613 | | The Air Handler HVAC Component Requires Replacement | | \$206,371 | \$206,371 | \$206,371 | | |
| 614 | | The Aluminum Window Is Damaged And Requires Replacement | | \$72,720 | \$72,720 | \$72,720 | | |
| 615 | | The Exterior Condenser Requires Replacement | | \$77,292 | \$77,292 | \$77,292 | | |
| 616 | | The Overhead Door Requires Replacement | | \$4,037 | \$4,037 | | | \$4,037 |

| | | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|--|---|-----------------------------|---------------------------------|---------------------------------|-------------|---------------|--------------------|
| Site Name | Deficiency Description | Priority 1 | Priority 2 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 617 PFC Admin Annex Total | , , | \$199,297 | \$394,627 | \$593,924 | • | | • • |
| 618 | | | | | | | |
| 619 Progressive HS | All doors require re-keying | | \$22,605 | \$22,605 | \$22,605 | | |
| 620 | LC: The Mechanical / Pkg Units (Count Basis) / Packaged DX Unit system is beyond its useful life. | | \$231,707 | \$231,707 | \$231,707 | | |
| 621 | Public Address Is Inadequate And Should Be Replaced | \$25,160 | | \$25,160 | \$25,160 | | |
| 622 Progressive HS Total | | \$25,160 | \$254,313 | \$279,473 | | | |
| 623 | | | 400.000 | 400.000 | 400.000 | | |
| 624 Quail Valley Elementary | All doors require re-keying | | \$23,363 | \$23,363 | \$23,363 | | |
| 625 Quail Valley Elementary Total 626 | | | \$23,363 | \$23,363 | | | |
| 627 Quail Valley Middle School | All doors require re-keying | | \$46,948 | \$46,948 | \$46,948 | | |
| 628 | Fire Alarm Panel Requires Replacement | \$7,932 | 340,348 | \$7,932 | \$7,932 | | |
| 629 | LC: The Mechanical / Cooling - Chillers / Outdoor Air Cooled system is beyond its useful life. | 71,552 | \$155,957 | \$155,957 | \$155,957 | | |
| 630 | The Air Handler HVAC Component Requires Replacement | | \$2,486,397 | \$2,486,397 | \$2,486,397 | | |
| 631 | The Aluminum Storefront Exterior Door Requires Replacement | | \$96,694 | \$96,694 | \$96,694 | | |
| 632 | The Panelboard Requires Replacement | | \$3,321 | \$3,321 | | | \$3,321 |
| 633 Quail Valley Middle School Total | · · · | \$7,932 | \$2,789,317 | \$2,797,249 | | | |
| 634 | | | | | | | |
| 635 Ridge Point High School | All doors require re-keying | | \$92,593 | \$92,593 | \$92,593 | | |
| 636 Ridge Point High School Total | | | \$92,593 | \$92,593 | | | |
| 637 | | | | | | | |
| 638 Ridgegate Elementary | All doors require re-keying | | \$21,473 | \$21,473 | \$21,473 | | |
| 639 | Edge Metal Is Damaged And Requires Replacement | | \$11,111 | \$11,111 | \$11,111 | | |
| 640 | Emergency Lighting System Is Damaged Or Missing And Should Be Replaced | 4404.400 | \$46,830 | \$46,830 | \$46,830 | | |
| 641 | Public Address Is Inadequate And Should Be Replaced | \$124,428 | 6764 | \$124,428 | \$124,428 | | 6764 |
| 642 | Re-Seal Metal Roof-To-Wall Flashing At Wall | ć0 F20 | \$764 | \$764 | ¢0.530 | | \$764 |
| 643 Ridgegate Elementary Total | Skylight Requires Replacement | \$9,538 \$133,966 | \$80,179 | \$9,538 \$214,145 | \$9,538 | | |
| 645 | | \$155,500 | 300,173 | 3214,143 | | | |
| 646 Ridgemont Early Child Center | All doors require re-keying | | \$9,069 | \$9,069 | \$9,069 | | |
| 647 Ridgemont Early Child Center Total | This does steep me to the firms | | \$9,069 | \$9,069 | | | |
| 648 | | | 12/222 | , , , , , , | | | |
| 649 Ridgemont Elementary | All doors require re-keying | | \$20,920 | \$20,920 | \$20,920 | | |
| 650 | Fire Alarm is Missing or Inadequate | \$157,411 | | \$157,411 | \$157,411 | | |
| 651 | Package Roof Top Unit Requires Replacement | | \$85,871 | \$85,871 | \$85,871 | | |
| 652 | Public Address Is Inadequate And Should Be Replaced | \$46,470 | | \$46,470 | \$46,470 | | |
| 653 | Re-Seal Metal Roof-To-Wall Flashing At Wall | | \$24,979 | \$24,979 | \$24,979 | | |
| 654 | Skylight Requires Replacement | \$14,000 | | \$14,000 | \$14,000 | | |
| 655 | The Air Handler HVAC Component Requires Replacement | | \$1,197,000 | \$1,197,000 | \$1,197,000 | | |
| 656 | The Aluminum Window Is Damaged And Requires Replacement | | \$102,985 | \$102,985 | \$102,985 | | |
| 657 | The Boiler HVAC Component Is Damaged And Requires Replacement | | \$50,263 | \$50,263 | \$50,263 | | Ć4 34E |
| 658 659 | The Chiller HVAC Component Is Damaged And Requires Replacement The Exterior Chiller Requires Replacement | | \$1,245 \$431,778 | \$1,245 \$431,778 | \$431,778 | | \$1,245 |
| 660 Ridgemont Elementary Total | The Exterior Chiller Requires Replacement | \$217,880 | \$431,778 \$1,915,040 | \$431,778 \$2,132,920 | Ş431,//8 | | |
| 661 | | 3217,080 | 91,913,040 | <i>\$2,</i> 132,320 | | | |
| 662 Sartartia Middle School | All doors require re-keying | | \$56,016 | \$56,016 | \$56,016 | | |
| 663 | Expansion Joint Cover Should Be Replaced | | \$10,751 | \$10,751 | \$10,751 | | |
| 664 | Loose/Missing Exposed Panel Fasteners | | \$60,600 | \$60,600 | \$60,600 | | |
| 665 | Switchgear Is Needed Or Requires Replacement | | \$53,869 | \$53,869 | \$53,869 | | |
| 666 | The Chiller HVAC Component Is Damaged And Requires Replacement | | \$411,826 | \$411,826 | \$411,826 | | |
| 667 | The Exterior Cooling Tower Is Damaged And Requires Replacement | | \$71,642 | \$71,642 | \$71,642 | | |
| 668 | The Motor Control Center Is Damaged And Should Be Replaced | | \$11,256 | \$11,256 | \$11,256 | | |
| 669 Sartartia Middle School Total | | | \$675,960 | \$675,960 | | | |
| 670 | | | | | | | |
| 671 Scanlan Oaks Elementary | All doors require re-keying | | \$24,803 | \$24,803 | \$24,803 | | |
| 672 | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$3,002 | \$3,002 | | | \$3,002 |

| | Site Name | Deficiency Description | Priority 1 | E Priority 2 | stimated Cost Phase 1 | 2014 Bond Proposal | Other Capital Funds | General Fund (Items Under \$5K) |
|------------|----------------------------------|--|------------|---------------------------------|---------------------------------|------------------------|------------------------|------------------------------------|
| 673 | Scanlan Oaks Elementary Total | Dendency Description | 1 Honey 1 | \$27,805 | \$27,805 | Пороза | runus | (items onder \$5k) |
| 674 | • | | | • • | | | | |
| | Schiff Elementary | All doors require re-keying | | \$24,919 | \$24,919 | \$24,919 | | |
| 676 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$18,009 | \$18,009 | \$18,009 | | |
| | Schiff Elementary Total | | | \$42,928 | \$42,928 | | | |
| 678 | Seguin Elementary | All doors require re-keying | | \$24,647 | \$24,647 | \$24,647 | | |
| | Seguin Elementary Total | All doors require re-keying | | \$24,647 | \$24,647 | 324,047 | | |
| 681 | Jegum Elemental y Total | | | Ψ= 1,0 11 | Ψ <u>=</u> .,e | | | |
| 682 | Settlers Way Elementary | All doors require re-keying | | \$20,152 | \$20,152 | \$20,152 | | |
| 683 | | Complete HVAC System Wide Replacement | | \$2,079,620 | \$2,079,620 | \$2,079,620 | | |
| 684 | | Coping Termination At End Wall Is Damaged And Should Be Repaired | | \$336 | \$336 | | | \$336 |
| 685 | | Curbs Require Reflashing | | \$10,136 | \$10,136 | \$10,136 | | |
| 686 | | Expansion Joint Cover Should Be Replaced | | \$4,300 | \$4,300 | | | \$4,300 |
| 687 | | Expansion Joint Laps Require Repair | | \$1,205 | \$1,205 | | | \$1,205 |
| 688 | | Expansion Joint Termination At End Wall Requires Repair | | \$2,840 | \$2,840 | | | \$2,840 |
| 689 690 | | Membrane Flashing At Curb (<2') Requires Repair Membrane Flashing At Parapet (>2') Requires Repair | | \$3,506 \$2,010 | \$3,506 \$2,010 | | | \$3,506 \$2,010 |
| 691 | | Membrane Flashings At Equipment Curbs Require Repair Membrane Flashings At Equipment Curbs Require Repair | | \$2,010 | \$2,010 | | | \$2,010 |
| 692 | | Metal Roof-To-Curb Flashings Are Damaged And Should Be Resealed | | \$2,243 | \$2,243 | | | \$2,243 |
| 693 | | Re-Seal Metal Roof-To-Wall Flashing At Wall | | \$637 | \$637 | | | \$637 |
| 694 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$3,002 | \$3,002 | | | \$3,002 |
| 695 | | The Modified Roof Covering Requires Replacement | \$45,138 | . , | \$45,138 | \$45,138 | | , , |
| 696 | | The Multi-Ply Bitumen Roof Covering Requires Replacement | \$739,235 | | \$739,235 | \$739,235 | | |
| 697 | Settlers Way Elementary Total | | \$784,374 | \$2,131,108 | \$2,915,481 | | | |
| 698 | | | | | | | | |
| | Sienna Crossing Elementary | All doors require re-keying | | \$25,320 | \$25,320 | \$25,320 | | |
| 700 | | Fire Alarm is Missing or Inadequate | \$165,062 | | \$165,062 | \$165,062 | | 4 |
| 701 | | Gutters Require Replacement | | \$525 | \$525 | | | \$525 |
| 702 703 | | Hip/Ridge Requires Replacement | | \$1,176 \$780 | \$1,176 \$780 | | | \$1,176 \$780 |
| 703 | | Laps In Metal Cover At Hip/Ridge Require Resealing Membrane Flashings At Equipment Curbs Require Repair | | \$1,402 | \$1,402 | | | \$1,402 |
| 705 | | Membrane Flashings At Equipment Cords Require Repair Membrane Flashings At Penetration Require Repair | | \$1,402 | \$1,402 | | | \$79 |
| 706 | | Public Address Is Inadequate And Should Be Replaced | \$70,394 | 7,5 | \$70,394 | \$70,394 | | 4 75 |
| 707 | | Re-Seal Metal Roof Panel Laps (Seams) Require Repair And Re-Seal | | \$6,731 | \$6,731 | \$6,731 | | |
| 708 | | The Air Handler HVAC Component Requires Replacement | | \$1,289,104 | \$1,289,104 | \$1,289,104 | | |
| 709 | | The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility | | \$12,006 | \$12,006 | \$12,006 | | |
| 710 | | The Exterior Air Handler Is Damaged And Requires Replacement | | \$106,447 | \$106,447 | \$106,447 | | |
| 711 | | The Metal Roof Architectural Roof Covering Requires Replacement | \$10,409 | | \$10,409 | \$10,409 | | |
| | Sienna Crossing Elementary Total | | \$245,865 | \$1,443,571 | \$1,689,436 | | | |
| 713 | Constant and Middle C. L. L. | All de con accordes de lacción | | ć=0.070 | 650.050 | ć=0.070 | | |
| 714 | Sugar Land Middle School | All doors require re-keying | | \$50,370 | \$50,370 | \$50,370 | | |
| 716 | | Controls Require Repair Public Address Is Inadequate And Should Be Replaced | \$108,682 | \$275,963 | \$275,963 \$108,682 | \$275,963 \$108,682 | | |
| 717 | | The Air Handler HVAC Component Requires Replacement | \$100,002 | \$1,748,740 | \$1,748,740 | \$1,748,740 | | |
| 718 | | The Exterior Chiller Requires Replacement | | \$332,500 | \$332,500 | \$332,500 | | |
| 719 | | The Exterior Cooling Tower Is Damaged And Requires Replacement | | \$350,582 | \$350,582 | \$350,582 | | |
| 720 | | The Metal Exterior Door Requires Replacement | | \$36,628 | \$36,628 | \$36,628 | | |
| 721 | | The Retractable Bleachers are Damaged and Require Replacement | | \$142,767 | \$142,767 | \$142,767 | | |
| | Sugar Land Middle School Total | | \$108,682 | \$2,937,550 | \$3,046,232 | | | |
| 723 | | | | | | | | |
| | Sugar Mill Elementary | All doors require re-keying | | \$20,579 | \$20,579 | \$20,579 | | |
| 725 | | LC: The Mechanical / Pkg Units (Count Basis) / Split DX Unit system is beyond its useful life. | | \$42,777 | \$42,777 | \$42,777 | | |
| 726 727 | | The Air Handler HVAC Component Requires Replacement | | \$826,901 | \$826,901 | \$826,901 | | |
| | Sugar Mill Elementary Total | The HVAC Terminal Device Requires Replacement | | \$159,872 \$1,050,129 | \$159,872 \$1,050,129 | \$159,872 | | |
| 128 | Jugar IVIIII Elementary Total | | | \$1,U3U,129 | ş1,U3U,129 | | | |

| Estima Es | ated Cost | 2014 Bond | Other Capital | General Fund |
|--|------------------------------|-----------------------|---------------|--------------------|
| Site Name Deficiency Description Priority 1 Priority 2 Ph | hase 1 | Proposal | Funds | (Items Under \$5K) |
| 729 | 40.400 | 40.400 | | |
| 730 Technical Education Center All doors require re-keying \$9,138 | \$9,138 | \$9,138 | | |
| 731 Package Roof Top Unit Requires Replacement \$54,486 | \$54,486 \$57,441 | \$54,486 \$57,441 | | |
| 732 Public Address Is Inadequate And Should Be Replaced \$57,441 733 Technical Education Center Total \$57,441 | \$57,441 \$121,064 | \$57,441 | | |
| 734 303,024 303,024 | 3121,004 | | | |
| 735 Townewest Elementary All doors require re-keying \$21,654 | \$21,654 | \$21,654 | | |
| 736 Skylight Requires Replacement \$1,363 \$673 | \$2,035 | Ţ==,00 · | | \$2,035 |
| 737 Switchgear Is Needed Or Requires Replacement \$53,869 | \$53,869 | \$53,869 | | |
| 738 The Air Handler HVAC Component Requires Replacement \$68,790 | \$68,790 | \$68,790 | | |
| 739 The Boiler HVAC Component Is Damaged And Requires Replacement \$26,201 | \$26,201 | \$26,201 | | |
| 740 The Chiller HVAC Component Is Damaged And Requires Replacement \$136,395 | \$136,395 | \$136,395 | | |
| 741 The Distribution Panel Requires Replacement \$21,530 | \$21,530 | \$21,530 | | |
| 742 The Electrical Transformer Requires Replacement \$29,954 | \$29,954 | \$29,954 | | |
| The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility \$1,201 | \$1,201 | | | \$1,201 |
| 744 The Exterior Condenser Requires Replacement \$4,705 | \$4,705 | | | \$4,705 |
| 745 The Interior Door Hardware Requires Replacement \$35,092 | \$35,092 | \$35,092 | | |
| 746 The Metal Roof Structural Roof Covering Is Damaged And Requires Replacement \$41,887 747 The Motor Control Center Is Damaged And Should Be Replaced \$258,879 | \$41,887 | \$41,887 | | |
| | \$258,879 \$8,074 | \$258,879 \$8,074 | | |
| 748The Overhead Door Requires Replacement\$8,074749The Panelboard Requires Replacement\$50,647 | \$50,647 | \$50,647 | | |
| 750 Townewest Elementary Total \$43,250 \$717,665 | \$760,915 | \$30,047 | | |
| 751 751 | 7700,313 | | | |
| 752 Trammel Fresno Ag All doors require re-keying \$2,177 | \$2,177 | | | \$2,177 |
| 753 The Fire Hydrant Is Damaged And Requires Repair \$758 | \$758 | | | \$758 |
| 754 The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced \$2,830 | \$2,830 | | | \$2,830 |
| 755 Trammel Fresno Ag Total \$758 \$5,007 | \$5,764 | | | |
| 756 | | | | |
| 757 Transportation Center All doors require re-keying \$6,493 | \$6,493 | \$6,493 | | |
| 758 LC: The Fire and Life Safety / Fire Alarm System Is Beyond Its Useful Life \$70,000 | \$70,000 | \$70,000 | | |
| C: The Mechanical / Fan Coils (Count Basis) / Electric (Heat) system is beyond its useful life. \$175,000 | \$175,000 | \$175,000 | | |
| 760 The Air Handler HVAC Component Requires Replacement \$133,000 | \$133,000 | \$133,000 | | |
| 761 The Asphalt Shingles Roof Covering Is Damaged And Requires Replacement \$717 | \$717 | Ć40.40C | | \$717 |
| 762 The Clear Carbonate Roof Covering Is Damaged And Requires Replacement \$10,106 | \$10,106 | \$10,106 | | |
| 763 The Metal Roof Architectural Roof Covering Requires Replacement \$530,860 764 The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced \$11,621 | \$530,860 | \$530,860 \$11,621 | | |
| 764 The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced \$11,621 765 Transportation Center Total \$600,859 \$336,936 | \$11,621 \$937,796 | \$11,021 | | |
| 766 766 766 766 766 766 766 766 766 766 | 337,730 | | | |
| 767 Transportation West All doors require re-keying \$6,204 | \$6,204 | \$6,204 | | |
| 768 Generator Requires Replacement \$26,691 | \$26,691 | \$26,691 | | |
| 769 LC: The Mechanical / Pkg Units (Count Basis) / Split DX Unit system is beyond its useful life. \$64,165 | \$64,165 | \$64,165 | | |
| 770 Shingle Roof Requires Replacement \$14,638 | \$14,638 | \$14,638 | | |
| 771 The Electrical Transformer Requires Replacement \$9,985 | \$9,985 | \$9,985 | | |
| 772 The Metal Exterior Door Requires Replacement \$12,209 | \$12,209 | \$12,209 | | |
| 773 The Wood Exterior Is Damaged And Requires Replacement \$6,096 | \$6,096 | \$6,096 | | |
| 774 Transportation West Total \$41,329 \$98,658 | \$139,987 | | | |
| 775 | | | | |
| 776 Travis High School All doors require re-keying \$93,161 | \$93,161 | \$93,161 | | |
| 777 Travis High School Total \$93,161 | \$93,161 | | | |
| 778 770 Welliar Station Florenters All doors require to leaving | ć22.724 | 622.724 | | |
| 779 Walker Station Elementary All doors require re-keying \$22,721 | \$22,721 | \$22,721 | | |
| 780 Switchgear Is Needed Or Requires Replacement \$107,738 781 The Distribution Panel Requires Replacement \$7,177 | \$107,738 \$7,177 | \$107,738 \$7,177 | | |
| 781 The Distribution Panel Requires Replacement \$7,177 782 The Existing Sidewalk Is Cracked And Poses A Hazard To Accessibility \$6,003 | \$6,003 | \$6,003 | | |
| 762 The Existing Sidewark is Cracked And Poses A Hazard to Accessibility \$0,005 783 The Metal Exterior Door Requires Replacement \$24,418 | \$24,418 | \$6,003 | | |
| 784 Walker Station Elementary Total \$168,058 | \$168,058 | | | |

| | | | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|-----|-------------------------------|---|--------------|--------------|----------------|---------------|---------------|--------------------|
| | Site Name | Deficiency Description | Priority 1 | Priority 2 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 785 | | | | | | | | |
| | Warehouse Center | All doors require re-keying | | \$19,010 | \$19,010 | \$19,010 | | |
| 787 | | Skylight Requires Replacement | \$5,450 | | \$5,450 | \$5,450 | | |
| 788 | | The Air Handler HVAC Component Requires Replacement | | \$133,000 | \$133,000 | \$133,000 | | |
| 789 | | The Exterior Condenser Requires Replacement | | \$19,101 | \$19,101 | \$19,101 | | |
| 790 | | The Metal Roof Subdeck Is Damaged And Requires Replacement | | \$3,828 | \$3,828 | | | \$3,828 |
| 791 | | The Modified Roof Covering Requires Replacement | \$530,195 | | \$530,195 | \$530,195 | | |
| 792 | | The Water Heater Plumbing Fixtures Are Damaged And Should Be Replaced | | \$5,215 | \$5,215 | \$5,215 | | |
| 793 | Warehouse Center Total | | \$535,646 | \$180,155 | \$715,801 | | | |
| 794 | | | | | | | | |
| 795 | Warehouse Sugar Land | All doors require re-keying | | \$2,576 | \$2,576 | | | \$2,576 |
| 796 | | The Clear Carbonate Roof Covering Is Damaged And Requires Replacement | | \$16,843 | \$16,843 | \$16,843 | | |
| 797 | | The Metal Roof Architectural Roof Covering Requires Replacement | \$208,180 | | \$208,180 | \$208,180 | | |
| 798 | Warehouse Sugar Land Total | | \$208,180 | \$19,419 | \$227,600 | | | |
| 799 | | | | | | | | |
| 800 | Willowridge High School | All doors require re-keying | | \$104,956 | \$104,956 | \$104,956 | | |
| 801 | | Built Up Roofing (Bur) Lap Seams Require Repair | | \$839 | \$839 | | | \$839 |
| 802 | | Electrical Power Requires Re-Routing | | \$623,827 | \$623,827 | \$623,827 | | |
| 803 | | Elevator Cab And Or Controls Require Repair | | \$35,511 | \$35,511 | \$35,511 | | |
| 804 | | Elevator Control/Relay Is Damaged And Should Be Replaced | \$8,019 | | \$8,019 | \$8,019 | | |
| 805 | | Generator Requires Replacement | \$266,907 | | \$266,907 | \$266,907 | | |
| 806 | | Public Address Is Inadequate And Should Be Replaced | \$14,259 | | \$14,259 | \$14,259 | | |
| 807 | | Skylight Requires Replacement | \$5,450 | | \$5,450 | \$5,450 | | |
| 808 | | The Air Handler HVAC Component Requires Replacement | • • | \$7,013,777 | \$7,013,777 | \$7,013,777 | | |
| 809 | | The Exterior Chiller Requires Replacement | | \$500,000 | \$500,000 | \$500,000 | | |
| 810 | | The Exterior Dry Type Transformer Requires Replacement | | \$185,892 | \$185,892 | \$185,892 | | |
| 811 | | The Metal Exterior Door Requires Replacement | | \$54,941 | \$54,941 | \$54,941 | | |
| 812 | | The Roof Condenser Requires Replacement | | \$4,786 | \$4,786 | | | \$4,786 |
| 813 | Willowridge High School Total | · · | \$294,635 | \$8,524,530 | \$8,819,165 | | | . , |
| 814 | <u> </u> | | . , | . , , , | | | | |
| _ | Grand Total | | \$25,719,430 | \$88,427,135 | \$114,146,566 | \$113,869,021 | \$0 | \$277,545 |

7/18/14

| | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|--------------------------------------|--|------------|----------------|-----------|---------------|--------------------|
| Site Name | Deficiency Description | Priority 2 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 1 Armstrong Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | · | | \$3,700 |
| 2 | School site lacks appropriate lighting. | \$48,580 | \$48,580 | \$48,580 | | |
| 3 Armstrong Elementary Total | | \$52,280 | \$52,280 | | | |
| 4 | | | | | | |
| 5 Austin Parkway Elementary | School site lacks appropriate lighting. | \$136,025 | \$136,025 | \$136,025 | | |
| 6 Austin Parkway Elementary Total | | \$136,025 | \$136,025 | | | |
| 7 | | | | | | |
| 8 Baines Middle School | Room lighting is inadequate or in poor condition. | \$225,061 | \$225,061 | \$225,061 | | |
| 9 Baines Middle School Total | | \$225,061 | \$225,061 | | | |
| 10 | | | | | | |
| 11 Barrington Place Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 12 Barrington Place Elementary Total | | \$3,700 | \$3,700 | | | |
| 13 | | | | | | |
| 14 Blue Ridge Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 15 Blue Ridge Elementary Total | | \$3,700 | \$3,700 | | | |
| 16 | | | | | | |
| 17 Brazos Bend Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 18 | Room lighting is inadequate or in poor condition. | \$12,623 | \$12,623 | \$12,623 | | |
| 19 Brazos Bend Elementary Total | | \$16,323 | \$16,323 | | | |
| 20 | | | | | | |
| 21 Briargate Elementary | School site lacks appropriate lighting. | \$136,025 | \$136,025 | \$136,025 | | |
| 22 Briargate Elementary Total | | \$136,025 | \$136,025 | | | |
| 23 | | | | | | |
| 24 Bush High School | School site lacks appropriate lighting. | \$97,160 | \$97,160 | \$97,160 | | |
| 25 Bush High School Total | | \$97,160 | \$97,160 | | | |
| 26 | | | | | | |
| 27 Clements High School | School site lacks appropriate lighting. | \$121,450 | \$121,450 | \$121,450 | | |
| 28 Clements High School Total | | \$121,450 | \$121,450 | | | |
| 29 | | | | | | |
| 30 Colony Bend Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | , | | \$3,700 |
| 31 | School site lacks appropriate lighting. | \$34,006 | \$34,006 | \$34,006 | | |
| 32 Colony Bend Elementary Total | | \$37,706 | \$37,706 | | | |
| 33 | | | | | | |
| 34 Colony Meadows Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 35 | School site lacks appropriate lighting. | \$48,580 | \$48,580 | \$48,580 | | |
| 36 Colony Meadows Elementary Total | | \$52,280 | \$52,280 | | | |
| 37 | | 4 | 4 | | | |
| 38 Cornerstone Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 39 Cornerstone Elementary Total | | \$3,700 | \$3,700 | | | |
| 40 | | 4.000- | 4.00.000 | 442225 | | |
| 41 Dulles Elementary | School site lacks appropriate lighting. | \$126,309 | \$126,309 | \$126,309 | | |

| | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|-------------------------------------|--|------------|----------------|-----------|---------------|--------------------|
| Site Name | Deficiency Description | Priority 2 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 42 Dulles Elementary Total | , | \$126,309 | \$126,309 | • | | (|
| 43 | | | · | | | |
| 44 First Colony Middle School | School site lacks appropriate lighting. | \$189,462 | \$189,462 | \$189,462 | | |
| 45 First Colony Middle School Total | | \$189,462 | \$189,462 | | | |
| 46 | | | | | | |
| 47 Fleming Elementary | School site lacks appropriate lighting. | \$77,729 | \$77,729 | \$77,729 | | |
| 48 Fleming Elementary Total | | \$77,729 | \$77,729 | | | |
| 49 | | | | | | |
| 50 Glover Elementary | School site lacks appropriate lighting. | \$136,025 | \$136,025 | \$136,025 | | |
| 51 Glover Elementary Total | | \$136,025 | \$136,025 | | | |
| 52 | | | | | | |
| 53 Hodges Bend Middle School | School site lacks appropriate lighting. | \$77,729 | \$77,729 | \$77,729 | | |
| 54 Hodges Bend Middle School Total | | \$77,729 | \$77,729 | | | |
| 55 | | | | | | |
| 56 Holley Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 57 | School site lacks appropriate lighting. | \$34,006 | \$34,006 | \$34,006 | | |
| 58 Holley Elementary Total | | \$37,706 | \$37,706 | | | |
| 59 | | | | | | |
| 60 Hunters Glen Elementary | School site lacks appropriate lighting. | \$136,025 | \$136,025 | \$136,025 | | |
| 61 Hunters Glen Elementary Total | | \$136,025 | \$136,025 | | | |
| 62 | | | | | | |
| 63 Jones Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 64 Jones Elementary Total | | \$3,700 | \$3,700 | | | |
| 65 | | | | | | |
| 66 Kempner High School | School site lacks appropriate lighting. | \$121,450 | \$121,450 | \$121,450 | | |
| 67 Kempner High School Total | | \$121,450 | \$121,450 | | | |
| 68 | | | | | | |
| 69 Lake Olympia Middle School | School site lacks appropriate lighting. | \$77,729 | \$77,729 | \$77,729 | | |
| 70 Lake Olympia Middle School Total | | \$77,729 | \$77,729 | | | |
| 71 | | | | | | |
| 72 Lakeview Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 73 | School lacks an appropriate intrusion system. | \$38,693 | \$38,693 | \$38,693 | | |
| 74 | School site lacks appropriate lighting. | \$136,025 | \$136,025 | | | |
| 75 Lakeview Elementary Total | | \$178,418 | \$178,418 | | | |
| 76 | | | | | | |
| 77 Lantern Lane Elementary | K Play Area Requires Impact Resistant Material | \$42,086 | \$42,086 | | | |
| 78 | School site lacks appropriate lighting. | \$136,025 | \$136,025 | | | |
| 79 Lantern Lane Elementary Total | | \$178,110 | \$178,110 | | | |
| 80 | | 420.112 | 620.110 | 420.412 | | |
| 81 Lexington Creek Elementary | Room lighting is inadequate or in poor condition. | \$20,112 | \$20,112 | | | |
| 82 | School site lacks appropriate lighting. | \$53,439 | \$53,439 | \$53,439 | | |

| | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|---------------------------------------|--|------------|----------------|-----------|---------------|--------------------|
| Site Name | Deficiency Description | Priority 2 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 83 Lexington Creek Elementary Total | Denote they Description | \$73,551 | \$73,551 | 1100000 | 1 41145 | (nems ender pon) |
| 84 | | · , | · , | | | |
| 85 M.R. Wood | School site lacks appropriate lighting. | \$24,290 | \$24,290 | \$24,290 | | |
| 86 M.R. Wood Total | | \$24,290 | \$24,290 | | | |
| 87 | | | | | | |
| 88 McAuliffe Middle School | School site lacks appropriate lighting. | \$184,605 | \$184,605 | \$184,605 | | |
| 89 McAuliffe Middle School Total | | \$184,605 | \$184,605 | | | |
| 90 | | | | | | |
| 91 Meadows Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 92 Meadows Elementary Total | | \$3,700 | \$3,700 | | | |
| 93 | | | | | | |
| 94 Mission Bend Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 95 | Room lighting is inadequate or in poor condition. | \$27,443 | \$27,443 | \$27,443 | | |
| 96 | School site lacks appropriate lighting. | \$126,309 | \$126,309 | \$126,309 | | |
| 97 Mission Bend Elementary Total | | \$157,452 | \$157,452 | | | |
| 98 | | | | | | |
| 99 Mission Glen Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 100 | Room lighting is inadequate or in poor condition. | \$22,107 | \$22,107 | \$22,107 | | |
| 101 | School site lacks appropriate lighting. | \$87,445 | \$87,445 | \$87,445 | | |
| 102 Mission Glen Elementary Total | | \$113,251 | \$113,251 | | | |
| 103 | | | | | | |
| 104 Mission West Elementary | School site lacks appropriate lighting. | \$53,439 | \$53,439 | \$53,439 | | |
| 105 Mission West Elementary Total | | \$53,439 | \$53,439 | | | |
| 106 | | | | | | |
| 107 Missouri City Middle School | School site lacks appropriate lighting. | \$14,574 | \$14,574 | \$14,574 | | |
| 108 Missouri City Middle School Total | | \$14,574 | \$14,574 | | | |
| 109 | | | | | | |
| 110 Palmer Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 111 | School site lacks appropriate lighting. | \$121,450 | \$121,450 | \$121,450 | | |
| 112 Palmer Elementary Total | | \$125,150 | \$125,150 | | | |
| 113 | | | | | | |
| 114 Parks Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 115 | Room lighting is inadequate or in poor condition. | \$1,836 | \$1,836 | | | \$1,836 |
| 116 Parks Elementary Total | | \$5,536 | \$5,536 | | | |
| 117 | | | 44 | | | 4 |
| 118 Quail Valley Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 119 Quail Valley Elementary Total | | \$3,700 | \$3,700 | | | |
| 120 | B. 1919 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - | 4.00:- | 4.00- | 4.00.0 | | |
| 121 Quail Valley Middle School | Room lighting is inadequate or in poor condition. | \$10,049 | \$10,049 | \$10,049 | | |
| 122 | School site lacks appropriate lighting. | \$77,729 | \$77,729 | \$77,729 | | |
| 123 Quail Valley Middle School Total | | \$87,778 | \$87,778 | | | |

| | | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|-----|----------------------------------|--|-------------|----------------|-------------|---------------|--------------------|
| | Site Name | Deficiency Description | Priority 2 | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 124 | | | | | | | |
| 125 | Settlers Way Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 126 | | School site lacks appropriate lighting. | \$126,309 | \$126,309 | \$126,309 | | |
| 127 | Settlers Way Elementary Total | | \$130,009 | \$130,009 | | | |
| 128 | | | | | | | |
| 129 | Sugar Land Middle School | School site lacks appropriate lighting. | \$174,889 | \$174,889 | \$174,889 | | |
| 130 | Sugar Land Middle School Total | | \$174,889 | \$174,889 | | | |
| 131 | | | | | | | |
| 132 | Sugar Mill Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 133 | Sugar Mill Elementary Total | | \$3,700 | \$3,700 | | | |
| 134 | | | | | | | |
| 135 | Technical Education Center | School site lacks appropriate lighting. | \$9,716 | \$9,716 | \$9,716 | | |
| 136 | Technical Education Center Total | | \$9,716 | \$9,716 | | | |
| 137 | | | | | | | |
| 138 | Townewest Elementary | Room lighting is inadequate or in poor condition. | \$27,399 | \$27,399 | \$27,399 | | |
| 139 | | School site lacks appropriate lighting. | \$136,025 | \$136,025 | \$136,025 | | |
| 140 | Townewest Elementary Total | | \$163,423 | \$163,423 | | | |
| 141 | | | | | | | |
| 142 | Travis High School | School site lacks appropriate lighting. | \$242,901 | \$242,901 | \$242,901 | | |
| 143 | Travis High School Total | | \$242,901 | \$242,901 | | | |
| 144 | | | | | | | |
| 145 | Walker Station Elementary | K playground not appropriately fenced or buffered. | \$3,700 | \$3,700 | | | \$3,700 |
| 146 | Walker Station Elementary Total | | \$3,700 | \$3,700 | | | |
| 147 | | | | | | | |
| 148 | Willowridge High School | School site lacks appropriate lighting. | \$97,160 | \$97,160 | \$97,160 | | |
| 149 | Willowridge High School Total | | \$97,160 | \$97,160 | | | |
| 150 | | | | | | | |
| 151 | Grand Total | | \$3,898,328 | \$3,898,328 | \$3,826,189 | \$(| \$72,139 |

| | | | | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|----|-----------------------------------|---|------------|------------|-------------|----------------|-----------|---------------|--------------------|
| | Site Name | Deficiency Description | Priority 1 | Priority 2 | Priority 3* | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| | Administration Building | Decentralized Cooling | • | \$27,300 | • | \$27,300 | \$27,300 | | • |
| | Administration Building Total | | | \$27,300 | | \$27,300 | | | |
| 3 | | | | | | | | | |
| 4 | Armstrong Elementary | Carpeting | | \$329,537 | | \$329,537 | \$329,537 | | |
| į | i | Exterior Wall Veneer | | \$1,549 | | \$1,549 | | | \$1,549 |
| 6 | j e | Wall Painting and Coating | | \$69,615 | | \$69,615 | \$69,615 | | |
| | Armstrong Elementary Total | | | \$400,701 | | \$400,701 | | | |
| 8 | 3 | | | | | | | | |
| 9 | Athletic Complex | Domestic Water Equipment | | \$675 | | \$675 | | | \$675 |
| 10 |) | Wall Painting and Coating | | \$7,130 | | \$7,130 | \$7,130 | | |
| 13 | Athletic Complex Total | | | \$7,805 | | \$7,805 | | | |
| 12 | | | | | | | | | |
| 13 | Austin High School | Carpeting | | \$3,996 | | \$3,996 | | | \$3,996 |
| 14 | l I | Decentralized Cooling | | \$1,800 | | \$1,800 | | | \$1,800 |
| 15 | <u> </u> | Exterior Entrance Doors | \$25,320 | | | \$25,320 | \$25,320 | | |
| 16 | 5 | Heating System Supplementary Components | | \$4,417 | | \$4,417 | | | \$4,417 |
| 17 | , | Voice Communications | | \$2,098 | | \$2,098 | | | \$2,098 |
| 18 | 3 | Wall Painting and Coating | | \$1,489 | | \$1,489 | | | \$1,489 |
| 19 | Austin High School Total | | \$25,320 | \$13,801 | | \$39,120 | | | |
| 20 | | | | | | | | | |
| 2: | . Austin Parkway Elementary | Steep Slope Roofing | \$51,840 | | | \$51,840 | \$51,840 | | |
| 22 | | Wall Painting and Coating | | \$47,056 | | \$47,056 | \$47,056 | | |
| 23 | Austin Parkway Elementary Total | | \$51,840 | \$47,056 | | \$98,896 | | | |
| 24 | | | | | | | | | |
| 25 | Baines Middle School | Exterior Entrance Doors | \$11,915 | | | \$11,915 | \$11,915 | | |
| 26 | 5 | Stone Facing | | \$698,652 | | \$698,652 | \$698,652 | | |
| 27 | Baines Middle School Total | | \$11,915 | \$698,652 | | \$710,567 | | | |
| 28 | 3 | | | | | | | | |
| 29 | Barrington Place Elementary | Domestic Water Equipment | | \$3,600 | | \$3,600 | | | \$3,600 |
| 30 |) | Exterior Entrance Doors | \$17,873 | | | \$17,873 | \$17,873 | | |
| 33 | | Supply Air | | \$27,540 | | \$27,540 | \$27,540 | | |
| 32 | ! | Wall Painting and Coating | | \$5,346 | | \$5,346 | \$5,346 | | |
| 33 | Barrington Place Elementary Total | | \$17,873 | \$36,486 | | \$54,359 | | | |
| 34 | | | | | | | | | |
| 35 | Blue Ridge Elementary | Exterior Entrance Doors | \$8,936 | | | \$8,936 | \$8,936 | | |
| 36 | 5 | Wall Painting and Coating | | \$38,098 | | \$38,098 | \$38,098 | | |
| 37 | Blue Ridge Elementary Total | | \$8,936 | \$38,098 | | \$47,034 | | | |
| 38 | 3 | | | | | | | | |
| | Brazos Bend Elementary | Wall Painting and Coating | | \$46,208 | | \$46,208 | \$46,208 | | |
| | Brazos Bend Elementary Total | | | \$46,208 | | \$46,208 | | | |
| 43 | | | | | | | | | |
| | Burton Elementary | Exterior Entrance Doors | \$32,767 | | | \$32,767 | \$32,767 | | |
| 43 | | Exterior Wall Veneer | | \$990 | | \$990 | | | \$990 |
| 44 | | Low-Slope Roofing | \$690,750 | | | \$690,750 | \$690,750 | | |
| 45 | | Wall Coverings | \$3,354 | | | \$3,354 | | | \$3,354 |
| | Burton Elementary Total | | \$726,871 | \$990 | | \$727,861 | | | |
| 47 | I. | | | | | | | | |
| 48 | Bush High School | Exterior Entrance Doors | \$14,894 | | | \$14,894 | \$14,894 | | |

| | | | | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|----|---------------------------------|---------------------------|-------------|-------------|-------------|----------------|-------------|---------------|--------------------|
| | Site Name | Deficiency Description | Priority 1 | Priority 2 | Priority 3* | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 49 | | Steep Slope Roofing | \$1,101 | | , | \$1,101 | тторгози. | | \$1,101 |
| 50 | | Tile Flooring | \$20,687 | | | \$20,687 | \$20,687 | | |
| 51 | | Wall Painting and Coating | 1 -7 | \$250,192 | | \$250,192 | \$250,192 | | |
| 52 | Bush High School Total | | \$36,682 | \$250,192 | | \$286,874 | ,, | | |
| 53 | g | | 1 / | , , | | ,,- | | | |
| | Clements High School | Carpeting | | \$49,666 | | \$49,666 | \$49,666 | | |
| 55 | 5 1 5 G | Exterior Entrance Doors | \$23,830 | , -, | | \$23,830 | \$23,830 | | |
| 56 | | Exterior Wall Veneer | · , | \$990 | | \$990 | • | | \$990 |
| 57 | | HVAC Air Distribution | \$1,681,100 | • | | \$1,681,100 | \$1,681,100 | | · |
| 58 | | Wall Painting and Coating | | \$193,342 | | \$193,342 | \$193,342 | | |
| 59 | Clements High School Total | <u> </u> | \$1,704,930 | \$243,998 | | \$1,948,928 | • | | |
| 60 | | | | | | | | | |
| 61 | Colony Bend Elementary | Wall Painting and Coating | | \$25,306 | | \$25,306 | \$25,306 | | |
| | Colony Bend Elementary Total | <u> </u> | | \$25,306 | | \$25,306 | | | |
| 63 | | | | | | | | | |
| 64 | Colony Meadows Elementary | Wall Painting and Coating | | \$37,613 | | \$37,613 | \$37,613 | | |
| | Colony Meadows Elementary Total | | | \$37,613 | | \$37,613 | | | |
| 66 | | | | | | | | | |
| 67 | Commonwealth Elementary | Decentralized Cooling | | \$36,000 | | \$36,000 | \$36,000 | | |
| 68 | • | Exterior Wall Veneer | \$113,472 | | | \$113,472 | \$113,472 | | |
| 69 | Commonwealth Elementary Total | | \$113,472 | \$36,000 | | \$149,472 | | | |
| 70 | - | | | | | | | | |
| 71 | Cornerstone Elementary | Carpeting | | \$387,223 | | \$387,223 | \$387,223 | | |
| 72 | · | Exterior Entrance Doors | \$5,958 | | | \$5,958 | \$5,958 | | |
| 73 | | Wall Painting and Coating | | \$19,975 | | \$19,975 | \$19,975 | | |
| 74 | Cornerstone Elementary Total | | \$5,958 | \$407,198 | | \$413,156 | | | |
| 75 | - | | | | | | | | |
| 76 | Crockett Middle School | Carpeting | | \$1,026,330 | | \$1,026,330 | \$1,026,330 | | |
| 77 | | Wall Painting and Coating | | \$255,549 | | \$255,549 | \$255,549 | | |
| 78 | Crockett Middle School Total | | | \$1,281,879 | | \$1,281,879 | | | |
| 79 | | | | | | | | | |
| 80 | Don Cook Natatorium | Power Distribution | \$19,000 | | | \$19,000 | \$19,000 | | |
| 81 | Don Cook Natatorium Total | | \$19,000 | | | \$19,000 | | | |
| 82 | | | | | | | | | |
| 83 | Drabek Elementary | Decentralized Cooling | | \$36,000 | | \$36,000 | \$36,000 | | |
| 84 | | Wall Painting and Coating | | \$39,459 | | \$39,459 | \$39,459 | | |
| 85 | Drabek Elementary Total | | | \$75,459 | | \$75,459 | | | |
| 86 | | | | | | | | | |
| 87 | Dulles Elementary | Wall Painting and Coating | | \$67,370 | | \$67,370 | \$67,370 | | |
| 88 | Dulles Elementary Total | | | \$67,370 | | \$67,370 | | | |
| 89 | | | | | | | | | |
| | Dulles High School | Carpeting | | \$66,204 | | \$66,204 | \$66,204 | | |
| 91 | | Central Cooling | | \$151,200 | | \$151,200 | \$151,200 | | |
| 92 | | Domestic Water Equipment | | \$5,850 | | \$5,850 | \$5,850 | | |
| 93 | | Wall Coverings | \$26,574 | | | \$26,574 | \$26,574 | | |
| 94 | | Wall Painting and Coating | | \$336,480 | | \$336,480 | \$336,480 | | |
| 95 | Dulles High School Total | <u> </u> | \$26,574 | \$559,734 | | \$586,308 | | | |
| 96 | | | | | | | | | |

| | | | | E | stimated Cost | 2014 Bond | Other Capital | General Fund |
|--------------------------------------|---|------------|-------------|-------------|---------------|-------------|---------------|--------------------|
| Site Name | Deficiency Description | Priority 1 | Priority 2 | Priority 3* | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 97 Dulles Middle School | Decentralized Cooling | • | \$115,280 | • | \$115,280 | \$115,280 | | • |
| 98 | Exterior Entrance Doors | \$5,958 | | | \$5,958 | \$5,958 | | |
| 99 | Facility Hydronic Distribution | | \$2,700 | | \$2,700 | | | \$2,700 |
| 100 | Heat Generation | | \$127,710 | | \$127,710 | \$127,710 | | |
| 101 Dulles Middle School Total | | \$5,958 | \$245,690 | | \$251,648 | | | |
| 102 | | | | | | | | |
| 103 Elkins High School | Casework | \$135,000 | | | \$135,000 | \$135,000 | | |
| 104 | Exterior Entrance Doors | \$40,214 | | | \$40,214 | \$40,214 | | |
| 105 | Exterior Wall Veneer | | \$9,163 | | \$9,163 | \$9,163 | | |
| 106 | HVAC Air Distribution | | \$93,300 | | \$93,300 | \$93,300 | | |
| 107 | Lighting Fixtures | | \$2,160 | | \$2,160 | | | \$2,160 |
| 108 | Stone Facing | | \$200,840 | | \$200,840 | \$200,840 | | |
| 109 Elkins High School Total | | \$175,214 | \$305,463 | | \$480,677 | | | |
| 110 | | | | | | | | |
| 111 First Colony Middle School | Decentralized Cooling | | \$10,920 | | \$10,920 | \$10,920 | | |
| 112 | Wall Painting and Coating | | \$216,879 | | \$216,879 | \$216,879 | | |
| 113 First Colony Middle School Total | | | \$227,799 | | \$227,799 | | | |
| 114 | | | | | | | | |
| 115 Fleming Elementary | Wall Painting and Coating | | \$1,985 | | \$1,985 | | | \$1,985 |
| 116 Fleming Elementary Total | | | \$1,985 | | \$1,985 | | | |
| 117 | | | | | | | | |
| 118 Fort Settlement Middle School | Carpeting | | \$608,486 | | \$608,486 | \$608,486 | | |
| 119 | Central Cooling | | \$214,200 | | \$214,200 | \$214,200 | | |
| 120 | Packaged Generator Assemblies | | \$21,600 | | \$21,600 | \$21,600 | | |
| 121 | Wall Painting and Coating | | \$210,118 | | \$210,118 | \$210,118 | | |
| 122 Fort Settlement Middle School To | otal | | \$1,054,404 | | \$1,054,404 | | | |
| 123 | | | | | | | | |
| 124 Garcia Middle School | Carpeting | | \$541,879 | | \$541,879 | \$541,879 | | |
| 125 | Central Cooling | | \$453,600 | | \$453,600 | \$453,600 | | |
| 126 | Decentralized Cooling | | \$36,000 | | \$36,000 | \$36,000 | | |
| 127 | Facility Hydronic Distribution | \$1,800 | \$2,370,710 | | \$2,372,510 | \$2,372,510 | | |
| 128 | Heating System Supplementary Components | | \$7,868 | | \$7,868 | \$7,868 | | |
| 129 | HVAC Air Distribution | | \$857,100 | | \$857,100 | \$857,100 | | |
| 130 | Resilient Flooring | | \$304,808 | | \$304,808 | \$304,808 | | |
| 131 Garcia Middle School Total | | \$1,800 | \$4,571,965 | | \$4,573,765 | | | |
| 132 | | | | | | | | |
| 133 Glover Elementary | Carpeting | | \$436,694 | | \$436,694 | \$436,694 | | 4 |
| 134 | Exterior Entrance Doors | \$1,489 | | | \$1,489 | | | \$1,489 |
| 135 | Exterior Wall Veneer | | \$1,599 | | \$1,599 | | | \$1,599 |
| 136 | Heating System Supplementary Components | | \$7,852 | | \$7,852 | \$7,852 | | |
| 137 | Wall Painting and Coating | | \$10,026 | | \$10,026 | \$10,026 | | |
| 138 Glover Elementary Total | | \$1,489 | \$456,171 | | \$457,660 | | | |
| 139 | | | 4 | | 4 | 4 | | |
| 140 Goodman Elementary | Decentralized Cooling | | \$5,460 | | \$5,460 | \$5,460 | | |
| 141 | Domestic Water Equipment | | \$5,400 | | \$5,400 | \$5,400 | | |
| 142 | Heat Generation | 4 | \$38,700 | | \$38,700 | \$38,700 | | |
| 143 | Low-Slope Roofing | \$27,630 | 4.4. | | \$27,630 | \$27,630 | | . |
| 144 | Wall Painting and Coating | | \$4,212 | | \$4,212 | | | \$4,212 |

| | | | | | Estimated Cos | t 2014 Bond | Other Capital | General Fund |
|------------|---------------------------------|--|------------|--------------------|---------------------|-------------|---------------|-----------------------|
| | Site Name | Deficiency Description | Priority 1 | Priority 2 | Priority 3* Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 145 | Goodman Elementary Total | | \$27,630 | \$53,772 | \$81,40 | • | | (recine circuit quiry |
| 146 | • | | · , , | | • • | | | |
| 147 | Hall Stadium | Carpeting | | \$1,526 | \$1,52 | 6 | | \$1,526 |
| 148 | Hall Stadium Total | · | | \$1,526 | \$1,52 | 6 | | |
| 149 | | | | | | | | |
| 150 | Highlands Elementary | Carpeting | | \$317,225 | \$317,22 | 5 \$317,225 | | |
| 151 | | Domestic Water Equipment | | \$3,150 | \$3,15 | 0 | | \$3,150 |
| 152 | | Wall Painting and Coating | | \$21,340 | \$21,34 | 0 \$21,340 | | |
| 153 | Highlands Elementary Total | | | \$341,715 | \$341,71 | 5 | | |
| 154 | | | | | | | | |
| 155 | Hightower High School | Exterior Entrance Doors | \$59,576 | | \$59,57 | \$59,576 | | |
| 156 | | Exterior Wall Veneer | | \$4,637 | \$4,63 | 7 | | \$4,637 |
| 157 | | Steep Slope Roofing | \$6,804 | | \$6,80 | 4 \$6,804 | | |
| 158 | | Wall Painting and Coating | | \$381,629 | \$381,62 | 9 \$381,629 | | |
| 159 | | Wall Paneling | | \$5,825 | \$5,82 | | | |
| | Hightower High School Total | | \$66,380 | \$392,090 | \$458,47 | 0 | | |
| 161 | | | | | | | | |
| | Hodges Bend Middle School | Exterior Entrance Doors | \$2,979 | | \$2,97 | | | \$2,979 |
| 163 | | Wall Painting and Coating | | \$1,705 | \$1,70 | 5 | | \$1,705 |
| | Hodges Bend Middle School Total | | \$2,979 | \$1,705 | \$4,68 | 3 | | |
| 165 | | | | | | | | |
| | Holley Elementary | Carpeting | | \$353,023 | \$353,02 | | | |
| 167 | | Exterior Operating Windows | | \$509 | \$50 | _ | | \$509 |
| 168 | | Interior Swinging Doors | | \$1,385 | \$1,38 | | | \$1,385 |
| | Holley Elementary Total | | | \$354,917 | \$354,91 | 7 | | |
| 170 | | | | | | | | |
| | Hopson Field House | Facility Hydronic Distribution | | \$900 | \$90 | | | \$900 |
| 172 | | Wall Painting and Coating | | \$39,655 | \$39,65 | | | |
| | Hopson Field House Total | | | \$40,555 | \$40,55 | 5 | | |
| 174 | | | | | | | | |
| | Hunters Glen Elementary | Exterior Entrance Doors | \$2,979 | | \$2,97 | | | \$2,979 |
| | Hunters Glen Elementary Total | | \$2,979 | | \$2,97 | 9 | | |
| 177 | | | | | 1 | | | |
| | Jones Elementary | Wall Painting and Coating | | \$28,960 | \$28,96 | | | |
| | Jones Elementary Total | | | \$28,960 | \$28,96 | υ <u> </u> | | |
| 180 | Leader et annata | E to do Estado Da | 447.070 | | <i>*</i> | 2 447.055 | | |
| 181 | Jordan Elementary | Exterior Entrance Doors | \$17,873 | 640.00= | \$17,87 | | | |
| 182 | landan Flamantam Tabal | Wall Painting and Coating | A47.070 | \$18,907 | \$18,90 | | | |
| | Jordan Elementary Total | | \$17,873 | \$18,907 | \$36,78 | V | | |
| 184 | V | Wall Deinting and Conting | | ć20.107 | ¢20.46 | , ć20.407 | | |
| | Kempner Ag | Wall Painting and Coating | | \$20,187 | \$20,18 | | | |
| 186 | Kempner Ag Total | | | \$20,187 | \$20,18 | <u>'</u> | | |
| | Kompnor High School | Decentralized Cooling | | ¢10 000 | ¢40.00 | c10.000 | | |
| | Kempner High School | | | \$18,000 | \$18,00 | | | |
| 189 190 | | Heating System Supplementary Components Wall Painting and Coating | | \$7,868 \$7,077 | \$7,86 | | | |
| | Kempner High School Total | wan rainting and Coating | | \$7,077 | \$7,07 \$22.0/ | | | |
| 191 192 | Kempher nigh School Total | | | \$32,945 | \$32,94 | 2 | | |
| 192 | | | | | | | | |

| | | | | | Esti | mated Cost | 2014 Bond | Other Capital | General Fund |
|-----|----------------------------------|-------------------------------|------------|-------------|-------------|-------------|-------------|---------------|--|
| | Site Name | Deficiency Description | Priority 1 | Priority 2 | Priority 3* | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 193 | Lake Olympia Middle School | Carpeting | | \$801,569 | , - | \$801,569 | \$801,569 | | (received a received a |
| 194 | , . | Exterior Entrance Doors | \$19,362 | \$1,489 | | \$20,852 | \$20,852 | | |
| 195 | | Heat Generation | | \$129,645 | | \$129,645 | \$129,645 | | |
| 196 | Lake Olympia Middle School Total | | \$19,362 | \$932,703 | | \$952,066 | | | |
| 197 | | | | | | | | | |
| 198 | Lakeview Elementary | Fire Detection and Alarm | | \$11,075 | | \$11,075 | \$11,075 | | |
| 199 | | HVAC Air Distribution | \$36,800 | | | \$36,800 | \$36,800 | | |
| 200 | | Security System Component | | \$12,038 | | \$12,038 | \$12,038 | | |
| 201 | | Wall Painting and Coating | | \$11,061 | | \$11,061 | \$11,061 | | |
| 202 | Lakeview Elementary Total | | \$36,800 | \$34,173 | | \$70,973 | | | |
| 203 | | | | | | | | | |
| 204 | Lantern Lane Elementary | Exterior Wall Veneer | | \$800 | | \$800 | | | \$800 |
| 205 | | Wall Painting and Coating | | \$14,665 | | \$14,665 | \$14,665 | | |
| 206 | Lantern Lane Elementary Total | | | \$15,464 | | \$15,464 | | | |
| 207 | | | | | | | | | |
| 208 | Lexington Creek Elementary | Exterior Entrance Doors | \$11,915 | | | \$11,915 | \$11,915 | | |
| 209 | | Exterior Wall Veneer | | \$801 | | \$801 | | | \$801 |
| 210 | | Wall Painting and Coating | | \$3,409 | | \$3,409 | | | \$3,409 |
| 211 | Lexington Creek Elementary Total | | \$11,915 | \$4,211 | | \$16,126 | | | |
| 212 | | | | | | | | | |
| 213 | M.R. Wood | Wall Painting and Coating | | \$56,008 | | \$56,008 | \$56,008 | | |
| 214 | M.R. Wood Total | | | \$56,008 | | \$56,008 | | | |
| 215 | | | | | | | | | |
| 216 | Marshall High School | Carpeting | | \$1,013,965 | | \$1,013,965 | \$1,013,965 | | |
| 217 | | Resilient Flooring | | \$378 | | \$378 | | | \$378 |
| 218 | | Wall Painting and Coating | | \$345,698 | | \$345,698 | \$345,698 | | |
| 219 | Marshall High School Total | | | \$1,360,041 | | \$1,360,041 | | | |
| 220 | | | | | | | | | |
| 221 | Meadows Elementary | Wall Painting and Coating | | \$21,492 | | \$21,492 | \$21,492 | | |
| 222 | Meadows Elementary Total | | | \$21,492 | | \$21,492 | | | |
| 223 | | | | | | | | | |
| 224 | Mission Bend Elementary | Decentralized Cooling | | \$36,000 | | \$36,000 | \$36,000 | | |
| 225 | | Electrical Service | | \$144,960 | | \$144,960 | \$144,960 | | |
| 226 | | Exterior Entrance Doors | \$17,873 | | | \$17,873 | \$17,873 | | |
| 227 | | Wall Painting and Coating | | \$37,758 | | \$37,758 | \$37,758 | | |
| 228 | Mission Bend Elementary Total | | \$17,873 | \$218,718 | | \$236,591 | | | |
| 229 | | | | | | | | | |
| 230 | Mission Glen Elementary | Electrical Service | | \$230,400 | | \$230,400 | \$230,400 | | |
| 231 | | Low-Slope Roofing | | \$34,560 | | \$34,560 | \$34,560 | | |
| 232 | Mission Glen Elementary Total | | | \$264,960 | | \$264,960 | | | |
| 233 | | | | | | | | | |
| | Mission West Elementary | Carpeting | | \$213,905 | | \$213,905 | \$213,905 | | |
| 235 | | Wall Painting and Coating | | \$5,114 | | \$5,114 | \$5,114 | | |
| | Mission West Elementary Total | | | \$219,019 | | \$219,019 | | | |
| 237 | | | | | | | | | |
| | Oakland Elementary | Acoustical Suspended Ceilings | | \$44,584 | | \$44,584 | \$44,584 | | |
| 239 | | Decentralized Cooling | | \$47,207 | | \$47,207 | \$47,207 | | |
| 240 | | Exterior Operating Windows | | \$2,544 | | \$2,544 | | | \$2,544 |

| | | | | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|-----|----------------------------------|---|------------|------------|-------------|----------------|-----------|---------------|--------------------|
| | Site Name | Deficiency Description | Priority 1 | Priority 2 | Priority 3* | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 241 | | Exterior Wall Veneer | | \$112,256 | | \$112,256 | \$112,256 | | (come emper year) |
| 242 | | Interior Swinging Doors | | \$4,897 | | \$4,897 | | | \$4,897 |
| 243 | | Resilient Flooring | | \$7,868 | | \$7,868 | \$7,868 | | |
| 244 | | Voice Communications | | \$6,294 | | \$6,294 | \$6,294 | | |
| 245 | | Wall Painting and Coating | | \$26,639 | | \$26,639 | \$26,639 | | |
| 246 | Oakland Elementary Total | 3 5 | | \$252,288 | | \$252,288 | • • | | |
| 247 | , | | | | | | | | |
| 248 | Old Kempner Stadium | Carpeting | | \$929 | | \$929 | | | \$929 |
| 249 | | Low-Slope Roofing | | \$1,738 | | \$1,738 | | | \$1,738 |
| 250 | | Plaster and Gypsum Board Finish | | \$277 | | \$277 | | | \$277 |
| 251 | | Wall Painting and Coating | | \$601 | | \$601 | | | \$601 |
| 252 | Old Kempner Stadium Total | | | \$3,545 | | \$3,545 | | | |
| 253 | | | | | | | | | |
| 254 | Oyster Creek Elementary | Central Cooling | | \$453,600 | | \$453,600 | \$453,600 | | |
| 255 | | Decentralized Cooling | | \$36,000 | | \$36,000 | \$36,000 | | |
| 256 | | Electrical Service | | \$6,840 | | \$6,840 | \$6,840 | | |
| 257 | | Exterior Entrance Doors | \$5,958 | | | \$5,958 | \$5,958 | | |
| 258 | | Heating System Supplementary Components | | \$7,868 | | \$7,868 | \$7,868 | | |
| 259 | | Packaged Generator Assemblies | | \$29,520 | | \$29,520 | \$29,520 | | |
| 260 | | Steep Slope Roofing | | \$64,800 | | \$64,800 | \$64,800 | | |
| 261 | | Wall Painting and Coating | | \$3,409 | | \$3,409 | | | \$3,409 |
| 262 | Oyster Creek Elementary Total | | \$5,958 | \$602,037 | | \$607,995 | | | |
| 263 | | | | | | | | | |
| 264 | Palmer Elementary | Exterior Wall Veneer | | \$800 | | \$800 | | | \$800 |
| 265 | | HVAC Air Distribution | | \$431,200 | | \$431,200 | \$431,200 | | |
| 266 | | Wall Painting and Coating | | \$7,162 | | \$7,162 | \$7,162 | | |
| 267 | Palmer Elementary Total | | | \$439,162 | | \$439,162 | | | |
| 268 | | | | | | | | | |
| 269 | Parks Elementary | Low-Slope Roofing | \$785,383 | | | \$785,383 | \$785,383 | | |
| 270 | Parks Elementary Total | | \$785,383 | | | \$785,383 | | | |
| 271 | | | | | | | | | |
| 272 | Pecan Grove Elementary | Carpeting | | \$220,320 | | \$220,320 | \$220,320 | | |
| 273 | | Wall Painting and Coating | | \$31,824 | | \$31,824 | \$31,824 | | |
| 274 | Pecan Grove Elementary Total | | | \$252,144 | | \$252,144 | | | |
| 275 | | | | | | | | | |
| 276 | PFC Admin Annex | Carpeting | | \$69,566 | | \$69,566 | \$69,566 | | |
| 277 | | Domestic Water Equipment | | \$2,700 | | \$2,700 | | | \$2,700 |
| 278 | | Exterior Wall Veneer | | \$7,085 | | \$7,085 | \$7,085 | | |
| 279 | | Wall Painting and Coating | | \$15,133 | | \$15,133 | \$15,133 | | |
| 280 | PFC Admin Annex Total | | | \$94,484 | | \$94,484 | | | |
| 281 | | | | | | | | | |
| 282 | Quail Valley Middle School | Carpeting | | \$469,994 | | \$469,994 | \$469,994 | | |
| 283 | | Domestic Water Equipment | | \$900 | | \$900 | | | \$900 |
| 284 | | Wall Painting and Coating | | \$200,223 | | \$200,223 | \$200,223 | | |
| 285 | Quail Valley Middle School Total | | | \$671,117 | | \$671,117 | | | |
| 286 | | | | | | | | | |
| 287 | | Carpeting | | \$463,759 | | \$463,759 | \$463,759 | | |
| 288 | | Exterior Entrance Doors | \$5,958 | | | \$5,958 | \$5,958 | | |

| | | | | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|-----|----------------------------------|---|------------|------------|-------------|--------------------|--------------------|---------------|--------------------|
| | Site Name | Deficiency Description | Priority 1 | Priority 2 | Priority 3* | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 289 | | Wall Painting and Coating | • | \$22,057 | • | \$22,057 | \$22,057 | | |
| 290 | Ridgegate Elementary Total | | \$5,958 | \$485,816 | | \$491,773 | | | |
| 291 | | | | | | | | | |
| 292 | Ridgemont Elementary | Central Cooling | \$168,750 | | | \$168,750 | \$168,750 | | |
| 293 | Ridgemont Elementary Total | | \$168,750 | | | \$168,750 | | | |
| 294 | | | | | | | | | |
| 295 | Sartartia Middle School | Carpeting | | \$595,555 | | \$595,555 | \$595,555 | | |
| 296 | | Domestic Water Equipment | | \$3,600 | | \$3,600 | | | \$3,600 |
| 297 | | Wall Painting and Coating | | \$205,653 | | \$205,653 | \$205,653 | | |
| | Sartartia Middle School Total | | | \$804,808 | | \$804,808 | | | |
| 299 | | | | | | | | | |
| | Scanlan Oaks Elementary | Electrical Service | \$6,840 | \$41,040 | | \$47,880 | \$47,880 | | |
| 301 | | Exterior Entrance Doors | \$70,002 | | | \$70,002 | \$70,002 | | |
| | Scanlan Oaks Elementary Total | | \$76,842 | \$41,040 | | \$117,882 | | | |
| 303 | | | | | | | | | |
| | Schiff Elementary | Exterior Entrance Doors | \$11,915 | | | \$11,915 | \$11,915 | | |
| 305 | | Wall Coverings | \$3,302 | | | \$3,302 | | | \$3,302 |
| | Schiff Elementary Total | | \$15,217 | | | \$15,217 | | | |
| 307 | | | | | | | | | |
| | Sienna Crossing Elementary | Exterior Entrance Doors | \$41,703 | | | \$41,703 | \$41,703 | | |
| 309 | | Low-Slope Roofing | \$49,734 | | | \$49,734 | \$49,734 | | |
| | Sienna Crossing Elementary Total | | \$91,437 | | | \$91,437 | | | |
| 311 | | | | | | | | | |
| | Sugar Land Middle School | Decentralized Cooling | | \$72,000 | | \$72,000 | \$72,000 | | |
| 313 | | Electrical Service | | \$13,680 | | \$13,680 | \$13,680 | | |
| 314 | | Facility Hydronic Distribution | \$900 | | | \$900 | | | \$900 |
| 315 | | Heating System Supplementary Components | | \$15,736 | | \$15,736 | \$15,736 | | |
| 316 | | Wall Painting and Coating | | \$85,313 | | \$85,313 | \$85,313 | | |
| | Sugar Land Middle School Total | | \$900 | \$186,728 | | \$187,628 | | | |
| 318 | | | | | | | | | |
| | Sugar Mill Elementary | Decentralized Heating Equipment | | \$18,000 | | \$18,000 | \$18,000 | | 4 |
| 320 | | Domestic Water Equipment | | \$3,600 | | \$3,600 | | | \$3,600 |
| 321 | | Wall Painting and Coating | | \$39,416 | | \$39,416 | \$39,416 | | |
| | Sugar Mill Elementary Total | | | \$61,016 | | \$61,016 | | | |
| 323 | - 1 : 151 .: 0 : | 5 | | 440.070 | | 410.070 | 410.070 | | |
| | | Exterior Wall Veneer | | \$18,070 | | \$18,070 | \$18,070 | | |
| 325 | Technical Education Center Total | | | \$18,070 | | \$18,070 | | | |
| 326 | | | 472.000 | 454.000 | | 4426.000 | 4125.000 | | |
| 327 | Townewest Elementary | Decentralized Cooling | \$72,000 | \$54,000 | | \$126,000 | \$126,000 | | |
| 328 | Tarria arrant Flame antama Tatal | Heating System Supplementary Components | \$16,589 | \$12,442 | | \$29,030 | \$29,030 | | |
| | Townewest Elementary Total | | \$88,589 | \$66,442 | | \$155,030 | | | |
| 330 | Transportation Contar | Carnoting | | ¢0.007 | | ć0 00 7 | ¢0.00 . | | |
| 331 | Transportation Center | Carpeting Description Cooling | | \$9,007 | | \$9,007 | \$9,007 | | |
| 332 | | Decentralized Cooling | | \$9,100 | | \$9,100 | \$9,100 | | 643 |
| 333 | Transportation Courts: Tatal | Wall Painting and Coating | | \$42 | | \$42 | | | \$42 |
| | Transportation Center Total | | | \$18,149 | | \$18,149 | | | |
| 335 | Transportation West | Decentralized Cooling | | ຕ່າດ າາດ | | ຕ່ວດ ວວດ | ຕາດ ກາດ | | |
| 336 | Transportation West | Decembranzed Cooling | | \$38,220 | | \$38,220 | \$38,220 | | |

| | | | | | | Estimated Cost | 2014 Bond | Other Capital | General Fund |
|-----|---------------------------------|---|-------------|--------------|--------------|----------------|--------------|---------------|--------------------|
| | Site Name | Deficiency Description | Priority 1 | Priority 2 | Priority 3* | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 337 | | Exterior Entrance Doors | \$2,979 | | | \$2,979 | | | \$2,979 |
| 338 | | Wall Painting and Coating | | \$25,799 | | \$25,799 | \$25,799 | | |
| 339 | Transportation West Total | | \$2,979 | \$64,019 | | \$66,997 | | | |
| 340 | | | | | | | | | |
| 341 | Walker Station Elementary | Decentralized Cooling | | \$36,000 | | \$36,000 | \$36,000 | | |
| 342 | | Exterior Entrance Doors | \$5,958 | | | \$5,958 | \$5,958 | | |
| 343 | | Heating System Supplementary Components | | \$9,358 | | \$9,358 | \$9,358 | | |
| 344 | | HVAC Air Distribution | | \$886,095 | | \$886,095 | \$886,095 | | |
| 345 | | Wall Painting and Coating | | \$34,320 | | \$34,320 | \$34,320 | | |
| 346 | Walker Station Elementary Total | | \$5,958 | \$965,773 | | \$971,730 | | | |
| 347 | | | | | | | | | |
| 348 | Warehouse Center | Exterior Wall Veneer | | \$37,711 | | \$37,711 | \$37,711 | | |
| 349 | | Wall Painting and Coating | | \$40,111 | | \$40,111 | \$40,111 | | |
| 350 | Warehouse Center Total | | | \$77,822 | | \$77,822 | | | |
| 351 | | | | | | | | | |
| 352 | Willowridge High School | Wall Painting and Coating | | \$365,994 | | \$365,994 | \$365,994 | | |
| 353 | Willowridge High School Total | | • | \$365,994 | • | \$365,994 | | | |
| 354 | | | | | | | | | |
| 355 | Grand Total | | \$4,385,592 | \$21,049,847 | \$16,424,663 | \$41,860,102 | \$25,336,856 | \$0 | \$98,582 |

^{*} Priority 3 allocation between sites is to be determined

7/18/14

Fort Bend ISD Capital Plan Security Cameras Budget Estimate - Phase 1 Only

| | | | | Estimated Cost | Estimated Cost |
|---|---------------------|-----------------------|----------|-----------------------|-----------------------|
| | Campus Type | Current Analog | Proposed | Per Camera | Phase 1 |
| 1 | Elementary Schools | 733 | 1,530 | \$3,000 | \$4,590,000 |
| 2 | Middle Schools | 487 | 924 | \$3,000 | \$2,772,000 |
| 3 | High Schools | 652 | 1,056 | \$3,000 | \$3,168,000 |
| 4 | Specialized Schools | 106 | 130 | \$3,000 | \$390,000 |
| 5 | Support Areas | 104 | 66 | \$3,000 | \$198,000 |
| 6 | Infrastructure | | | | \$3,000,000 |
| 7 | Total | 2,082 | 3,706 | | \$14,118,000 |

Fort Bend ISD Capital Plan Security Vestibules Budget Estimate - Phase 1 Only

| | | Estimated | | | Estimated Cost Per Site - | | | |
|---|---------------------|----------------|----------|-------------|---------------------------|----------|-----------|-----------------------|
| | | Cost Per Site- | Number | Estimated | Teller Window/Door | Number | Estimated | Estimated Cost |
| | Campus Type | Vestibule | Required | Cost | Upgrade | Required | Cost | Phase 1 |
| 1 | Elementary School | \$62,000 | 20 | \$1,240,000 | \$10,000 | 23 | \$230,000 | \$1,470,000 |
| 2 | Middle School | \$85,000 | 10 | \$850,000 | \$10,000 | 4 | \$40,000 | \$890,000 |
| 3 | High School | \$110,000 | 8 | \$880,000 | \$10,000 | 3 | \$30,000 | \$910,000 |
| 4 | Specialized Schools | \$65,000 | 3 | \$195,000 | \$10,000 | 2 | \$20,000 | \$215,000 |
| 5 | Sub-To | otal | 41 | \$3,165,000 | | 32 | \$320,000 | \$3,485,000 |
| 6 | Permitting | \$450 | 41 | 18,450 | | | | \$18,450 |
| 7 | A/E Fees | \$12,500 | 41 | 512,500 | | | • | \$512,500 |
| 8 | Contingency 10% | | | 316,500 | | | • | \$316,500 |
| 9 | | | _ | | | | Total | \$4,332,450 |

Fort Bend ISD Capital Plan Window Film Budget Estimate - Phase 1 Only

| | | | Year | Estimated Cost |
|----|--------|--------------------------|--------|-----------------------|
| | Design | Elementary School | Opened | Phase 1 |
| 1 | ESD0 | Lantern Lane | 1978 | \$24,320 |
| 2 | ESD0 | Townewest | 1978 | \$24,320 |
| 3 | ESD0 | Ridgegate | 1980 | \$24,320 |
| 4 | ESD0 | Colony Bend | 1981 | \$24,320 |
| 5 | ESD0 | Mission Bend | 1981 | \$24,320 |
| 6 | ESD0 | Ridgemont | 1973 | \$24,320 |
| 7 | ESD1 | Settlers Way | 1984 | \$18,420 |
| 8 | ESD1 | Sugar Mill | 1984 | \$18,420 |
| 9 | ESD1 | Hunters Glen | 1985 | \$18,420 |
| 10 | ESD1 | Palmer | 1985 | \$18,420 |
| 11 | ESD1 | Highlands | 1986 | \$18,420 |
| 12 | ESD1 | Mission Glen | 1986 | \$18,420 |
| 13 | ESD1 | Pecan Grove | 1988 | \$18,420 |
| 14 | ESD2 | Austin Parkway | 1989 | \$10,920 |
| 15 | ESD2 | Barrington Place | 1990 | \$10,920 |
| 16 | ESD2 | Colony Meadows | 1991 | \$10,920 |
| 17 | ESD2 | Mission West | 1991 | \$10,920 |
| 18 | ESD2 | Walker Station | 1992 | \$10,920 |
| 19 | ESD2 | Glover, Edgar | 1994 | \$10,920 |
| 20 | ESD2 | Lexington Creek | 1994 | \$10,920 |
| 21 | ESD3 | Fleming, Arizona | 1995 | \$10,780 |
| 22 | ESD3 | Burton, Walter | 1996 | \$10,780 |
| 23 | ESD3 | Brazos Bend | 1997 | \$10,780 |
| 24 | ESD3 | Commonwealth | 1997 | \$10,780 |
| 25 | ESD3 | Sienna Crossing | 1998 | \$10,780 |
| 26 | ESD3 | Oyster Creek | 1999 | \$10,780 |
| 27 | ESD3 | Goodman, Lula Belle | 2001 | \$10,780 |
| 28 | ESD4 | Drabek, Rita | 2001 | \$14,840 |
| 29 | ESD4 | Jordan, Barbara | 2002 | \$14,840 |
| 30 | ESD4 | Scanlan Oaks | 2004 | \$14,840 |
| 31 | ESD4 | Holley, Mary Austin | 2005 | \$14,840 |
| 32 | ESD4 | Seguin, Juan | 2009 | \$14,840 |
| 33 | ESD5 | Oakland | 2006 | \$17,200 |
| 34 | ESD5 | Cornerstone | 2007 | \$17,200 |
| 35 | ESD5 | Schiff, Jan | 2008 | \$17,200 |
| 36 | ESD6 | Parks, Rosa | 2007 | \$8,400 |
| 37 | ESD7 | Armstrong | 2007 | \$27,240 |
| 38 | ESD7 | ES #46 | 2014 | \$27,240 |
| 39 | Unique | Jones, E.A. | 1954 | \$29,280 |
| 40 | Unique | Lakeview** | 1959 | |
| 41 | Unique | Blueridge | 1970 | \$10,320 |
| 42 | Unique | Meadows | 1973 | \$24,320 |
| 43 | Unique | Quail Valley | 1975 | \$13,680 |
| 44 | Unique | Dulles, John Foster | 1976 | \$19,560 |
| 45 | Unique | Briargate | 1977 | \$12,420 |
| 46 | Unique | Heritage Rose | 2010 | \$30,280 |
| 47 | | Elementary subtotal | | \$755,300 |
| 48 | | ** Lakeview not included | | |

7/18/14

Fort Bend ISD Capital Plan Window Film Budget Estimate - Phase 1 Only

| 49 | | | | |
|----------|----------------------|-------------------------------------|-----------------|----------------|
| | | | Year | Estimated Cost |
| 50 | Design | Middle School | Opened | Phase 1 |
| 51 | Unique | Dulles, John Foster | 1965 | \$20,403 |
| 52 | Unique | Sugar Land | 1975 | \$20,340 |
| 53 | Unique | Missouri City | 1976 | \$46,200 |
| 54 | Unique | Quail Valley | 1978 | \$21,840 |
| 55 | MSD00 | First Colony | 1985 | \$17,880 |
| 56 | MSD00 | McAuliffe, Christa | 1986 | \$17,880 |
| 57 | MSD0 | Hodges Bend | 1987 | \$22,800 |
| 58 | MSD0 | Lake Olympia | 1992 | \$22,800 |
| 59 | MSD1 | Garcia, Macario | 1995 | \$50,640 |
| 60 | MSD1 | Sartartia | 2001 | \$50,640 |
| 61 | MSD1 | Fort Settlement | 2001 | \$50,640 |
| 62 | MSD1 | Baines, Billy | 2006 | \$50,640 |
| 63 | MSD2 | Crockett, David | 2007 | \$22,080 |
| 64 | MSD3 | Bowie, James | 2011 | \$46,200 |
| 65 | | Middle School subtotal | | \$460,983 |
| 66 | | | | |
| | | | Year | Estimated Cost |
| 67 | Design | High School | Opened | Phase 1 |
| 68 | Unique | Dulles, John Foster | 1962 | \$27,659 |
| 69 | HSD00 | Willowridge | 1979 | \$30,200 |
| 70 | HSD00 | Clements, William P. | 1983 | \$28,040 |
| 71 | HSD0 | Kempner, I.H. | 1988 | \$27,260 |
| 72 | HSD0 | Elkins, Lawrence E. | 1992 | \$39,260 |
| 73 | HSD1 | Austin, Stephen F. | 1995 | \$64,580 |
| 74 | HSD1 | Hightower, L.V. | 1998 | \$64,580 |
| 75 76 | HSD1 | Marshall, Thurgood | 2002 | \$64,580 |
| 76 | HSD2 | Bush, George | 2001 | \$39,660 |
| 77 | HSD2 | Travis, William B. | 2006 | \$39,660 |
| 78 | HSD3 | Ridge Point | 2010 | \$94,873 |
| 79 | | High School subtotal | | \$520,352 |
| 80 | | | Year | Estimated Cost |
| 81 | Dosian | Specialized | Opened | Phase 1 |
| 82 | Design Unique | Specialized MR. Wood | 2006 | \$9,000 |
| 83 | Unique | Ferndell Henry | 2010 | \$19,900 |
| 84 | Unique | Tech Ed Center | 1973 | \$19,900 |
| 85 | Unique | Ridgemont ECC | 2010 | \$31,540 |
| 86 | Unique | Progressive HS | 1986 | \$9,240 |
| 87 | - Jinque | Specialized subtotal | 1300 | \$88,280 |
| 88 | | openianzea autotai | | 700,200 |
| 89 | | Total | | \$1,824,915 |
| 90 | | ** Lakeview not included | | Ÿ±,0±¬,010 |
| 91 | | Edicate various included | | |
| | Note: The cos | st of 8 mm film is approximately \$ | 20/sf installed | d |
| | | | , -, | |

Fort Bend ISD Capital Plan Security Fencing Budget Estimate - Phase 1 Only

| | | | | | | Estimated | | | |
|---|-------------------|-----------|------------|----------------|---------------|------------|----------------|------------|-----------------------|
| | | Total | | | | Vinyl Clad | | | |
| | | Estimated | Estimated | Iron Cost | | Chain Link | Vinyl Cost | Estimated | |
| | | Linear | Iron Fence | (1/3 of total) | Estimated | Fence | (2/3 of total) | Cost for | Estimated Cost |
| | Campus Type | Footage | Footage | per foot | Cost for Iron | Footage | per foot | Chain Link | Phase 1 |
| 1 | Elementary School | 36,000 | 12,000 | 49 | \$588,000 | 24,000 | 29 | \$695,993 | \$1,283,993 |
| 2 | Total | 36,000 | 12,000 | | \$588,000 | 24,000 | | \$695,993 | \$1,283,993 |

Fort Bend ISD Capital Plan Access Control Including Video Intercom Budget Estimate - Phase 1 Only

| | | | Estimated | Estimated | | | Estimated | |
|---|---------------------|----------|-----------|-------------|-----------------------|-----------------|-----------|-----------------------|
| | | Proposed | Cost Per | Cost for | | Estimated | Cost for | |
| | | Access | Access | Access | Proposed Video | Cost Per | Video | Estimated Cost |
| | Campus Type | Control | Control | Control | Intercom | Camera | Intercom | Phase 1 |
| 1 | Elementary School | 714 | \$2,000 | \$1,428,000 | 45 (2 dr system) | \$3,000 | \$135,000 | \$1,563,000 |
| 2 | Middle School | 314 | \$2,000 | \$628,000 | 14 (8 dr system) | \$13,000 | \$182,000 | \$810,000 |
| 3 | High School | 291 | \$2,000 | \$582,000 | 11 (8 dr system) | \$13,000 | \$143,000 | \$725,000 |
| 4 | Specialized Schools | 51 | \$2,000 | \$102,000 | 5 (8 dr system) | \$13,000 | \$65,000 | \$167,000 |
| 5 | Support Areas | 75 | \$2,000 | \$150,000 | | | | \$150,000 |
| 6 | Total | 1,445 | | \$2,890,000 | | • | \$525,000 | \$3,415,000 |

Fort Bend ISD Capital Plan Emergency Generators Budget Estimate - Phase 1 Only

| | | | Estimated Cost | Estimated Cost |
|----|--------------------|----------|----------------|----------------|
| | Campus | Proposed | Per Generator | Phase 1 |
| 1 | Admin Annex | 1 | \$80,000 | \$80,000 |
| 2 | Aquatic Practice | 1 | \$80,000 | \$80,000 |
| | Athletic Complex | 1 | \$80,000 | \$80,000 |
| | Austin Parkway ES | 1 | \$80,000 | \$80,000 |
| | Blueridge ES | 1 | \$80,000 | \$80,000 |
| | Brazos Bend ES | 1 | \$80,000 | \$80,000 |
| 7 | Briargate ES | 1 | \$80,000 | \$80,000 |
| | Burton ES | 1 | \$80,000 | \$80,000 |
| 9 | Clements HS | 1 | \$80,000 | \$80,000 |
| 10 | Colony Bend ES | 1 | \$80,000 | \$80,000 |
| | Commonwealth ES | 1 | \$80,000 | \$80,000 |
| _ | Dulles ES | 1 | \$80,000 | \$80,000 |
| | Dulles MS | 1 | \$80,000 | \$80,000 |
| | First Colony MS | 1 | \$80,000 | \$80,000 |
| | Highlands ES | 1 | \$80,000 | \$80,000 |
| | Hunters Glen ES | 1 | \$80,000 | \$80,000 |
| _ | Kempner Ag | 1 | \$80,000 | \$80,000 |
| | Kempner HS | 1 | \$80,000 | \$80,000 |
| | Lakeview ES | 1 | \$80,000 | \$80,000 |
| | Lantern Lane ES | 1 | \$80,000 | \$80,000 |
| _ | McAuliffe MS | 1 | \$80,000 | \$80,000 |
| | Meadows ES | 1 | \$80,000 | \$80,000 |
| | Mission Bend ES | 1 | \$80,000 | \$80,000 |
| | Mission Glen ES | 1 | \$80,000 | \$80,000 |
| 25 | Old Kempner | 1 | \$80,000 | \$80,000 |
| | Palmer ES | 1 | \$80,000 | \$80,000 |
| 27 | Pecan Grove ES | 1 | \$80,000 | \$80,000 |
| 28 | Progressive HS | 1 | \$80,000 | \$80,000 |
| | Quail Valley MS | 1 | \$80,000 | \$80,000 |
| 30 | Ridgegate ES | 1 | \$80,000 | \$80,000 |
| 31 | Ridgemont ES | 1 | \$80,000 | \$80,000 |
| 32 | Settlers Way ES | 1 | \$80,000 | \$80,000 |
| _ | Sienna Crossing ES | 1 | \$80,000 | \$80,000 |
| _ | SL Warehouse | 1 | \$80,000 | \$80,000 |
| 35 | Sugar Land MS | 1 | \$80,000 | \$80,000 |
| | Sugar Mill ES | 1 | \$80,000 | \$80,000 |
| | Tech Center | 1 | \$80,000 | \$80,000 |
| 38 | Townewest ES | 1 | \$80,000 | \$80,000 |
| - | Trammel Ag | 1 | \$80,000 | \$80,000 |
| | Willowridge HS | 1 | \$80,000 | \$80,000 |
| | Total | 40 | • | \$3,200,000 |

Fort Bend ISD Capital Plan Emergency Notification System Budget Estimate - Phase 1 Only

| | | | Estimated Cost Per | Estimated Cost |
|---|---------------------|----------|---------------------------|-----------------------|
| | Campus Type | Proposed | Camera | Phase 1 |
| 1 | Elementary Schools | 45 | \$6,100 | \$274,500 |
| 2 | Middle Schools | 14 | \$6,100 | \$85,400 |
| 3 | High Schools | 11 | \$6,100 | \$67,100 |
| 4 | Specialized Schools | 5 | \$6,100 | \$30,500 |
| 5 | Support Areas | 11 | \$6,100 | \$67,100 |
| 6 | Total | 86 | _ | \$524,600 |

Fort Bend ISD Capital Plan Two Way Radio Budget Estimate - Phase 1 Only

| | | Devices Per | Cost Per | Estimated Cost |
|---|-------------------------|-------------|----------|----------------|
| | Devices Type | Campus | unit | Phase 1 |
| 1 | Hand Held Radios | 695 | \$245 | \$170,275 |
| 2 | Building Repeaters | 113 | \$3,500 | \$395,500 |
| 3 | Bus Radios | 467 | \$400 | \$186,800 |
| 4 | Bus Dispatcher | 2 | \$12,000 | \$24,000 |
| 5 | Radio Tower Repeaters | 8 | \$6,500 | \$52,000 |
| 6 | Police Portable Radio | 65 | \$4,258 | \$276,743 |
| 7 | Police Dash mount Radio | 45 | \$3,943 | \$177,450 |
| 8 | Dispatch Consoles | 2 | \$75,000 | \$150,000 |
| 9 | Total | | | \$1,432,768 |

Fort Bend ISD Capital Plan Bus Cameras and GPS Budget Estimate - Phase 1 Only

| | | | Material | | Total | Estimated | | | | |
|-----|---|-----------|-----------------|-------------------|-----------------|-----------------|-----------|------------------|-------------------|-----------------------|
| | | Proposed | Cost Per | | Camera | Cost Per | | Estimated | | |
| | | Number of | Bus | Labor Cost | Cost Per | Bus | Number of | Cost Per | Total Cost | Estimated Cost |
| | Campus Type | Buses* | Camera | Per Bus | Bus | Camera | Buses | GPS | Bus GPS** | Phase 1 |
| 1 | District-Wide | 327 | \$2,160 | \$225 | \$2,385 | \$779,944 | 467 | \$275 | \$128,425 | 908,369 |
| 2 | Total | 327 | | | | \$779,944 | 467 | | \$128,425 | 908,369 |
| Not | Note: *Some of our fleet is already equipped with a bus camera system | | | | | | | | | |
| Not | Note: **There is a \$17 per month, per unit charge for service. | | | | | | | | | |

Fort Bend ISD Capital Plan Bus Replacement Budget Estimate - Phase 1 Only

| | | | Estimated Cost | Estimated Cost |
|---|------------------------------------|----------|-----------------------|-----------------------|
| | Bus Type | Proposed | Per Bus | Phase 1 |
| 1 | Regular Ed | 142 | \$100,000 | \$14,200,000 |
| 2 | Special Ed | 29 | \$100,000 | \$2,900,000 |
| 3 | Out of Service | 9 | \$100,000 | \$900,000 |
| 4 | Total | 180 | | \$18,000,000 |
| 5 | | | | |
| 6 | Other Capital Funds | | | \$3,000,000 |
| 7 | Total Phase 1 amount for new buses | | | \$15,000,000 |

Note: \$3.0M of funding is from 2007 bond funds

Fort Bend ISD Capital Plan Technology Budget Estimate - Phase 1 Only

| | Fatimatad | | | | |
|--|-----------------------|----------------|--|---------------|--------------------|
| | Estimated Duration | Estimated Cost | 2014 Band | Other Canital | Conoral Fund |
| Initiativa | Duration | Estimated Cost | 2014 Bond | Other Capital | General Fund |
| Initiatives 1 Internet Infrastructure Upgrade | | Phase 1 | Proposal | Funds | (Items Under \$5K) |
| 2 Fiber for Mission Critical Internet, Cloud, DC | | \$1,800,000 | | \$1,800,000 | |
| 3 POP on Internet Backbone-DC, Power, Services | | \$1,800,000 | | \$1,800,000 | |
| 4 Internet Infrastructure Systems | | \$2,145,822 | | \$2,145,822 | |
| 5 WAN Design Contingency | | \$324,146 | | \$324,146 | |
| 6 Internet Infrastructure Upgrade | 6 months | \$4,375,968 | | \$4,375,968 | |
| 7 | o months | 34,373,308 | | 34,373,308 | |
| 8 Wide Area Network/Backbone Refresh | | | | | |
| 9 WAN Electronics - Campuses and Existing Core | | \$11,259,593 | \$11,259,593 | | |
| 10 WAN Electronics (Secondary Core at Internet POP) | | \$1,213,976 | \$1,213,976 | | |
| 11 WAN Fiber Infrastructure | | \$3,528,000 | \$3,528,000 | | |
| 12 WAN Design Contingency | | \$1,280,125 | \$1,280,125 | | |
| 13 Wide Area Network/Backbone Refresh | 12-14 months | \$17,281,694 | \$17,281,694 | \$0 | |
| 14 | | + | 7 7 | 7.2 | |
| 15 Data Center SAN and Virtualization | | | | | |
| 16 Virtualization/Cloud Server Infrastructure | | \$1,007,975 | | \$1,007,975 | |
| 17 5 Yr Virtualization/Cloud Software, Licsg & Main. | | \$1,091,606 | | \$1,091,606 | |
| 18 Data Center Network, SAN Infrastructure | | \$1,129,112 | | \$1,129,112 | |
| 19 Install a Storage Area Network (SAN) | | \$2,155,798 | | \$2,155,798 | |
| 20 Expand POP to Active DC Facility, Power, Service 5 Yr | | \$840,000 | | \$840,000 | |
| 21 Build Backup, Recovery, and Business Continuity | | \$960,000 | | \$960,000 | |
| 22 WAN Design Contingency | | \$574,759 | | \$574,759 | |
| 23 Data Center SAN and Virtualization | 12-14 months | \$7,759,250 | \$0 | \$7,759,250 | |
| 24 | | | | | |
| 25 Data Center Facilities Modifications | | | | | |
| 26 Priority Action - Existing Data Center Repairs | | \$574,992 | | \$574,992 | |
| 27 WAN Design Contingency | | \$45,999 | | \$45,999 | |
| 28 Data Center Facilities Modifications | 18-20 months | \$620,991 | \$0 | \$620,991 | |
| 29 | | | | | |
| 30 Wireless Network Deployment | | | | | |
| 31 Wireless Access Points and Associated Systems | | \$11,721,975 | \$11,721,975 | | |
| 32 Cabling | | \$3,955,799 | \$3,955,799 | | |
| 33 Switches (POE+) | | \$4,833,477 | \$4,833,477 | | |
| 34 Wireless Design Contingency | | \$1,640,901 | \$1,640,901 | | |
| 35 Wireless Network Deployment | 36 months | \$22,152,153 | \$22,152,153 | \$0 | |
| 36 | | | | | |
| 37 Local Area Network Refresh | | | | 1 | |
| 38 Refresh Existing Wired Switching | | \$8,914,937 | | \$8,914,937 | |
| 39 UPS Refresh | | \$1,093,961 | | \$1,093,961 | |
| 40 Cabling – Closet Backbone Fiber Upgrades | | \$1,250,362 | | \$1,250,362 | |
| 41 LAN Design Contingency | | \$900,740 | 4- | \$900,740 | |
| 42 Local Area Network Refresh | 60 months | \$12,160,000 | \$0 | \$12,160,000 | |
| 43 | | | | | |
| 44 VoIP Collaborative System Upgrade | | 64.000.000 | | 64.600.075 | |
| 45 VoIP Collaborative System Upgrade | | \$4,698,976 | | \$4,698,976 | |
| 46 VOIP Design Contingency | 42 | \$375,918 | 4- | \$375,918 | |
| 47 VoIP Collaborative System Upgrade | 12 months | \$5,074,894 | \$0 | \$5,074,894 | |
| 48 | | | | | |
| 49 Adding Communications Closets on Campus | | ¢1 140 200 | | ¢1 140 300 | |
| 50 Add Communications Closets on Campus Generators | | \$1,140,300 | | \$1,140,300 | |
| 51 Facilities Power Design Contingency | 20+1: | \$126,700 | 40 | \$126,700 | |
| 52 Adding Communications Closets on Campus 53 | 30 months | \$1,267,000 | \$0 | \$1,267,000 | |
| | | 670 604 050 | ¢20,422,047 | 624 250 402 | |
| 54 Total | | \$70,691,950 | \$39,433,847 | \$31,258,103 | |

 ${\bf Note: The\ Technology\ Master\ Plan\ was\ presented\ to\ the\ Board\ of\ Trustees\ June\ {\bf 23,2014.}}$

Fort Bend ISD Capital Plan Athletic Facility Cycle Replacement Budget Estimate - Phase 1 Only

| | | | Tennis Court | |
|----|---------------------|-------------------------|-----------------------|-----------------------|
| | | Required Capital | Resurface | Estimated Cost |
| | Campus | Track Resurface | Estimated Cost | Phase 1 |
| 1 | Dulles HS | \$150,000 | \$37,500 | \$187,500 |
| 2 | Willowridge HS | \$150,000 | \$37,500 | \$187,500 |
| 3 | Clements HS | \$150,000 | \$37,500 | \$187,500 |
| 4 | Kempner HS | \$150,000 | \$37,500 | \$187,500 |
| 5 | Elkins HS | \$150,000 | \$37,500 | \$187,500 |
| 6 | Austin HS | \$150,000 | \$37,500 | \$187,500 |
| 7 | Hightower HS | \$150,000 | \$37,500 | \$187,500 |
| 8 | Bush HS | \$150,000 | \$37,500 | \$187,500 |
| 5 | Dulles MS | | \$25,000 | \$25,000 |
| 6 | Missouri City MS | | \$25,000 | \$25,000 |
| 7 | Sugar Land MS | | \$25,000 | \$25,000 |
| 8 | Quail Valley MS | | \$25,000 | \$25,000 |
| 9 | First Colony MS | | \$25,000 | \$25,000 |
| 10 | McAuliffe MS | | \$25,000 | \$25,000 |
| 11 | Hodges Bend MS | | \$25,000 | \$25,000 |
| 12 | Lake Olympia MS | | \$25,000 | \$25,000 |
| 13 | Garcia MS | | \$25,000 | \$25,000 |
| 14 | Sartartia MS | | \$25,000 | \$25,000 |
| 10 | Contingency | | | \$41,216 |
| 11 | Total | | | \$1,791,216 |
| 12 | Note: Other seconda | ry campuses will be add | ressed in Phase 2 | |

Fort Bend ISD Capital Plan White Fleet Vehicle Replacement Budget Estimate - Phase 1 Only

| | Vehicles - Long Term Replacement Schedule | Proposed | Estimated Replacement Cost | Fleet Replacement Value | Annual Replacement Rate | Estimated Cost Phase 1 |
|----------|--|------------------|-------------------------------|----------------------------|---|------------------------------|
| 1 | <u>Vans</u> | • | • | | | |
| | 1/2 ton | 24 | \$25,000 | \$600,000 | 10.0% | \$60,000 |
| | 3/4 ton | 39 | \$26,000 | \$1,014,000 | | \$101,400 |
| | 1 ton 1 ton step | 28 6 | \$28,000 \$32,000 | \$784,000 \$192,000 | 10.0% 8.3% | \$78,400 \$15,936 |
| | 1 ton box | 3 | \$32,000 | \$96,000 | 8.3% | \$7,968 |
| | CND Transit | 7 | \$25,000 | \$175,000 | 8.3% | \$14,525 |
| 8 | | | | | | |
| | Ranger* | 12 | \$16,500 | \$198,000 | 8.3% | \$16,434 |
| | 1/2 ton 3/4 ton | 13 17 | \$16,500 \$19,000 | \$214,500 \$323,000 | 8.3% 10.0% | \$17,804 \$32,300 |
| | 1 ton | 2 | \$22,000 | \$44,000 | | \$4,400 |
| | 1 ton crew | 16 | \$26,000 | \$416,000 | 10.0% | \$41,600 |
| | 2 ton flat* | 1 | \$30,000 | \$30,000 | 8.3% | \$2,490 |
| 15 | | | \$25.000 | 4245.000 | 5.00/ | 442.250 |
| | Delivery 450 Delivery 650 | 7 3 | \$35,000 \$45,000 | \$245,000 \$135,000 | 5.0% | \$12,250 \$6,750 |
| | Dump 650 | 1 | \$45,000 | \$45,000 | 5.0% | \$2,250 |
| 19 | · | | + 10,000 | + 10,000 | | 7-/ |
| | Crown Vic* | 23 | \$30,000 | \$690,000 | 12.5% | \$86,250 |
| | Impala* | 2 | \$30,000 | \$60,000 | | \$7,500 |
| | Malibu* | 1 | \$30,000 | \$30,000 | 12.5% | \$3,750 |
| | Taurus* Charger | <u>3</u> | \$30,000 \$30,000 | \$90,000 \$210,000 | 12.5% 12.5% | \$11,250 \$26,250 |
| | Tahoe | 7 | \$37,000 | \$259,000 | | \$32,375 |
| | Fusion | 2 | \$28,000 | \$56,000 | 10.0% | \$5,600 |
| 27 | Non Police Cars | | | | | |
| | Explorer* | 1 | \$16,000 | \$16,500 | | \$1,650 |
| | Escort/Focus Wagon Fusion | 32 1 | \$16,000 \$22,000 | \$512,000 \$22,000 | | \$51,200 \$2,200 |
| | Impala* | 1 | \$22,000 | \$22,000 | 10.0% | \$2,200 |
| 32 | Vehicles | 259 | | | ual Replacement Plan: | \$644,732 |
| 33 | | | | | | |
| | Vehicles For Immediate Replacement | | Mechanical | | | |
| 34 | and Purchase 1996 2-TON VAN VEH# 771 | Year 1996 | Condition Poor | Mileage 249,926 | Replacement Step Van | Cost \$32,000 |
| | 1999 1-TON VAN VEH# 831 | 1999 | Poor | 205,040 | E350 | \$28,000 |
| | 1999 1-TON VAN VEH# 831 | 1999 | Poor | 205,040 | E350 | \$28,000 |
| 38 | 2000 1-TON VAN VEH# 855 | 2000 | Poor | 197,143 | E350 | \$28,000 |
| | EXPRESS C1500 | 2002 | Poor | 176,013 | F550 | \$42,000 |
| | EXPRESS C1500 EXPRESS C1500 | 2002 | Poor | 175,419 | F550 E250 | \$42,000 \$26,000 |
| | 1998 3/4-TON VAN VEH# 805 | 1998 | Poor Poor | 174,858 172,722 | E250 | \$26,000 |
| | EXPRESS C1500 | 2002 | Poor | 172,132 | E150 | \$25,000 |
| 44 | 1997 VAN VEH# 791 | 1997 | Poor | 167,589 | E250 | \$26,000 |
| | EXPRESS C1500 | 2002 | Poor | 167,444 | E150 | \$25,000 |
| | EXPRESS C1500 | 2002 | Poor | 166,040 | E150 | \$25,000 |
| | 2000 4-DOOR S.U.V. VEH# 846 1999 3/4-TON PICK-UP VEH# 821 | 2000 1999 | Poor Poor | 163,468 163,031 | E250 E350 | \$26,000 \$28,000 |
| | 1997 VAN VEH# 792 | 1997 | Poor | 160,822 | E250 | \$26,000 |
| 50 | EXPRESS C1500 | 2002 | Poor | 158,320 | E150 | \$25,000 |
| | 1998 3/4-TON VAN VEH# 800 | 1998 | Poor | 157,384 | E250 | \$26,000 |
| | 2005 FORD ECONOLINE VAN VEH# 941 | 2005 | Poor | 156,674 | E250 | \$26,000 |
| | 2001 3/4-TON VAN VEH# 878 1998 3/4-TON VAN VEH# 810 | 2001 1998 | Poor Undrivable | 156,316 156,257 | E250 E250 | \$26,000 \$26,000 |
| | 2000 3/4-TON VAN VEH# 848 | 2000 | Poor | 154,172 | E250 | \$26,000 |
| | 1997 3/4-TON PICK-UP VEH# 782 | 1997 | Poor | 153,627 | E250 | \$26,000 |
| | 2001 3/4-TON PICK-UP VEH# 871 | 2001 | Poor | 152,615 | E350 | \$28,000 |
| | 1999 1-TON VAN VEH# 818 | 1999 | Poor | 150,400 | E350 | \$28,000 |
| | 1998 3/4-TON VAN VEH# 808 New HVAC Position | 1998 | Undrivable | 114,987 | E350 E350 | \$28,000 \$28,000 |
| | New HVAC Position | | | | E350 | \$28,000 |
| _ | New HVAC Position | | | | E350 | \$28,000 |
| | New HVAC Position | - | | | E350 | \$28,000 |
| | New HVAC Position | | | | F150 | \$16,500 |
| 65 66 | New Supervisor Vehicle Vehicles | 21 | T-1-10 T 0 : : | thouston for the Prince | F250 | \$27,000 \$853,500 |
| 67 | venicies | 31 | | | eplacement of Poor and e Vehicles for New Staff: | 202 2,200 |
| | Total One-Time Contribution to Vehicle | e Replaceme | | | | \$1,498,232 |
| 69 | | • | | | | |
| 70 | Note: * Vehicles will be replaced with | a same or lik | e kind vehicle | | | |